



# Borneo Motors



# TOYOTA

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no. : 6631 1188

## ESTIMATE

| Account Details                                                                | Account No.                 | Customer Details                                                         |
|--------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------|
| HL Assurance Pte Ltd<br>11 Keppel Road<br>#11-01 Abi Plaza<br>Singapore 089057 | S1000028 / ICHLA            | Mr Yong Chor Chim<br>238 Bishan Street 22<br>#12-220<br>Singapore 570238 |
|                                                                                | Document No.<br>0           | Mobile: 98340572                                                         |
|                                                                                | Document Date<br>04/01/2022 |                                                                          |

| Year | Model   | Variant   | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|-----------|------------|----------|------------|---------|---------------------|
| 2018 | NSP151R | AEXRKT E1 | 24/04/2018 | SLZ1418T | 0          | 12455   | 72/OD/SLZ1418T      |

| Chassis No.       | Engine No. | Terms | SA / Counter    | Vehicle In | Collected On         |
|-------------------|------------|-------|-----------------|------------|----------------------|
| MR2B23F3901109906 | 2NRX258512 | 60    | Thomas Pang W T | --/--/---- | 0.00 --/--/---- 0.00 |

| L  | Cd | Job/Parts Description                                                                                                                                             | Qty | Unit Price | Disc % | Amount                  |
|----|----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|-------------------------|
| 1  | Z  | BP-SUNDRY SUNDRIES<br>POLICY NO.:MP316928 ACC DATE:02.01.2022<br>DRIVE IN:03.01.2022 EXCESS:<br>DATE-IN: DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORISED ON: |     |            |        | <del>50</del> 100.00    |
| 2  | Z  | BP-SLANT SUPPLY SEALANT (NETT)                                                                                                                                    |     |            |        | <del>100</del> 200.00   |
| 3  | B  | BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR                                                                                                                     |     |            |        | <del>180.00</del>       |
| 4  | B  | BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST                                                                                                                       |     |            |        | <del>122.40</del>       |
| 5  | B  | BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS<br>ONTO NEW BOOTLID.<br>R/I REAR REVERSE CAMERA TO FAC REPAIR.                                                     |     |            |        | <del>540.00</del>       |
| 6  | B  | BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR                                                                                                                  |     |            |        | <del>360</del> 720.00   |
| 7  | B  | BP-LAB2 R/I REAR WINDSCREEN GLASS TO FAC REPAIR.                                                                                                                  |     |            |        | <del>462.00</del>       |
| 8  | S  | BP-SUBLET TO RESET ECU AND REPROGRAMME                                                                                                                            |     |            |        | <del>180.00</del>       |
| 9  | L  | BP-LPO SUPPLY REGN PLATE (PO# )                                                                                                                                   |     |            |        | <del>80.00</del>        |
| 10 | B  | BP-LAB2 REPLACE ACC DAMAGED PARTS<br>AND STRAIGHTEN/REALIGN<br>ACC AFFECTED AREAS                                                                                 |     |            |        | <del>2880</del> 5040.00 |

| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total      |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less       |
|                                   |                                       |                                                          | Amount Due |



# Borneo Motors



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                | Account No.                 | Customer Details                                                         |
|--------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------|
| HL Assurance Pte Ltd<br>11 Keppel Road<br>#11-01 Abi Plaza<br>Singapore 089057 | S1000028 / ICHLA            | Mr Yong Chor Chim<br>238 Bishan Street 22<br>#12-220<br>Singapore 570238 |
|                                                                                | Document No.<br>0           | Mobile: 98340572                                                         |
|                                                                                | Document Date<br>04/01/2022 |                                                                          |

| Year              | Model      | Variant   | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|-----------|-----------------|------------|--------------|------------|---------------------|
| 2018              | NSP151R    | AEXRKT E1 | 24/04/2018      | SLZ1418T   | 0            | 12455      | 72/OD/SLZ1418T      |
| Chassis No.       | Engine No. | Terms     | SA / Counter    | Vehicle In | Collected On |            |                     |
| MR2B23F3901109906 | 2NRX258512 | 60        | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L  | Cd | Job/Parts Description                         | Qty   | Unit Price | Disc % | Amount |
|----|----|-----------------------------------------------|-------|------------|--------|--------|
| 11 | B  | BP-RES2 RESPRAY ACC AFFECTED AREAS @590 X 5   |       |            |        | 2950   |
| 12 | 1  | SPC507-0D015 11 BACK SENSOR 040 SUPER WHITE ? | 1.00  | 197.80     |        | 197.80 |
| 13 | 2  | S52159-0U963 COVER, RR BUMPER L/C             | 1.00  | 557.70     |        | 557.70 |
| 14 | 3  | S52161-0K040 PIECE, RR BUMPER                 | 10.00 | 4.30       |        | 43.00  |
| 15 | 4  | S52462-0D020 PAD, RR BUMPER, RH               | 2.00  | 11.70      |        | 23.40  |
| 16 | 5  | S75895-0D270 TAPE, MOULDING, NO.1             | 2.00  | 53.50      |        | 107.00 |
| 17 | 6  | S52575-0D340 RETAINER, RR BUMPER              | 1.00  | 164.30     |        | 164.30 |
| 18 | 7  | S52576-0D330 RETAINER, RR BUMPER              | 1.00  | 164.30     |        | 164.30 |
| 19 | 8  | S52023-0D090 REINFORCEMENT SUB-AS             | 1.00  | 353.10     |        | 353.10 |
| 20 | 9  | S81910-0D050 REFLECTOR ASSY, REFL             | 1.00  | 99.80      |        | 99.80  |
| 21 | 0  | S81920-0D050 REFLECTOR ASSY, REFL             | 1.00  | 99.80      |        | 99.80  |
| 22 | 1  | S58307-0D480 PANEL SUB-ASSY, BODY             | 1.00  | 786.30     |        | 786.30 |
| 23 | 2  | S61601-0D260 PANEL SUB-ASSY, QUAR             | 1.00  | 963.70     |        | 963.70 |
| 24 | 3  | S61063-0D090 TROUGH SUB-ASSY, LUG             | 1.00  | 128.20     |        | 128.20 |
| 25 | 4  | T08826-08115 PANEL BONDING ADX                | 1.00  | 267.20     |        | 267.20 |
| 26 | 5  | S64401-0D360 PANEL SUB-ASSY, LUGG             | 1.00  | 838.90     |        | 838.90 |
| 27 | 6  | S64461-0D180 WEATHERSTRIP, LUGG               | 1.00  | 186.50     |        | 186.50 |
| 28 | 7  | S64503-0D090 ARM SUB-ASSY, LUG CO             | 2.00  | 69.70      |        | 139.40 |
| 29 | 8  | S64600-0D040 LOCK ASSY, LUGGAGE C             | 1.00  | 423.90     |        | 423.90 |
| 30 | 9  | S58387-0D200 PLATE, RR FLOOR FINI             | 1.00  | 295.40     |        | 295.40 |

| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total              |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|--------------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less<br>Amount Due |

Company Copy



inciscope

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                | Account No.                 | Customer Details                                                         |
|--------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------|
| HL Assurance Pte Ltd<br>11 Keppel Road<br>#11-01 Abi Plaza<br>Singapore 089057 | S1000028 / ICHLA            | Mr Yong Chor Chim<br>238 Bishan Street 22<br>#12-220<br>Singapore 570238 |
|                                                                                | Document No.<br>0           | Mobile: 98340572                                                         |
|                                                                                | Document Date<br>04/01/2022 |                                                                          |

| Year | Model   | Variant   | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|-----------|------------|----------|------------|---------|---------------------|
| 2018 | NSP151R | AEXRKT E1 | 24/04/2018 | SLZ1418T | 0          | 12455   | 72/OD/SLZ1418T      |

| Chassis No.       | Engine No. | Terms | SA / Counter    | Vehicle In | Collected On         |
|-------------------|------------|-------|-----------------|------------|----------------------|
| MR2B23F3901109906 | 2NRX258512 | 60    | Thomas Pang W T | --/--/---- | 0.00 --/--/---- 0.00 |

| L  | Cd | Job/Parts Description                               | Qty  | Unit Price | Disc % | Amount |
|----|----|-----------------------------------------------------|------|------------|--------|--------|
| 31 | 0  | T90467-08186 C3 CLIP <i>ne</i>                      | 2.00 | 2.60       |        | 5.20   |
| 32 | 1  | S75431-02090 LUGGAGE COMP EMBLEM, <i>ne</i>         | 1.00 | 65.30      |        | 65.30  |
| 33 | 2  | S75442-0D400 PLATE, LUGGAGE COMPT <i>ne</i>         | 1.00 | 48.30      |        | 48.30  |
| 34 | 3  | S75444-0D690 PLATE, LUGGAGE COMPT <i>ne</i>         | 1.00 | 37.60      |        | 37.60  |
| 35 | 4  | S81550-0DA50 LAMP ASSY, RR COMBIN <i>ca</i>         | 1.00 | 403.80     |        | 403.80 |
| 36 | 5  | S81560-0DA50 LAMP ASSY, RR COMBIN <i>Xnn</i>        | 1.00 | 403.80     |        | 403.80 |
| 37 | 6  | S52562-0D130 RETAINER, RR BUMPER, <i>?Xnn</i>       | 1.00 | 63.40      |        | 63.40  |
| 38 | 7  | S52563-0D130 RETAINER, RR BUMPER, <i>?Xnn</i>       | 1.00 | 63.40      |        | 63.40  |
| 39 | 8  | S81580-0D500 LAMP ASSY, RR, RH <i>Xnn</i>           | 1.00 | 260.60     |        | 260.60 |
| 40 | 9  | S81590-0D500 LAMP ASSY, RR, LH <i>Xnn</i>           | 1.00 | 260.60     |        | 260.60 |
| 41 | 0  | T89997-30100 ANTENNA, ELECTRICAL <i>?Xnn</i>        | 1.00 | 76.30      |        | 76.30  |
| 42 | 1  | T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>Xnn</i> | 2.00 | 108.00     |        | 216.00 |
| 43 | 2  | T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>Xnn</i>  | 1.00 | 200.00     |        | 200.00 |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*Handwritten notes:*  
2 days  
EXCESS: TBA  
07/01/22  
Remy before paint

|                                                         |                                       |                                                                                              |                                                                      |
|---------------------------------------------------------|---------------------------------------|----------------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd | Customer's Signature                  | Charge Summary                                                                               | Total                                                                |
| Signature:<br>Date:                                     | Please acknowledge receipt of vehicle | Parts 7,944.00<br>Labour 10,904.40<br>Sublet 260.00<br>Lubrication/Fluid 0.00<br>Others 0.00 | 19,108.40<br>GST 7.00% 1,337.59<br>Less 0.00<br>Amount Due 20,445.99 |