

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Wong

Date: 10 Jan 2022

## **Preliminary Advice**

Vehicle No	: SLZ1418T	Accident Date	: 02/01/2022
Make	: TOYOTA VIOS	Policy No.	: MP316928
Assignment Date	: 04/01/2022	Excess	: S\$0.00
Date of Inspection	: 7/1/2022	Est. Duration of Repair	: 7
Inspection At	: BORNEO MOTORS (S) PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,108.40
Revised Amount	:S\$	9,492.60
Check Items (Estimated)	:S\$	2,355.80
Total	:S\$	11,848.40
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	35,446.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,554.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .