

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details
Case Ref. No. : OD/012022/5163
Date : 04-01-2022
Accident Date : 01-01-2022

Vehicle Details

Make & Model : Mercedes Benz C200 SPORT
AUTO
Chassis No : WDD2050422R338855
Registration No : SLT8367S

Third Party Vehicle Details

Registration No : SMN167A

S/N	Description	Qty	Amount (\$S)
1	FRONT RH HEADLAMP <i>✓ SDR</i>	1.00	✓ \$1,800.00
2	FRONT LH HEADLAMP <i>✓ SDR</i>	1.00	✓ \$1,800.00
3	FRONT RH HEADLAMP BRACKET <i>X SDR</i>	1.00	\$40.00
4	FRONT LH HEADLAMP BRACKET <i>X SDR</i>	1.00	\$40.00
5	FRONT GRILLE BASE <i>✓ SDR</i>	1.00	\$80.00 ✓
6	FRONT GRILLE <i>✓ SDR</i>	1.00	\$120.00 ✓
7	FRONT GRILLE EMBLEM <i>✓ SDR</i>	1.00	\$80.00 ✓
8	FRONT GRILLE EMBLEM HOUSING <i>✓ SDR</i>	1.00	\$50.00 ✓
9	FRONT GRILLE RH CHROME - TOP <i>✓ SDR</i>	1.00	\$40.00 ✓
10	FRONT GRILLE RH CHROME - LOWER <i>✓ SDR</i>	1.00	\$50.00 ✓
11	FRONT GRILLE LH CHROME - TOP <i>✓ SDR</i>	1.00	\$40.00 ✓
12	FRONT GRILLE LH CHROME - LOWER <i>✓ SDR</i>	1.00	\$50.00 ✓
13	FRONT BUMPER <i>✓ SDR</i>	1.00	\$880.00 ✓
14	FRONT BUMPER CENTRE LOWER BUMPER <i>grille X SDR</i>	1.00	\$70.00
15	FRONT BUMPER RH FOG LAMP COVER <i>X</i>	1.00	\$40.00
16	FRONT BUMPER LH FOG LAMP COVER <i>X</i>	1.00	\$40.00
17	FRONT BUMPER PARKING SENSOR - OUTER @ \$100.00 <i>✓ DM</i>	2.00	\$200.00 100
18	FRONT BUMPER PARKING SENSOR - INNER @ \$100.00 <i>✓ DM</i>	4.00	\$400.00 100
19	FRONT BUMPER RH SIDE RETAINER <i>X SDR</i>	1.00	\$50.00
20	FRONT BUMPER LH SIDE RETAINER <i>X SDR</i>	1.00	\$50.00
21	FRONT BUMPER AIR DUCT <i>✓ SDR</i>	1.00	\$70.00 ✓
22	FRONT BUMPER SPONGE <i>✓ SDR</i>	1.00	\$110.00 ✓
23	FRONT BUMPER REINFORCEMENT <i>✓ SDR</i>	1.00	\$250.00 ✓
24	FRONT BUMPER INNER TOP BEAM <i>✓ SDR</i>	1.00	\$140.00 ✓
25	FRONT BUMPER TOP CENTRE COVER <i>✓ BR</i>	1.00	\$50.00 ✓
26	FRONT SUPPORT PANEL <i>✓ BT</i>	1.00	\$410.00 ✓

Margin: 10%

\$6,950.00 7570

\$695.00

\$7,645.00 8327

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

27	FRONT NO. PLATE SZ X NN	1.00	\$40.00
28	TO REFILL AIRCON GAS X NN	1.00	\$120.00
29	TO RESET ECU X NN	1.00	\$250.00
30	TO REPAIR DAMAGES (Inc. bonnet)	1.00	\$780.00 <i>600</i>
31	TO SPRAY PAINTING (Inc. bonnet)	1.00	\$880.00 <i>700</i>

Subtotal w/o GST: \$9,715.00

9627

5 Days.
 P/B
 Refuel first photos
 Gmo QSP
 Guess : TBA
 Not Authorise

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.