

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 24 February 2022 10:07 AM
To: Shiau Chan (LKKAUTO)
Subject: FW: SLN 5055T

Case finalised

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: EM Auto [<mailto:emautosolution@singnet.com.sg>]
Sent: Wednesday, 23 February, 2022 5:04 PM
To: Rasul (LKKAUTO)
Subject: RE: SLN 5055T

Hi Rasul

Confirmed Lump Sum \$2550.00 – 4 working days.

Thank you.

Sirina Soon

Senior Claim Executive

E M Solution Pte Ltd

160 Sin Ming Drive

#03-18/19 Sin Ming Autocity

Singapore 575722

Tel. 64560226

Fax. 64584500

HP. 92236288

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]
Sent: Wednesday, 23 February, 2022 9:30 AM
To: emautosolution@singnet.com.sg
Subject: RE: SLN 5055T

Hi Mdm,

Any update?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)

Sent: Tuesday, 22 February, 2022 10:31 AM

To: 'emautosolution@singnet.com.sg'

Subject: SLN 5055T

Hi Mdm,

Refer to attachment

Take note, audit checked 1 of the item part prices slightly high, necessary adjustment has to be made.

We will be advising our Principal a cost of repair of L/S \$2,550.00/- with 4 days of repair, subject to their approval

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.