

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowok@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 11.01.2022

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **PA8738H**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 03.01.2022
TIME OF ACCIDENT : 14:30HRS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE PANEL RH <i>Repair</i>	1	\$ 2,979.00	\$ 2,979.00
2	REAR SIDE PANEL GLASS LH <i>new</i>	1	\$ 1,210.10	\$ 1,210.10
3	SIDE PANEL GLASS MOULDING (FRONT) RH	1	\$ 218.00	\$ 218.00
4	SIDE PANEL GLASS MOULDING (CENTER) RH	1	\$ 101.00	\$ 101.00
5	SIDE PANEL GLASS MOULDING (REAR) RH	1	\$ 218.00	\$ 218.00
6	REAR BUMPER SIDE RETAINER	2	\$ 55.00	\$ 110.00

TOTAL PRICE \$ 4,836.10
LESS 25% \$ 1,209.03
SUB TOTAL PRICE \$ 3,627.08

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR SIDE PANEL STICKER 'PRIVATE BUS' <i>new</i>	1	\$ 120.00	\$ 120.00
2	REAR SIDE PANEL STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 380.00	\$ 380.00
3	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	SIDE PANEL GLASS SEALANT (FRONT) RH	1	\$ 80.00	\$ 80.00
5	SIDE PANEL GLASS INNER SEAL (FRONT) RH	1	\$ 60.00	\$ 60.00
6	SIDE PANEL GLASS SEALANT(CENTER) RH	1	\$ 80.00	\$ 80.00
7	SIDE PANEL GLASS INNER SEAL (CENTER) RH	1	\$ 60.00	\$ 60.00
8	SIDE PANEL GLASS SEALANT(REAR) RH	1	\$ 80.00	\$ 80.00
9	SIDE PANEL GLASS INNER SEAL (REAR) RH	1	\$ 60.00	\$ 60.00
10	TAIL LAMP CLIP (SET)	1	\$ 40.00	\$ 40.00
11	SIDE PANEL INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00

TOTAL \$ 1,090.00

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **PA8738H**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 03.01.2022
TIME OF ACCIDENT : 14:30HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,800.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	400
3	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 650.00	x
4	REMOVE AND REFIX REAR SIDE PANEL GLASS RH X3	\$ 480.00	x
5	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	x
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

4990

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,717.08
TOTAL LABOUR COST : \$ 4,990.00
TOTAL REPAIR COST : \$ 9,707.08

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P 12/01/22
03 Days

total: 950 (P/P)