

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000173/GVY3E2

Date: 09/03/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00254022104

Claimant Vehicle
No : SBS3128Y

Insured Vehicle
No : SJL8197G

Date of Loss: 30/12/2021

Nature of Claim: TP

Claim
No: SNM21D207714/C03/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS3128Y

Make & Model: VOLVO B9TL, 9.4 D (A)

Engine No: D9187056

Reg. Date: 30/05/2012 (Man. Year: 2012)

Chassis No: YV3S4P925CA155931

Colour: Multi-colour

Odometer: 0 km

Engine Capacity: 9364 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,960.00	1,960.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,279.50	1,095.50	184.00	14.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,239.50	3,055.50	184.00	5.68
+ GST 7.00/7.00% (S\$)	226.77	213.89	12.88	5.68
Nett Amount (S\$)	3,466.27	3,269.39	196.88	5.68

INSPECTION

Date of Assignment: 05/01/2022

Date Inspected: 06/01/2022

Inspected At: SBS Transit Ltd (AMK)
15 Ang Mo Kio Street 63
Singapore 569117

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Mar 2022)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3128Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BATTERY ACCESS PANEL;SHEETMETAL	Distorted	639.00 F	*639.00 F
2	1		*SEALED LEVER LATCH;OS/NS;RR SIDE DR	Necessary	34.00 F	*34.00 F
3	1		*SEMI MAINT.FREE BATTERY 200AH;FURUKAWA	Damaged	195.00 F	*195.00 F
4	1		*SEMI MAINT.FREE BATTERY 200AH;FURUKAWA	Damaged	195.00 F	*195.00 F
5	1		*BATTERY BOX;B9TL EU5	Cracked	897.00 F	*897.00 F
F=Franchise part.						
Total Parts (S\$)					1,960.00	1,960.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	(2) WORKSHOP LABOUR	New	184.00	0.00
2	CONTRACTORS REPAIR CHARGES	New	780.00	780.00
3	TOWING CHARGES	New	218.00	218.00
4	REPAIR COST OF ADVERTISEMENT / LIVERY	New	97.50	97.50
Gross Labour Cost (\$\$)			1,279.50	1,095.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >