

AUTOLUTION
CARTIMES
 CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel : 6471 5111
 Email : claims@cartimes.com.sg

Not Authorized
Permy B4pain
6/1/82
6-7 days

VEHICLE NO: SMY7896A

MODEL: TOYOTA SIENTA

CHASSIS NO: NHP170-7189150

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>			
REAR TAILGATE	R	\$ 1,200.00	✓
REAR TAILGATE INNER TRIM		\$ 200.00	?
REAR TAILGATE LOCK ASSY	Tr	\$ 200.00	✓
TAILGATE CENTRE GARNISH		\$ 150.00	
REAR TAIL LAMP PANEL LHS		\$ 100.00	?
REAR TAIL LAMP PANEL RHS		\$ 100.00	?
REAR TAIL LAMP LHS		\$ 320.00	?
REAR TAIL LAMP RHS		\$ 320.00	?
REAR TAILGATE LAMP LHS		\$ 300.00	?
REAR TAILGATE LAMP RHS	Tr	\$ 300.00	X
REAR BUMPER	R	\$ 400.00	✓
REAR BUMPER RETAINER LHS	Tr	\$ 80.00	X
REAR BUMPER RETAINER RHS	Tr	\$ 80.00	X
REAR TOYOTA EMBLEM	Tr	\$ 80.00	✓
REAR HYBRID EMBLEM	Tr	\$ 70.00	✓
REAR BUMPER CENTRE TRIM	R	\$ 200.00	✓
REAR BUMPER LHS TRIM	Adl	\$ 180.00	✓
REAR BUMPER RHS TRIM	Tr	\$ 180.00	X
REAR BUMPER REFLECTOR RHS	Tr	\$ 100.00	X
REAR BUMPER REFLECTOR LHS	Tr	\$ 100.00	X
REAR FENDER LHS	R	\$ 1,500.00	X
REAR FENDER RHS	R	\$ 1,500.00	X
REAR FENDER INNER TRIM LHS	Tr	\$ 400.00	X
REAR FENDER INNER TRIM RHS	Tr	\$ 400.00	X
REAR WINDSCREEN MOULDING	Tr	\$ 120.00	✓
END PANEL OUTER		\$ 400.00	?
END PANEL INNER		\$ 710.00	?
REAR FENDER INNER TRIM LHS	Tr	\$ 630.00	X
REAR FENDER INNER TRIM RHS	Tr	\$ 630.00	X
END PANEL TOP GARNISH	Tr	\$ 150.00	✓
SMART BUZZER		\$ 100.00	?
SPARE TYRE PANEL	R	\$ 700.00	?

TAIL LAMP INNER PANEL BRACKET LHS	\$ 200.00	7
TAIL LAMP INNER PANEL BRACKET RHS	\$ 200.00	7
TAILGATE WEATHERSTRIP	\$ 400.00	7
SPARE TYRE PANEL	<i>nc</i> \$ 900.00	X
FLOORBOARD	\$ 1,200.00	7
FLOORBOARD COVER	\$ 500.00	7
	\$ 15,300.00	
25%	\$ 3,825.00	
	\$ 11,475.00	
<u>SPECIAL NETT ITEMS</u>		
REAR BUMPER CLIPS 1 SET	<i>nc</i> \$ 100.00	<i>Join</i>
REAR CARPLATE W/HOLDER	<i>in</i> \$ 60.00	X
REAR SENSORS	<i>short</i> \$ 200.00	✓
DASH CAM	<i>in</i> \$ 300.00	X
WINDSCREEN SEALANT	<i>nc</i> \$ 40.00	✓
CEREMIC COATING	\$ 400.00	7
(REAR BUMPER / TAILGATE)		
Total	\$ 1,100.00	
TOTAL PARTS	\$ 12,575.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
	LABOUR	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00
4	To provide anti-rust treatment on affected areas	\$ 100.00
5	Remove & refit rear upholstery	\$ 300.00
6	Transfer tailgate parts	\$ 150.00
7	Dignostic Check	\$ 100.00
8	Remove & refit rear sensors	\$ 100.00
	Labour Total :	\$ 4,250.00
	TOTAL (PARTS & LABOUR):	\$ 16,825.00

?

8001

201

?

801

601

?

501