

Not Authorized
Repairing B4paim
6/1/22
10-days
1/1/22 @ 5800h

VEHICLE NO: SMY7896A

MODEL: TOYOTA SIENTA

CHASSIS NO: NHP170-7189150

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
REAR TAILGATE	Ry	\$ 1,200.00 ✓
REAR TAILGATE INNER TRIM	Sn	\$ 200.00 X
REAR TAILGATE LOCK ASSY	Tm	\$ 200.00 ✓
TAILGATE CENTRE GARNISH	Sn	\$ 150.00 X
REAR TAIL LAMP PANEL LHS	R	\$ 100.00 X
REAR TAIL LAMP PANEL RHS	R	\$ 100.00 X
REAR TAIL LAMP LHS	mym	\$ 320.00 ✓
REAR TAIL LAMP RHS	m	\$ 320.00 ✓
REAR TAILGATE LAMP LHS	mym	\$ 300.00 ✓
REAR TAILGATE LAMP RHS	Sn	\$ 300.00 X
REAR BUMPER 350.20	Ry	\$ 400.00 ✓
REAR BUMPER RETAINER LHS	Sn	\$ 80.00 X
REAR BUMPER RETAINER RHS	Sn	\$ 80.00 ✓
REAR TOYOTA EMBLEM	mm	\$ 80.00 ✓
REAR HYBRID EMBLEM	mm	\$ 70.00 ✓
REAR BUMPER CENTRE TRIM	Ry	\$ 200.00 ✓
REAR BUMPER LHS TRIM	Red/G	\$ 180.00 ✓
REAR BUMPER RHS TRIM	Sn	\$ 180.00 X
REAR BUMPER REFLECTOR RHS	Sn	\$ 100.00 X
REAR BUMPER REFLECTOR LHS	Sn	\$ 100.00 X
REAR FENDER LHS	R	\$ 1,500.00 X
REAR FENDER RHS	R	\$ 1,500.00 X
REAR FENDER INNER TRIM LHS	Sn	\$ 400.00 X
REAR FENDER INNER TRIM RHS	Sn	\$ 400.00 X
REAR WINDSCREEN MOULDING	mm	\$ 120.00 ✓
END PANEL OUTER 689.75	Ry	\$ 400.00 ✓
END PANEL INNER	Ry	\$ 710.00 ✓
REAR FENDER INNER TRIM LHS	Sn	\$ 630.00 X
REAR FENDER INNER TRIM RHS	Sn	\$ 630.00 X
END PANEL TOP GARNISH	mm	\$ 150.00 ✓
SMART BUZZER	CM	\$ 100.00 ✓
SPARE TYRE PANEL	Ry/Bu	\$ 700.00 ✓

TAIL LAMP INNER PANEL BRACKET LHS	n	\$	200.00	X
TAIL LAMP INNER PANEL BRACKET RHS	n	\$	200.00	X
TAILGATE WEATHERSTRIP 361	Di i lnd	\$	400.00	n
SPARE TYRE PANEL	n	\$	900.00	X
FLOORBOARD	sn	\$	1,200.00	X
FLOORBOARD COVER	ln	\$	500.00	X
			\$ 15,300.00	
	25%		\$ 3,825.00	
			\$ 11,475.00	
<u>SPECIAL NETT ITEMS</u>				
REAR BUMPER CLIPS 1 SET	ln	\$	100.00	50sn
REAR CARPLATE W/HOLDER	ln	\$	60.00	X
REAR SENSORS	shen	\$	200.00	✓
DASH CAM	ln	\$	300.00	X
WINDSCREEN SEALANT	ln	\$	40.00	✓
CEREMIC COATING	(Bill) NEC	\$	400.00	n
(REAR BUMPER / TAILGATE)				
	Total		\$ 1,100.00	
	TOTAL PARTS		\$ 12,575.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00
4	To provide anti-rust treatment on affected areas	\$ 100.00
5	Remove & refit rear upholstery	\$ 300.00
6	Transfer tailgate parts	\$ 150.00
7	Dignostic Check	\$ <i>nn</i> 100.00
8	Remove & refit rear sensors	\$ 100.00
	Labour Total :	\$ 4,250.00
	TOTAL (PARTS & LABOUR):	\$ 16,825.00

1200

800

200

900

800

600

X

500