

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

OH HUI CHIN
BLK 737 YISHUN STREET 72 #05-93
SINGAPORE 760737

Contact : 96454552

TAX INVOICE

Repair Code : CLM17046

Date in : 03/01/2022

Vehicle Num. : SMU9774B

Model : AUDI A1 SB S LINE 1.0 TFSI S TRONIC

Chassis/Eng# : WAUZZZGB8LR044561/DKJ052732

TP AXA
Cecilia

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	1900.75	✓ 1,900.75
FRONT RH DOOR CHECKER <i>new</i>	1	189.71	✗ 189.71
FRONT RH DOOR GLASS CHANNEL SEAL <i>3 new</i>	1	389.96	✗ 389.96
FRONT RH DOOR GLASS REGULATOR	1	399.70	✗ 399.70
FRONT RH DOOR HINGES (TOP & LOWER) <i>Lower Bent</i>	2	300.35	<i>300.35</i> 600.70
FRONT RH DOOR INNER TRIM BOARD <i>cracked</i>	1	1700.10	<i>950.</i> 1,700.10
FRONT RH DOOR MECHANISM LOCK <i>new</i>	1	689.85	✗ 689.85
FRONT RH DOOR OUTER MOULDING <i>new</i>	1	189.70	✗ 189.70
FRONT RH DOOR WEATHER STRIP SEAL <i>new</i>	1	200.33	✓ 200.33
FRONT RH FENDER <i>Dented</i>	1	800.77	✓ 800.77
FRONT RH FENDER 'S LINE' EMBLEM <i>new</i>	1	90.95	✓ 90.95
FRONT RH FENDER INNER END COVER <i>new</i>	1	133.95	✗ 133.95
FRONT RH FENDER INNER SHIELD <i>torn</i>	1	120.95	✓ 120.95
RH SIDE ROCKER PANEL <i>Dented</i>	1	1500.75	✓ 1,500.75
RH SIDE ROCKER PANEL GARNISH MOULDING <i>Dented</i>	1	400.05	✓ 400.05
RH SIDE ROCKER PANEL TOP GARNISH <i>new</i>	1	397.60	✓ 397.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

7 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

OH HUI CHIN

BLK 737 YISHUN STREET 72 #05-93

SINGAPORE 760737

Contact : 96454552

TAX INVOICE

Repair Code : CLM17046

Date in : 03/01/2022

Vehicle Num. : SMU9774B

Model : AUDI A1 SB S LINE 1.0 TFSI S TRONIC

Chassis/Eng# : WAUZZZGB8LR044561/DKJ052732

Subtotal before discount 6662.50 9,705.82

Percentage discount 0%

Sub-total 1

0.00

9,705.82

FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>Nec</i>	1	50.00	30	50.00
FRONT RH FENDER INNER END COVER CLIPS - SET <i>Ne n</i>	1	20.00	X	20.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>Nec</i>	1	50.00	30	50.00
RH SIDE ROCKER PANEL GARNISH MOULDING CLIPS - SET <i>Nec</i>	1	50.00	✓	50.00
RH SIDE ROCKER PANEL GARNISH MOULDING WRAP STICKER <i>Nec</i>	1	200.00	X	200.00

Subtotal before discount 370.00

Percentage discount 0%

Sub-total 2

0.00

370.00

Parts-total

10,075.82

LABOUR

To reset system after repair works

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

150 300.00

80 150.00

80 150.00

750 1,200.00

800 1,400.00

60 120.00

Labour Total

3,320.00

Parts & Labour Total

13,395.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items (if any) is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.

page 2

Total 8/2625

4/5: 6.5K

07 Days

6.5K