



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 04/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	07/06/2017	SLP4767T	0	12463	75/DS/SLP4767T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3902011936		2NRX159042	60	Ng Mei Yen	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PC821S ACC DATE:04/01/2022 DRIVE IN:04/01/2022 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30 100.00	
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				180.00	
3	B	BP-LAB2 RESET ECU UPON COMPLETION OF REPAIR				180.00	
4	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00	
5	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA				1440 5040.00	
6	B	BP-RES2 RESPRAY ACC AFF AREA				2360 3540.00	
7	1	K52119-0U920 COVER, FR BUMPER, L	1.00	525.80		525.80	
8	2	K53112-0D360 GRILLE, RADIATOR, LW	1.00	304.70		304.70	
9	3	K52021-0D140 REINFORCEMENT SUB-AS	1.00	423.90		423.90	
10	4	K52127-0D430 COVER, FR BUMPER HOL	1.00	63.40		63.40	
11	5	K53101-0D904 GRILLE SUB-ASSY, RAD	1.00	216.60		216.60	
12	6	K53121-0D200 MOULDING, RADIATOR G	1.00	73.40		73.40	
13	7	K53124-0D140 MOULDING, RADIATOR G	1.00	73.40		73.40	
14	8	K53301-0D160 HOOD SUB-ASSY	1.00	982.10		982.10	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

ICODE
Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
				Document No.					
				0					
				Document Date					
				04/01/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	NSP151R	CEXRKT Q1	07/06/2017	SLP4767T	0	12463	75/DS/SLP4767T		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MHFB29F3902011936		2NRX159042	60	Ng Mei Yen	--/--/----		0.00		0.00
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
15	9	K53866-0D160	SEAL, FR FENDER TO C	1.00	48.60		48.60		
16	0	K53867-0D160	SEAL, FR FENDER TO C	1.00	48.60		48.60		
17	1	K90105-T0120	BOLT, FLANGE ?	1.00	2.50		2.50		
18	2	K53811-K0020	PANEL, FR FENDER, RH	1.00	747.70		747.70		
19	3	K53812-K0020	PANEL, FR FENDER, LH	1.00	747.70		747.70		
20	4	K16400-0Y231	RADIATOR ASSY	1.00	2176.50		2176.50		
21	5	K16711-0Y090	SHROUD, FAN	1.00	314.90		314.90		
22	6	K81110-0D831	HEADLAMP ASSY, RH	1.00	644.20		644.20		
23	7	K81150-0D831	HEADLAMP ASSY, LH	1.00	644.20		644.20		
24	8	K90975-T2008	EMBLEM, SYMBOL	1.00	61.90		61.90		
IKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer									
Signature: _____ Date: _____ Borneo Motors (Singapore) Pte Ltd				Customer's Signature _____		Charge Summary		Total 17,220.10	
Please acknowledge receipt of vehicle				Parts 8,100.10 Labour 9,040.00 Sublet 80.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 1,205.41 Less 0.00		Amount Due 18,425.51	

email: rasul@ikkauto.com