

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO22000188/Ktf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623		Date:	28/02/2022	
				Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKM 6855L	Veh. Inspected		SML 9873X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2200057/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		06/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES C180 (A)	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	WDD2040452A500278	Colour		METALLIC GREY	
	Odometer	193734 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	PIRELLI		7 mm	
	L/H Front Tyre	225/45 R17	PIRELLI		7 mm	
	R/H Rear Tyre	225/45 R17	PIRELLI		7 mm	
	L/H Rear Tyre	225/45 R17	PIRELLI		7 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/01/2022	Inspection Date	•	06/01/2022	
	Survey held at	TENG MENG MOTOR SERVICE				
		176 SIN MING DRIVE SIN MING AUTOCARE				
		#04-01 & #04-10 SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
	·					