

TO : ERGO MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL1162Y
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 05.01.2022
 TIME OF ACCIDENT : 18:00HRS

27	COOLER AIR GUARD RUBBER	2	\$ 110.00	\$ 220.00	x
28	WASHER TANK	1	\$ 210.30	\$ 210.30	f
29	ADBULB TANK	1	\$ 983.40	\$ 983.40	t
30	AIR CLEANER BOX	1	\$ 794.60	\$ 794.60	t.
31	TAILGATE	1	\$ 1,850.00	\$ 1,850.00	✓
32	TAILGATE WINDSCREEN GLASS	1	\$ 1,351.70	\$ 1,351.70	✓
33	TAILGATE OUTER MOULDING	1	\$ 324.00	\$ 324.00	-
34	TAILGATE OUTER HANDLE	1	\$ 149.00	\$ 149.00	+
35	TAIGATE NUMBER PLATE LAMP	1	\$ 65.30	\$ 65.30	+
36	TAILGATE LOGO	1	\$ 50.00	\$ 50.00	-
37	TAILGATE 'HIACE' STICKER	1	\$ 59.00	\$ 59.00	-
38	TAILGATE CORNER GARNISH	2	\$ 36.20	\$ 72.40	+
39	TAILGATE STOPPER	2	\$ 24.60	\$ 49.20	-
40	TAILGATE INNER BOARD	1	\$ 240.00	\$ 240.00	162
41	TAILGATE WEATHERSTRIP	1	\$ 395.00	\$ 395.00	✓
42	TAILGATE WEATHERSTRIP PROTECTOR	1	\$ 217.00	\$ 217.00	✓
43	TAILGATE INNER LOCK	1	\$ 340.00	\$ 340.00	-
44	TAILGATE LOCK MOTOR	1	\$ 545.00	\$ 545.00	+
45	TAILGATE LOWER LOCK	1	\$ 105.00	\$ 105.00	+
46	TAIL LAMP	2	\$ 375.00	\$ 750.00	-
47	TAIL LAMP PANEL	2	\$ 350.00	\$ 700.00	370
48	TAILLAMP LOWER GARNISH	2	\$ 167.00	\$ 334.00	-
49	TAILLAMP LOWER GARNISH RETAINER	2	\$ 65.00	\$ 130.00	+
50	REAR BUMPER	1	\$ 479.00	\$ 479.00	-
51	REAR BUMPER NUT COVER	2	\$ 29.00	\$ 58.00	+
52	REAR BUMPER STEP PANEL	1	\$ 398.00	\$ 398.00	✓
53	REAR BUMPER SIDE RETAINER	2	\$ 55.00	\$ 110.00	-
54	REAR END PANEL (EXTEND)	1	\$ 295.00	\$ 295.00	+
55	REAR END PANEL (INNER)	1	\$ 871.00	\$ 871.00	-
56	REAR END PANEL (OUTER)	1	\$ 597.00	\$ 597.00	-
53	REAR FLOOR PANEL	1	\$ 1,960.00	\$ 1,960.00	+
57	REAR FLOOR PANEL MAT	1	\$ 1,359.00	\$ 1,359.00	+
58	REAR SPARE TYRE HOLDER BRACKET	1	\$ 380.00	\$ 380.00	+
59	REAR SPARE TYRE HOLDER BOLT	1	\$ 60.00	\$ 60.00	+
60	REAR EXHAUST PIPE	1	\$ 1,410.00	\$ 1,410.00	+
61	REAR EXHAUST MOUNTING	2	\$ 58.00	\$ 116.00	+
62	REAR EXHAUST BRACKET	1	\$ 90.00	\$ 90.00	+

TO : ERGO MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL1162Y
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 05.01.2022
 TIME OF ACCIDENT : 18:00HRS

21865
 16398.75

TOTAL PRICE \$ 37,985.70
 LESS 25% \$ 9,496.43
 SUB TOTAL PRICE \$ 28,489.28

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Repld</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
3	FRONT GRILLE (UPPER) CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
4	FRONT GRILLE (LOWER) CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
5	FRONT GRILLE UPPER COVER GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
6	FRONT GRILLE CENTER COVER GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
7	FRONT SUPPORT PANEL SEALANT <i>New</i>	1	\$ 60.00	\$ 60.00
8	WIPER PANEL GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
9	BONNET SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00
10	COOLANT <i>New</i>	1	\$ 60.00	\$ 60.00
11	REAR NUMBER PLATE <i>Repld</i>	1	\$ 50.00	\$ 50.00
12	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
13	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
14	TAILLAMP LOWER GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
15	TAILGATE CENTER MOULDING CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
16	TAILGATE SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00
17	TAILGATE OUTER MOULDING CLIP (SET) <i>Repld</i>	1	\$ 50.00	\$ 50.00
18	TAILGATE CORNER GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00
19	TAILGATE TOP TRIM CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
20	TAILGATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
21	TAIL GATE STICKER "8PAX" <i>New</i>	1	\$ 50.00	\$ 50.00
22	TAILGATE STICKER '70KM/H' <i>New</i>	1	\$ 30.00	\$ 30.00
23	TAIL GATE STICKER 'CHINESE WORDING' <i>New</i>	1	\$ 80.00	\$ 80.00
24	TAIL GATE STICKER 'AR' SPECAIL TYPE <i>New</i>	1	\$ 120.00	\$ 120.00
25	TAILGATE WINDSCREEN SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00
26	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
27	REAR END PANEL (OUTER) SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00
28	REAR END PANEL (EXTEND) SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00
29	REAR FLOOR PANEL TOP BOARD (WOODEN) SPECAIL TYPE <i>Repld</i>	1	\$ 800.00	\$ 800.00
30	REVERSE SENSOR <i>Repld</i>	1	\$ 220.00	\$ 220.00
31	REVERSE CAMERA <i>Repld</i>	1	\$ 550.00	\$ 550.00

11530 TOTAL \$ 3,350.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

TO : ERGO MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL1162Y
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 05.01.2022
 TIME OF ACCIDENT : 18:00HRS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600
3	TUFF COAT	\$ 250.00	60.
4	WIRING CHECK	\$ 80.00	30
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x
6	REMOVE AND REFIX TURBO COOLER	\$ 120.00	x.
7	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60

16/0

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,200.00	1200.
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	1000.
3	WIRING, BULB CHECKING	\$ 80.00	30
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	✓
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
6	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
8	REMOVE AND REFIX REAR FLOOR TOP BOARD (WOODEN)	\$ 500.00	100.
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
8	REAR CHASSIS ALIGHMENT	\$ 250.00	x
9	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50

TO : ERGO MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL1162Y
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 05.01.2022
 TIME OF ACCIDENT : 18:00HRS

10	REMOVE AND REFIX REAR WINDSCREEN	\$	120.00	✓
----	----------------------------------	----	--------	---

TOTAL \$ 9,040.00 2580

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,839.28
 TOTAL LABOUR COST : \$ 9,040.00
 TOTAL REPAIR COST : \$ 40,879.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP 8297 9787

Adrian G
 H/S 07/01/22.

15 Days.

Total: 22618.75

H/S: 17.7K

17.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: