

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000194/UTY3E2**Date:** 14/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00006932100

Claimant Vehicle No : SLM6754H **Insured Vehicle No :** SLZ671J

Date of Loss: 05/01/2022 Nature of Claim: TP Claim No: SNM22D200129/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM6754H**

Make & Model: HONDA VEZEL HYBRID, 1.5 RS (A) Engine No: LEB5913945

Reg. Date: 05/04/2017 (Man. Year: 2016) Chassis No: RU31213935

Colour: Black Odometer: 70032 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,130.00	2,165.00	965.00	30.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	394.80	163.80	231.00	58.51
Paintwork Labour	373.96	373.96	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,898.76	2,702.76	1,196.00	30.68
+ GST 7.00/7.00% (S\$)	272.91	189.19	83.72	30.68
Nett Amount (S\$)	4,171.67	2,891.95	1,279.72	30.68

INSPECTION

Date of Assignment: 06/01/2022 Present Location: Jin Auto Services Pte Ltd (Defu)

Date Inspected: 06/01/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Mar 2022)**Parts:** M1-SUV HONDA VEZEL HYBRID 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLM6754H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRY	Necessary	100.00 F	*100.00 F	
2	1		*TOTAL PARTS		2,400.00 F	*1,515.00 F	
3	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
<u>Supplementary #1</u>							
4	1		*Supplementary LH Taillamp \$350.	Cracked	350.00 F	*350.00 F	
					Total Parts (\$)	3,130.00	2,165.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT LABOUR	New	373.96	373.96
<u>Labour Items</u>				
2	TOTAL LABOUR	New	394.80	163.80
			Gross Labour Cost (S\$)	768.76
				537.76

Report was unsubmitted during this print-out.

< END OF ESTIMATES >