

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520

Date : 06/01/2022

FAX :

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000059 Accident Date : 15/12/2021

Vehicle No : GBD-4132-G Make & Model : MITSUBISHI L200 TRITON DOUBLE C 2.5 G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	Cost price	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>				
1	TAILGATE	Body rd	1,100.00	✓
1	TAILGATE EMBLEM CENTRE	ner	40.00	✓
1	TAILGATE EMBLEM MITSUBISHI	ner	40.00	✓
1	TAILGATE EMBLEM L200	ner	40.00	✓
1	TAILGATE HANDLE	nn	220.00	x
1	TAIL LAMP LH	nn	140.00	x
1	TAIL LAMP RH	one nlc	140.00	x
1	REAR REFLECTOR LH	nn	25.00	x
1	REAR REFLECTOR RH	one	25.00	✓

Date : 06/01/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000059

Accident Date : 15/12/2021

Vehicle No : GBD-4132-G

Make & Model : MITSUBISHI L200 TRITON DOUBLE C 2.5 G (A

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL <i>R</i>	650.00 <i>X</i>	
2	REAR END PANEL STOPPER <i>11</i>	60.00 <i>X</i>	
	Sub Total	2480.00	
	Add 15% On Parts	372.00	
	<u>Special Nett Item</u>		
1	REAR NUMBER PLATE <i>320</i>	35.00 <i>✓</i>	
1	REAR BUMPER BAR <i>su</i>	300.00 <i>X</i>	
1	REAR STOPPER LAMP RH <i>su</i>	180.00 <i>X</i>	
<i>1627</i> 1	REVERSE SENSOR <i>cro</i>	200.00 <i>✓</i>	
1	LTA STICKER (70 KM/H) <i>ner</i>	15.00 <i>10</i>	

Date : 06/01/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000059 Accident Date : 15/12/2021

Vehicle No : GBD-4132-G Make & Model : MITSUBISHI L200 TRITON DOUBLE C 2.5 G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	730.00	
	Labour & Misc		
	LABOUR TO CARRY OUT REAR REPAIR	800.00	680
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	20
	TO SPRAY PAINTING ON REAR AFFECTED AREA	800.00	600
	SPRAY RUST PROOF ON AFFECTED AREA	60.00	40
	TO DETACH & RENEW REVERSE SENSOR	60.00	40

Date : 06/01/2022

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000059

Accident Date : 15/12/2021

Vehicle No : GBD-4132-G

Make & Model : MITSUBISHI L200 TRITON DOUBLE C 2.5 G (N

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

1755.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5 \$ 2400

1245
157
2 - 1431.75
S.N - 245
L-1380
308.75
202
2445

Remarks:

Not Authorized
LKK means

SUB TOTAL 5,337.00

GST 7.0 % 373.59

TOTAL 5,710.59

Surveyor's name:

tel: 62533561 HP 90096608

Principal's name: ETHOZ Group Ltd

moreuschuo@lkkauto.com

Survey Date & Time:

At day's

Tehephw Others

PAGE: 4