



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000195/Utf3n2	
			Date: 28/02/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMC 2828X	Veh. Inspected	GBD 4132G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103718/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	06/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	mitsubishi L200 TRITON (M)	c.c	2477
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	MMCJNKB40FD021546	Colour	WHITE
	Odometer	191544 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205 R16	WINDFORCE	6 mm
	L/H Front Tyre	205 R16	WINDFORCE	6 mm
	R/H Rear Tyre	205 R16	WINDFORCE	6 mm
	L/H Rear Tyre	205 R16	WINDFORCE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	15/12/2021	Inspection Date	06/01/2022
	Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	