

SKQ56996. 2014 Dec.

TP Somp
Veron.

Volkswagen Jetta 1390cc
WVWZZZ16ZEM05946

Rear Bumper	delid	1148	✓
Rear Bumper Clips.	x2	30(SN)	✓
Rear Bumper Side Holder x02	MP	75x2=150.	x
Rear Bumper Reflector x02	MP	85x2=170	x
Rear Bumper Reinforcement	MP	632	x
Rear Bumper Lower Garnish	delid	395	✓
Rear Bumper Centre Guide.	could	185	✓
Reverse Sensor x02	Pangc	200x2=400	✓
Bootlid	Ryis	1450	x
Bootlid Lock		385	x
Bootlid Weatherstripe	MP	319.	x
Volkswagen Logo	?	85	✓
Jetta Emblem.	MP	78	✓
TSI Emblem.	MP	55	✓
Bootlid Reflector x02	MP	365x2=730.	x

2346 SN: 30
2111.40

SKW 56996

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor.

~~600~~ 300

~~600~~ 500

~~50~~ 30

~~100~~ 50

7562.00

8800

total: 3021.40

H/s: 2.4K.

030 days

2.4K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: