

TPSMRT.
Veron

SLC7580M 2016 May.
Toyota Sienta 1496cc
NSP1707013891

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance Company

Approved by Repairer
Signature:

Reer	Bumper	Dehd	678.10	✓
Reer	Bumper Clips	nr	30(SN)	✓
Reer	Bumper Side Holder	x02 ^{xt} nr	82 x 2 = 164.	x
Reer	Bumper Centre Pad	Dehd	225	✓
Reer	Bumper Side Pad.	Crhd	127.5 x 2 = 255	✓
Reer	Bumper Reflector	x02 ^{xt} nr	80.5 x 2 = 161	x
Reer	Bumper Tow Cover	^{xt} nr	25	x
Reer	Bumper Centre Sponge	Crhd	98	✓
Reer	Reverse Sensor	Damaged	280(SN) 200(SN)	✓
Reer	End Panel	Repr	609	x
Reer	End Panel Top Garnish	Dehd	195.10	✓
Reer	End Panel Top Garnish Clips	nr	20(SN)	✓
Reer	End Panel Antenna Sensor.	Dmd	130.50	✓
Reer	Tailgate	Dented	1245.10	✓
Reer	Tailgate Lock	Damaged	372.90	✓

4488.80

SLC 7580M

Tailgate Weathershipe - ^{NY}_M 329.50 X
 Tailgate Inner Trim Board 322.10 X
 Tailgate Inner Trim Board Clips. ^{NY}_M 30(SN) X
 Tailgate Glass Sealant } 60(SN). ✓
 Toyota Logo. } New 75.30 ✓
 Benta Wording. 68.30 ✓

Floor Panel Top Board ^{NY}_{rec} 488.20 X

Tools Tray Delhd 419.40 ✓
 3762.80 S.W: 310
 2822.10

Panel Beating ~~1200~~ 600
 Spray Painting 1630 ~~1200~~ 600
 Wiring, ~~50~~ 30
 To remove reverse sensor ~~100~~ 50
 To remove rear camera. ~~100~~ 50
 To remove upholstery. ~~150~~ 50
 To spray tuft coat 150 50
 To remove tailgate glass 180 120
 To transfer tailgate fittings, ~~150~~ 80

total: 4762.10
 H/S: 3.8K
 04 Days