

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: SKN7393R
Model and make: Nissan Sylphy
Chassis: MNTBBAB17Z0019229

Qty Spare parts

List price

2014

1	Bootlid	\$	850.90	1,162.80	BTU
1	Bootlid upper chrome moulding	\$		185.70	
1	Bootlid lower chrome moulding	\$		81.70	NNX
1	Bootlid centre emblem	\$		46.90	
1	Bootlid "Sylphy" emblem	\$	75.20	87.00	KECV
1	Bootlid "XTONIC CVT" emblem	\$		57.70	
1	Bootlid RH lamp	\$		144.80	
1	Bootlid LH lamp	\$		144.80	NDX
1	Bootlid lock	\$		64.50	JMV
1	Bootlid lock catch	\$		57.60	NDX
1	Bootlid weatherstrip	\$		87.30	DISV
1	Bootlid RH hinge	\$		88.10	
1	Bootlid LH hinge	\$		88.10	NDX
1	Bootlid inner trim	\$		185.40	NDX
1	Rear bumper	\$		637.00	DDV
1	Rear bumper RH reflector	\$		55.30	
1	Rear bumper LH reflector	\$		55.30	BRV
1	Rear bumper RH retainer	\$	40.00	51.30	
1	Rear bumper LH retainer	\$	40.00	51.30	NECV
1	Rear bumper centre inner sponge	\$		56.00	
1	Rear bumper RH inner sponge	\$		105.30	
1	Rear bumper LH inner sponge	\$		105.30	BRV
1	Rear bumper RH bracket	\$		57.80	
1	Rear bumper LH bracket	\$		57.80	NSX
1	End panel	\$		428.60	DDV
1	End panel inner garnish	\$		91.80	BRV
1	End pane antenna sensor	\$	68.90	100.20	BRV
1	RH taillamp	\$	397.60	441.00	
1	LH taillamp	\$	397.60	441.00	BR
1	Rear RH fender	\$		1,387.50	NDX
1	Rear RH fender inner trim	\$	297.50	417.80	BRV
1	Rear LH fender	\$	703.40	1,387.50	BTU
1	Rear LH fender inner trim	\$	325.00	417.80	BRV
1	Spare tyre panel top cover	\$	280.00	421.20	BRV
1	Exhaust silencer	\$		890.20	NDX
1	Exhaust silencer gasket	\$		55.00	NNX

\$ 5,280.70 10,288.40
-10% \$ 528.07 1,028.84
\$ 4752.63 9,259.56

Qty Spare parts

1set Bootlid inner trim clips
 1set Rear bumper clips
 1set Rear bumper reverse sensor
 1 Rear windscreen glass sealant
 1 Rear windscreen glass inner seal
 1set Rear fender RH inner trim clips
 1set Rear fender LH inner trim clips
 1 End panel joint sealant
 1 Rear RH fender joint sealant
 1 Rear LH fender joint sealant

Special Nett price

\$ 30.00	70.00	} NECV
\$ 30.00	70.00	
\$ 200.00	280.00	} SCV
\$ 30.00	70.00	
\$ 20.00	50.00	} NECV
\$ 30.00	60.00	
\$ 30.00	60.00	} NECV
\$ 30.00	70.00	
\$ 30.00	60.00	} NNX
\$ 30.00	60.00	
<u>430.00</u>		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
 To panel beating, cut / weld and re-align all affected panels

\$ 1000.00 + 800.00 ✓

Spray painting on affected panels

\$ 8,000.00 + 500.00 ✓

Check all wiring and all lighting system

\$ 100.00 } NNX
 \$ 150.00 }

Apply rust coating chemical on affected panels

\$ 150.00

Remove and replace bootlid inner mechanism to new bootlid

\$ 80.00 + 120.00 ✓

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 + 100.00 ✓

Remove and replace rear bumper inner trims and boards to assist repair

\$ 220.00 NNX

Remove and reinstall rear windscreen glass to assist repair

\$ 120.00 + 220.00 ✓

Remove and reinstall fuel tank, pipes and sensors to assist repair

\$ 180.00 NNX

Remove and reinstall roof lining, seats and carpet to assist repair

\$ 400.00 NNX

Remove and replace exhaust silencer and gasket to assist repair

\$ 120.00 NNX

2060.00

Grand Total: \$ 15,019.56

Parts 4752.63
 SN 430.00
 Labour 2060.00
 7,242.63
 @ 20% 1,448.53
 5,794.10

LS 5,800/2

TCrim Min
 8/1/2022

Survey 7/1/2022
 1350hrs
 TCrim Min
 Resurvey 7/1/2022
 1140hrs
 TCrim Min

Lump sum repair
 Repair days 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____