

M/S : CHANG HOW YEW
BLK 601 CHOA CHU KANG ST62 #02-17
S680601
SINGAPORE
TEL: 96686519
ATTN:

Your Ref No: SLU8640Y
Claim Type:
Accident Date:

Estimate No: WQT1602306
Date: 04 Jan 2022
Policy No:
Veh Reg No: SLU8640Y
Make/Model: SEAT LEON ST 1.0
ECOTSI 115 STYLE 7AT
Chassis No: VSSZZZ5FZJR047542
Engine No: CHZ575847
Reg. Date: 15/12/2017
Payment Term: COD

Estimate Repair Cost to Vehicle No :SLU8640Y

Description	Quantity	List Price	Amount
		S\$	S\$
Others			
BUMPER REINF RR	1 PCS	700.00	700.00 DT
BUMPER BKT RR LH OTR	1 PCS	50.00	50.00 XSUC
BUMPER BKT RR RH OTR	1 PCS	50.00	50.00 XSUC
BUMPER BKT LH RR INN	1 PCS	70.00	70.00 Cut
BUMPER BKT RR RH INN	1 PCS	70.00	70.00 Cut
BUMPER SPONGE RR	1 PCS	80.00	80.00 Cut
BUMPER STRIP RR CTR	1 PCS	80.00	80.00 XSUC
BUMPER STRIP RR	1 PCS	70.00	70.00 Cut
BUMPER RR	1 PCS	1,600.00	1,600.00 DT
BUMPER TOW CAP	1 PCS	40.00	40.00 DIS
B/REFLECTOR LH	1 PCS	60.00	60.00 XSUC
B/REFLECTOR RH	1 PCS	60.00	60.00 XSUC
CLIP	2 PCS	6.00	12.00 nec
COVER-REVERSE CAMERA	1 PCS	110.00	110.00 XSUC
COVER-REVERSE CAMERA	1 PCS	150.00	150.00 XSUC
BUMPER SPOILER RR	1 PCS	570.00	570.00 Cut
LID RR	1 PCS	2,550.00	2,550.00 XT
RUBBER-LID RR*	1 PCS	300.00	300.00 XSUC
LETTERING 'LEON'	1 PCS	50.00	50.00 nec
T/LAMP LH OTR	1 PCS	410.00	410.00 XSUC
T/LAMP RH OTR	1 PCS	410.00	410.00 XSUC
T/LAMP LH INN	1 PCS	400.00	400.00 XSUC
T/LAMP RH INN	1 PCS	400.00	400.00 XSUC
NUMBER PLATE REAR	1 PC	80.00	80.00 DT
NO PLANT REAR			
NUMBER PLATE FRONT	1 PC	80.00	80.00 DT
BUMPER REINF FRT	1 PC	780.00	780.00 Cut
BUMPER BKT FRT LH	1 PCS	120.00	120.00 XSUC
BUMPER BKT FRT RH	1 PCS	120.00	120.00 XSUC
BUMPER FRT	1 PCS	1,650.00	1,650.00 XT Cut
BUMPER TOW CAP FRT	1 PCS	105.00	105.00 XSUC
BUMPER GRILLE FRT	1 PCS	200.00	200.00 XSUC Cut
F/LAMP GRILLE LH	1 PCS	130.00	130.00 XSUC
F/LAMP GRILLE RH	1 PCS	130.00	130.00 XSUC
BUMPER SPOILER FRT BIG	1 PCS	640.00	640.00 XSUC Cut
BUMPER SPOILER FRT SMALL	1 PCS	500.00	500.00 XSUC Cut
BONNET	1 PCS	1,700.00	1,700.00 XSUC

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
RCB NO:201535856D

M/S : CHANG HOW YEW

BLK 601 CHOA CHU KANG ST62 #02-17

S680601

SINGAPORE

TEL: 96686519

ATTN:

Your Ref No: SLU8640Y

Claim Type:

Accident Date:

Estimate No: WQT1602306

Date: 04 Jan 2022

Policy No:

Veh Reg No: SLU8640Y

**Make/Model: SEAT LEON ST 1.0
ECOTSI 115 STYLE 7AT**

Chassis No: VSSZZZ5FZJR047542

Engine No: CHZ575847

Reg. Date: 15/12/2017

Payment Term: COD

Estimate Repair Cost to Vehicle No :SLU8640Y

Description	Quantity	List Price	Amount
		SS	SS
F/LAMP LH	1 PC	360.00 X SVC	
F/LAMP RH	1 PC	360.00 X SVC	
H/LAMP LH	1 PC	1,450.00 ? / Crq	
H/LAMP RH	1 PC	1,450.00 X SVC / Crq	
DIRT DEFLECTOR FRT	1 PCS	125.00 X SVC	
RAD GRILLE FRT	1 PCS	580.00 X SVC - Cut	
RAD GRILLE COVER FRT	1 PCS	225.00 X SVC - Cut	
RAD GRILLE LOGO "S"	1 PCS	100.00 X SVC - Cut	
CLIP	7 PCS	7.00 X N/V	
RADIATOR COVER LOWER	1 PCS	50.00 X SVC	
ADD RADIATOR	1 PCS	460.00 X SVC	
RADIATOR	1 PCS	460.00 X SVC	
RAD AIR GUIDE LH	1 PCS	45.00 X SVC / Cut	
RAD AIR GUIDE RH	1 PCS	45.00 X SVC	
RAD BUSH	2 PCS	90.00 X SVC	
RADIATOR FAN	1 PC	820.00 X SVC	
AIR DUCT TOP-SUPPORT PANEL	1 PCS	100.00 X SVC	
AIR DUCT COVER-SUPPORT PANEL	1 PCS	55.00 X SVC	
AIR DUCT RR-SUPPORT PANEL	1 PCS	40.00 X SVC	
HOSE-AIR DUCT SMALL	1 PCS	65.00 X SVC	
A/C CONDENSER W DRYER	1 PC	500.00 X SVC	
SUPPORT PANEL	1 PC	620.00 X SVC	
H/LAMP BKT LH	1 PCS	60.00 ? - Cut	
H/LAMP BKT RH	1 PCS	60.00 X SVC - Cut	
S/PANEL BKT LH	1 PCS	230.00 ? - Cut	
S/PANEL BKT RH	1 PC	230.00 X SVC - Cut	
BONNET HINGE LH	1 PCS	100.00 X SVC	
BONNET HINGE RH	1 PCS	100.00 X SVC	
SEAL FILTER PIECE LH*	1 PCS	145.00 X SVC	
SEAL FILTER PIECE RH*	1 PCS	145.00 X SVC	
P/SENSOR RR LH & RH	2 PCS	640.00 X SVC	
P/SENSOR FRT OTR CTR	2 PCS	640.00 X SVC	
O-RING-P/SENSOR	4 PCS	20.00 / n/c	
BKT-P/SENSOR NO.1*	1 PC	90.00 / n/c	
BKT-P/SENSOR NO.2*	1 PC	90.00 / n/c	
BKT-P/SENSOR NO.3*	1 PC	90.00 / n/c	
BKT-P/SENSOR NO.4*	1 PC	90.00 / n/c	
LABOUR TO REMOVE,REINSTALL AND CHECK FRONT WIRENESS	1	180.00 /	

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
RCB NO:201535856D

M/S : CHANG HOW YEW
BLK 601 CHOA CHU KANG ST62 #02-17
S680601
SINGAPORE
TEL: 96686519
ATTN:

Your Ref No: SLU8640Y
Claim Type:
Accident Date:

Estimate No: WQT1602306
Date: 04 Jan 2022
Policy No:
Veh Reg No: SLU8640Y
Make/Model: SEAT LEON ST 1.0
ECOTSI 115 STYLE 7AT
Chassis No: VSSZZZ5FZJR047542
Engine No: CHZ575847
Reg. Date: 15/12/2017
Payment Term: COD

Estimate Repair Cost to Vehicle No :SLU8640Y

Description	Quantity	List Price	Amount
		S\$	S\$
LABOUR TO REPLACE,REPAIR FRT BUMPER,RR BUMPER,RR LID ,BONNET, SUPPORT PANEL, RR IRON PANEL	1	5,500.00	1950
LABOUR TO RESPRAY FRT BUMPER,RR BUMPER ,LID RR,BONNET,RR IRON PANEL	1	3,500.00	1800
LABOUR TO RENEW AND TRANSFER REAR PARKING AID	1	180.00	✓
LABOUR TO REFILL VACUUM AND REFILL A/C GAS	1	120.00	XNW
LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	180.00	✓
SUNDRIES	1	120.00	40
		35,038.00	35,038.00
Total			S\$ 35,038.00
Add GST @ 7%			2,452.66
Total Amount Payable			S\$ 37,490.66

TOTAL: SINGAPORE DOLLAR THIRTY SEVEN THOUSAND FOUR HUNDRED NINETY AND CENTS SIXTY SIX ONLY

Thuan@LHauto.com
82235769
6 days wp
7/1/22 1530
Plp. bfr paint photo

For VERTEX EURO MOTORS PTE LTD



AUTHORISED SIGNATURE

F: 16737-92

RD: 6

VERTEX EURO MOTORS PTE LTD

REGD OFFICE
1101 Road 4 Singapore 408608
TEL: (+65) 6743 9368 FAX: (+65) 6743 4388

TAX INVOICE NO:

WS1608990

Owner's Information		Service Advisor		Job Card No	
A/C: C0148		RAYMOND TING SING WEE		JH1608H47	
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD		Make/Model		Date of Invoice	
1 ANSON ROAD #15-00 SPRING HILL TOWER SINGAPORE 079909		SHATLERN ST LORCOTSI 115 STYLE 7A		10/3/2022	
Registration No	SLU8640Y	Mileage (km)	Next Mileage	Next Service Date	Date In
		15806			07/02/2022
					Time In
					10:42 AM
Chassis No	VSSZLLZ5PZJR047542	Engine No	Promised Date/Time		
		CHZ575847	7/2/2022 10:48:00 AM		

Service Description	Quantity	Unit Price	Amount
		S\$	S\$
RAD GRILL COVER FRT 0-0	1 PCS	225.00	225.00
RAD AIR GUIDE LH 0-0	1 PCS	45.00	45.00
H/LAMP BKT LH 1-20	1 PCS	60.00	60.00
H/LAMP BKT RH 1-20	1 PCS	60.00	60.00
S/PANEL BKT LH 1-100	1 PCS	230.00	230.00
S/PANEL BKT RH	1 PC	230.00	230.00
O-RING-P/SENSOR 10-3600	4 PCS	5.00	20.00
BKT-P/SENSOR NO.1	1 PC	90.00	90.00
BKT-P/SENSOR NO.2	1 PC	90.00	90.00
BKT-P/SENSOR NO.3	1 PC	90.00	90.00
BKT-P/SENSOR NO.4	1 PC	90.00	90.00
LABOUR TO REMOVE,REINSTALL AND CHECK FRONT WIRENESS	1	180.00	180.00
LABOUR TO REPLACE,REPAIR FRT BUMPER,RR BUMPER AND RR LID	1	1,950.00	1,950.00
LABOUR TO RESPRAY FRT BUMPER,RR BUMPER AND LID RR	1	1,800.00	1,800.00
LABOUR TO RENEW AND TRANSFER REAR PARKING AID	1	180.00	180.00
LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	180.00	180.00
SUNDRIES	1 PC	40.00	40.00
AIR FREIGHT CHARGES (Sup)	1 PC	411.92	411.92

VERTEX EURO MOTORS PTE LTD

RCB NO:201535856D
3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281

TAX INVOICE NO:

WS1608990

Owner's Information	Service Advisor			Job Card No
A/C: C0148 CHINA TAIPING INSURANCE (SINGAPORE) PTE.LTD. 3 ANSON ROAD #15-00 SPRINGLEAF TOWER SINGAPORE 079909	RAYMOND TING SING WEI			JB1608847
	Registration No.	Make/Model		Date of Invoice
	SLU8640Y	SEAT LEON ST 1.0 ECOTSI 115 STYLE 7A		10/3/2022
	Mileage (km)	Next Mileage	Next Service Date	Date In
	35806			07/02/2022
				Time In
				10:42 AM
	Chassis No.	Engine No.		Promised Date/Time
	VSSZZZ5FZJR047542	CHZ575847		7/2/2022 10:48:00 AM

Service Description	Quantity	Unit Price	Amount
		SS	SS
BUMPER REINF RR 1-60	1 PCS	700.00	700.00
BUMPER BKT LH RR INN 1-250	1 PCS	70.00	70.00
BUMPER BKT RR RH INN 1-250	1 PCS	70.00	70.00
BUMPER SPONGE RR 1-120	1 PCS	80.00	80.00
BUMPER STRIP RR 1-500	1 PCS	70.00	70.00
BUMPER RR 0-0	1 PCS	1,600.00	1,600.00
BUMPER TOW CAP 1-200	1 PCS	40.00	40.00
CLIP 10-800	2 PCS	3.00	6.00
BUMPER SPOILER RR 1-25	1 PCS	570.00	570.00
LETTERING 'LEON' 1-500	1 PCS	50.00	50.00
NUMBER PLATE REAR	1 PC	80.00	80.00
NUMBER PLATE FRONT	1 PC	80.00	80.00
BUMPER REINF FRT	1 PC	780.00	780.00
BUMPER FRT 1-1000	1 PCS	1,650.00	1,650.00
BUMPER GRILLE FRT 0-0	1 PCS	200.00	200.00
BUMPER SPOILER FRT BIG 0-0	1 PCS	640.00	640.00
BUMPER SPOILER FRT SMALL 1-150	1 PCS	500.00	500.00
H/LAMP LH	1 PC	1,450.00	1,450.00
H/LAMP RH	1 PC	1,450.00	1,450.00
RAD GRILLE FRT 0-0	1 PCS	580.00	580.00
RAD GRILLE LOGO "S" 0-0	1 PCS	100.00	100.00

VERTEX EURO MOTORS PTE LTD

RCB NO:201535856D
3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281

TAX INVOICE NO: WS1608990

TOTAL	SS 16,737.92
ADD GST @ 7%	1,171.65
GRAND TOTAL	<u>SS 17,909.57</u>

SINGAPORE DOLLAR SEVENTEEN THOUSAND NINE HUNDRED AND NINE AND CENTS FIFTY SEVEN ONLY

Remark: 1.) ACCIDENT REPAIR.(SNM21D207683/C02/GBL1558P/TANKW)



Customer's Signature/Co. Stamp

E. & O. E.

Service Advisor's Signature