

# VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608  
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281  
RCB NO:201535856D

M/S : CHANG HOW YEW

BLK 601 CHOA CHU KANG ST62 #02-17

S680601

SINGAPORE

TEL: 96686519

ATTN:

Your Ref No: SLU8640Y

Claim Type:

Accident Date:

Estimate No: WQT1602306

Date: 04 Jan 2022

Policy No:

Veh Reg No: SLU8640Y

Make/Model: SEAT LEON ST 1.0  
ECOTSI 115 STYLE 7AT

Chassis No: VSSZZZ5FZJR047542

Engine No: CHZ575847

Reg. Date: 15/12/2017

Payment Term: COD

## Estimate Repair Cost to Vehicle No :SLU8640Y

| Description              | Quantity | List Price | Amount     |
|--------------------------|----------|------------|------------|
|                          |          | <u>S\$</u> | <u>S\$</u> |
| <b>Others</b>            |          |            |            |
| BUMPER REINF RR          | 1 PCS    | 700.00     | ?          |
| BUMPER BKT RR LH OTR     | 1 PCS    | 50.00      | ?          |
| BUMPER BKT RR RH OTR     | 1 PCS    | 50.00      | ?          |
| BUMPER BKT LH RR INN     | 1 PCS    | 70.00      | ?          |
| BUMPER BKT RR RH INN     | 1 PCS    | 70.00      | ?          |
| BUMPER SPONGE RR         | 1 PCS    | 80.00      | ?          |
| BUMPER STRIP RR CTR      | 1 PCS    | 80.00      | ?          |
| BUMPER STRIP RR          | 1 PCS    | 70.00      | ?          |
| BUMPER RR                | 1 PCS    | 1,600.00   | DT         |
| BUMPER TOW CAP           | 1 PCS    | 40.00      | DES        |
| B/REFLECTOR LH           | 1 PCS    | 60.00      | X SVC      |
| B/REFLECTOR RH           | 1 PCS    | 60.00      | X SVC      |
| CLIP                     | 2 PCS    | 6.00       | NEC        |
| COVER-REVERSE CAMERA     | 1 PCS    | 110.00     | X SVC      |
| COVER-REVERSE CAMERA     | 1 PCS    | 150.00     | X SVC      |
| BUMPER SPOILER RR        | 1 PCS    | 570.00     | CUT        |
| LID RR                   | 1 PCS    | 2,550.00   | X R        |
| RUBBER-LID RR*           | 1 PCS    | 300.00     | X SVC      |
| LETTERING 'LEON'         | 1 PCS    | 50.00      | NEC        |
| T/LAMP LH OTR            | 1 PCS    | 410.00     | X SVC      |
| T/LAMP RH OTR            | 1 PCS    | 410.00     | X SVC      |
| T/LAMP LH INN            | 1 PCS    | 400.00     | X SVC      |
| T/LAMP RH INN            | 1 PCS    | 400.00     | X SVC      |
| NUMBER PLATE REAR        | 1 PC     | 80.00      | DT         |
| NO PLANT REAR            |          |            |            |
| NUMBER PLATE FRONT       | 1 PC     | 80.00      | DT         |
| BUMPER REINF FRT         | 1 PC     | 780.00     | ?          |
| BUMPER BKT FRT LH        | 1 PCS    | 120.00     | ?          |
| BUMPER BKT FRT RH        | 1 PCS    | 120.00     | ?          |
| BUMPER FRT               | 1 PCS    | 1,650.00   | X R        |
| BUMPER TOW CAP FRT       | 1 PCS    | 105.00     | X SVC      |
| BUMPER GRILLE FRT        | 1 PCS    | 200.00     | X SVC      |
| F/LAMP GRILLE LH         | 1 PCS    | 130.00     | X SVC      |
| F/LAMP GRILLE RH         | 1 PCS    | 130.00     | X SVC      |
| BUMPER SPOILER FRT BIG   | 1 PCS    | 640.00     | X SVC      |
| BUMPER SPOILER FRT SMALL | 1 PCS    | 500.00     | X SVC      |
| BONNET                   | 1 PCS    | 1,700.00   | X SVC      |

# VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608  
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281  
RCB NO:201535856D

M/S : CHANG HOW YEW  
BLK 601 CHOA CHU KANG ST62 #02-17  
S680601  
SINGAPORE  
TEL: 96686519  
ATTN:

Your Ref No: SLU8640Y  
Claim Type:  
Accident Date:

Estimate No: WQT1602306  
Date: 04 Jan 2022  
Policy No:  
Veh Reg No: SLU8640Y  
Make/Model: SEAT LEON ST 1.0  
ECOTSI 115 STYLE 7AT  
Chassis No: VSSZZZ5FZJR047542  
Engine No: CHZ575847  
Reg. Date: 15/12/2017  
Payment Term: COD

## Estimate Repair Cost to Vehicle No :SLU8640Y

| Description                                         | Quantity | List Price     | Amount |
|-----------------------------------------------------|----------|----------------|--------|
|                                                     |          | SS             | SS     |
| F/LAMP LH                                           | 1 PC     | 360.00 X SVC   |        |
| F/LAMP RH                                           | 1 PC     | 360.00 X SVC   |        |
| H/LAMP LH                                           | 1 PC     | 1,450.00 ?     |        |
| H/LAMP RH                                           | 1 PC     | 1,450.00 X SVC |        |
| DIRT DEFLECTOR FRT                                  | 1 PCS    | 125.00 X SVC   |        |
| RAD GRILLE FRT                                      | 1 PCS    | 580.00 X SVC   |        |
| RAD GRILLE COVER FRT                                | 1 PCS    | 225.00 X SVC   |        |
| RAD GRILLE LOGO "S"                                 | 1 PCS    | 100.00 X SVC   |        |
| CLIP                                                | 7 PCS    | 7.00 X NNN     |        |
| RADIATOR COVER LOWER                                | 1 PCS    | 50.00 X SVC    |        |
| ADD RADIATOR                                        | 1 PCS    | 460.00 X SVC   |        |
| RADIATOR                                            | 1 PCS    | 460.00 X SVC   |        |
| RAD AIR GUIDE LH                                    | 1 PCS    | 45.00 X SVC    |        |
| RAD AIR GUIDE RH                                    | 1 PCS    | 45.00 X SVC    |        |
| RAD BUSH                                            | 2 PCS    | 90.00 X SVC    |        |
| RADIATOR FAN                                        | 1 PC     | 820.00 X SVC   |        |
| AIR DUCT TOP-SUPPORT PANEL                          | 1 PCS    | 100.00 X SVC   |        |
| AIR DUCT COVER-SUPPORT PANEL                        | 1 PCS    | 55.00 X SVC    |        |
| AIR DUCT RR-SUPPORT PANEL                           | 1 PCS    | 40.00 X SVC    |        |
| HOSE-AIR DUCT SMALL                                 | 1 PCS    | 65.00 X SVC    |        |
| A/C CONDENSER W DRYER                               | 1 PC     | 500.00 X SVC   |        |
| SUPPORT PANEL                                       | 1 PC     | 620.00 X SVC   |        |
| H/LAMP BKT LH                                       | 1 PCS    | 60.00 ?        |        |
| H/LAMP BKT RH                                       | 1 PCS    | 60.00 X SVC    |        |
| S/PANEL BKT LH                                      | 1 PCS    | 230.00 ?       |        |
| S/PANEL BKT RH                                      | 1 PC     | 230.00 X SVC   |        |
| BONNET HINGE LH                                     | 1 PCS    | 100.00 X SVC   |        |
| BONNET HINGE RH                                     | 1 PCS    | 100.00 X SVC   |        |
| SEAL FILTER PIECE LH*                               | 1 PCS    | 145.00 X SVC   |        |
| SEAL FILTER PIECE RH*                               | 1 PCS    | 145.00 X SVC   |        |
| P/SENSOR RR LH & RH                                 | 2 PCS    | 640.00 X SVC   |        |
| P/SENSOR FRT OTR CTR                                | 2 PCS    | 640.00 X SVC   |        |
| O-RING-P/SENSOR                                     | 4 PCS    | 20.00 / n.c    |        |
| BKT-P/SENSOR NO.1*                                  | 1 PC     | 90.00 / n.c    |        |
| BKT-P/SENSOR NO.2*                                  | 1 PC     | 90.00 / n.c    |        |
| BKT-P/SENSOR NO.3*                                  | 1 PC     | 90.00 / n.c    |        |
| BKT-P/SENSOR NO.4*                                  | 1 PC     | 90.00 / n.c    |        |
| LABOUR TO REMOVE,REINSTALL AND CHECK FRONT WIRENESS | 1        | 180.00 /       |        |

# VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608  
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281  
RCB NO:201535856D

M/S : CHANG HOW YEW  
BLK 601 CHOA CHU KANG ST62 #02-17  
S680601  
SINGAPORE  
TEL: 96686519  
ATTN:

Your Ref No: SLU8640Y  
Claim Type:  
Accident Date:

Estimate No: WQT1602306  
Date: 04 Jan 2022  
Policy No:  
Veh Reg No: SLU8640Y  
Make/Model: SEAT LEON ST 1.0  
ECOTSI 115 STYLE 7AT  
Chassis No: VSSZZZ5FZJR047542  
Engine No: CHZ575847  
Reg. Date: 15/12/2017  
Payment Term: COD

## Estimate Repair Cost to Vehicle No :SLU8640Y

| Description                                                                                | Quantity | List Price | Amount        |
|--------------------------------------------------------------------------------------------|----------|------------|---------------|
|                                                                                            |          | S\$        | S\$           |
| LABOUR TO REPLACE,REPAIR FRT BUMPER,RR BUMPER,RR LID ,BONNET, SUPPORT PANEL, RR IRON PANEL | 1        | 5,500.00   | 1950          |
| LABOUR TO RESPRAY FRT BUMPER,RR BUMPER ,LID RR,BONNET,RR IRON PANEL                        | 1        | 3,500.00   | 1800          |
| LABOUR TO RENEW AND TRANSFER REAR PARKING AID                                              | 1        | 180.00     | ✓             |
| LABOUR TO REFILL VACUUM AND REFILL A/C GAS                                                 | 1        | 120.00     | XNW           |
| LABOUR TO CARRY OUT DIAGNOSTIC CHECK                                                       | 1        | 180.00     | ✓             |
| SUNDRIES                                                                                   | 1        | 120.00     | 40            |
|                                                                                            |          | 35,038.00  | 35,038.00     |
| Total                                                                                      |          |            | S\$ 35,038.00 |
| Add GST @ 7%                                                                               |          |            | 2,452.66      |
| Total Amount Payable                                                                       |          |            | S\$ 37,490.66 |

TOTAL: SINGAPORE DOLLAR THIRTY SEVEN THOUSAND FOUR HUNDRED NINETY AND CENTS SIXTY SIX ONLY

Thuan@Lkhauto.com  
82235769  
6 days wp  
7/1/22 1530  
Plp bfr paint photo

For VERTEX EURO MOTORS PTE LTD



AUTHORISED SIGNATURE