



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

2-8489

QUOTATION

L-3240

QUOTATION FOR

NAME: LONPAC INSURANCE BHD
COMPANY NAME: LONPAC INSURANCE BHD
STREET ADDRESS: 300 Beach Road, #17-04/07 The Concourse
POSTAL CODE: Singapore 199555
PHONE: 6250 7388

DATE: 6/1/2022

REF: SKH2996R
VEHICLE NO.: SKH2996R

MAKE: MAZDA

MODEL: 3

PREPARED BY: POON

Handwritten notes:
4585800 Not Authorized
Take photo after 10 days? HP. 90096608
LHR Mercedes
Tel: 62503581
7/1/22 Take photo after repair

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REFIX REAR DASHBOARD, INNER TRIM COVER AND CLEAN UP ALL BROKEN GLASSES	1		\$ 200.00	\$ 200.00	80	\$ 200.00
2	TO REMOVE & REFIX ELECTRICAL WIRING, TAIL LAMPS AND TEST FOR PROPER FUNCTIONING	1		\$ 120.00	\$ 120.00	30	\$ 120.00
3	TO REMOVE & REFIX REVERSE SENSORS	1		\$ 120.00	\$ 120.00	50	\$ 120.00
4	TO REMOVE & REFIX RR WINDSCREEN	1		\$ 200.00	\$ 200.00	120	\$ 200.00
5	TO REMOVE & REFIX EXHAUST PIPE TO ASSIST FOR REPAIR	1		\$ 1,200.00	\$ 1,200.00	11X	\$ 1,200.00
6	TO DO ELECTRICAL 4 WHEEL ALIGNMENT	1		\$ 120.00	\$ 120.00	11X	\$ 120.00
7	TO REMOVE & REFIX FUEL TANK TO ASSIST FOR REPAIR	1		\$ 280.00	\$ 280.00	60	\$ 280.00
8	TO REMOVE & REFIX REAR LH & RH SUSPENSION TO ASSIST FOR REPAIR	1		\$ 400.00	\$ 400.00	11X	\$ 400.00
9	TO PROVIDE SKILL LABOUR TO REMOVE ALL REAR DAMAGED PANELS, PANEL BEAT, CUT AND WELD IN PLACE NEW PARTS AND PANELS WITH FULL REALIGNMENT	1		\$ 2,000.00	\$ 2,000.00	1600	\$ 2,000.00
10	TO PROVIDE SKILL LABOUR AND MATERIAL TO PREPARE AND PAINT ALL NEW PARTS AND PANELS	1		\$ 2,000.00	\$ 2,000.00	1300	\$ 2,000.00
PARTS							
1	REAR NO PLATE WITH CASING	1		\$ 45.00	\$ 45.00	Self	\$ 45.00
2	REAR BUMPER	1	1096	\$ 1,444.00	\$ 1,444.00	Dis	\$ 1,444.00
3	REAR BUMPER CLIPS	10		\$ 5.00	\$ 50.00	net	\$ 50.00
4	REAR BUMPER SIDE RETAINER LH & RH	2		\$ 39.00	\$ 78.00	Self	\$ 78.00
5	REAR BUMPER SIDE BRACKET LH & RH	2		\$ 14.00	\$ 28.00	Self	\$ 28.00
6	REAR BUMPER REFLECTOR LH & RH	2		\$ 63.00	\$ 126.00	Self	\$ 126.00
7	REAR BUMPER REINFORCEMENT	1	507	\$ 557.00	\$ 557.00	Self	\$ 557.00
8	REAR BUMPER REVERSE SENSOR 1 SET	1		\$ 400.00	\$ 400.00	Should	\$ 400.00
9	REAR NO PLATE LAMP LH & RH	1		\$ 164.00	\$ 164.00	Self	\$ 164.00
10	REAR TRUNK	1	1067	\$ 1,220.00	\$ 1,220.00	DD	\$ 1,220.00
11	REAR TRUNK HINGES LH & RH	2		\$ 129.00	\$ 258.00	Self	\$ 258.00
12	REAR TRUNK REFLECTOR LH & RH	2		\$ 494.00	\$ 988.00	CRG	\$ 988.00
13	REAR TRUNK THIRD BRAKE LAMP	1	350	\$ 515.00	\$ 515.00	CRG	\$ 515.00

Handwritten notes on right margin:
s/n 40
—
—
—
X
—
—
200 s/n
X
—
—
—

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
14	REAR TRUNK MAZDA 3 LOGO	1		\$ 39.00	\$ 39.00	nee	\$ 39.00
15	REAR TRUNK MAZDA LOGO	1		\$ 75.00	\$ 75.00	nee	\$ 75.00
16	REAR TRUNK DAMPER LH & RH	2		\$ 82.00	\$ 164.00	nr	\$ 164.00
17	REAR TRUNK INNER TRIM COVER	1		\$ 160.00	\$ 160.00	see	\$ 160.00
18	REAR TRUNK INNER TRIM COVER CLIPS	10		\$ 5.00	\$ 50.00	nr	\$ 50.00
19	REAR TRUNK INNER LOCK	1		\$ 177.00	\$ 177.00	see/see	\$ 177.00
20	REAR TRUNK INNER LOCK HATCH	1		\$ 35.00	\$ 35.00	nr	\$ 35.00
21	REAR TRUNK INNER RUBBER	1		\$ 98.00	\$ 98.00	nm	\$ 98.00
22	TAIL LAMP LH & RH	2		\$ 494.00	\$ 988.00	one	\$ 988.00
23	REAR FENDER LH & RH	2	o/s r	\$ 1,129.00	\$ 2,258.00	mls see	\$ 2,258.00
24	REAR FENDER INNER TRIM COVER	1		\$ 204.00	\$ 204.00	see	\$ 204.00
25	REAR FENDER INNER TRIM COVER CLIPS	10		\$ 5.00	\$ 50.00	nr	\$ 50.00
26	REAR END PANEL	1		\$ 422.00	\$ 422.00	see/see	\$ 422.00
27	REAR END PANEL TOP GARNISH	1		\$ 204.00	\$ 204.00	see	\$ 204.00
28	REAR END PANEL TOP GARNISH CLIPS	10		\$ 5.00	\$ 50.00	nr	\$ 50.00
29	SPARE TRYE HOUSING PANEL	1		\$ 1,070.00	\$ 1,070.00	r	\$ 1,070.00
30	SPARE TRYE HOUSING BOARD	1		\$ 513.00	\$ 513.00	see	\$ 513.00
31	REAR WINDSCREEN	1		\$ 945.00	\$ 945.00	shattered	\$ 945.00
32	SEALANT	1		\$ 45.00	\$ 45.00	nee	\$ 45.00
33	REAR DASHBOARD	1		\$ 437.00	\$ 437.00	see	\$ 437.00
34	REAR FENDER INNER SHIELD LH & RH	2		\$ 62.00	\$ 124.00	see	\$ 124.00
35	REAR FENDER INNER SHIELD CLIPS	12		\$ 5.00	\$ 60.00	nr	\$ 60.00
36	REAR EXHAUST PIPE	1		\$ 1,077.00	\$ 1,077.00	nr	\$ 1,077.00
37	REAR EXHAUST PIPE END COVER	1		\$ 55.00	\$ 55.00	nr	\$ 55.00
38	REAR FENDER INNER PANEL LH & RH	2		\$ 978.00	\$ 1,956.00	r	\$ 1,956.00

SUBTOTAL	\$ 23,769.00	SUBTOTAL	\$ 23,769.00
GST 7%	\$ 1,663.83	GST 7%	1663.83
TOTAL	\$ 25,432.83	TOTAL	\$ 25,432.83

REMARKS:

(20%)

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

(CUSTOMER'S SIGNATURE AND COMPANY STAMP) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(AUTHORISED SIGNATURE)