

Date: 05/01/2022
Vehicle No: SMA2144X
Model: TOYOTA CHR HYBRID 1.8S CVT
Chassis: ZYX102118974-2018
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: GY2657C
Date of Accident: 04/01/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET LOCK	1		R \$105.00
2	FRONT BUMPER REINFORCEMENT	1		R \$296.00
3	FRONT BUMPER ABSORBER FOAM	1		in \$80.00
	Reda Bumper 1295			Short 1335.00
SUB TOTAL				\$481.00
LESS 25%				-\$120.25
PARTS TOTAL				\$360.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET (CARBON FIBER) 1200	1		CM \$1,300.00
2	FRONT BUMPER	1		CM \$1,000.00
S/N TOTAL				\$2,300.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.

\$400.00 2501

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER & ETC.

\$300.00 2201

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 151

LABOUR TOTAL \$780.00

TING AN

TOTAL \$3,440.75

Not Withheld
11 Pys @ 2900k

Painting After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action (claim) is allowed
- Supplemental survey is allowed

Head office

6 Kung Chang Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 093

81k 10 Ang Mo Kio Ind. Park 630047
Tel: (+65) 651 6671 | Fax: (+65) 651 6671

