

ASS REC. BY: TGLim

REF:

CC4/FC/22000212/Bea 3

Asher

ASSIGNMENT

From: _____ Date: 7/1/2022

Estimated Cost: _____

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNC 351C

at Workshop m/s Dean Autopro

of 160 Sin Ming Dr # 01-14

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 112,000/2

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS NP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNC 351E Yr Regn: 27A/2021

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Sienta Hybrid 15x.c.c 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 27227 T/Radio: Insured / Std / NI / NA

Eng/No: 1N8R801327

C/No: NHP1707178535

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: S/Rim / STD A/Rim or

Tyre Size: F: 185/60/15

R: 185/60/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 5/1/2022 D.O.I. 7/1/2022

Survey held at Dean Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: 7,000/2 - 8,000/2
	Recommended CER: \$7,470.00 on Part by Part basis TGLim
	MV 112,000/2
	PV 48,992/2
	NV 63,008/2
	TGLim 31/1/2022

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Equip Serial / I.S.I. () _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation: _____

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com /teamautopl@gmail.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ **After-Paint:** _____
 Contacts : _____

Vehicle Nos : **SNC 351 E**
 Model : Toyota Sienta
 Year : 2021
 Chassis No : NHP1707178535

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,431.90	\$ 1076.00 1,431.90
2	Tailgate logo	1	\$ 84.60	\$ 60.00 84.60
3	Tailgate emblem " HYBRID "	1	\$ 98.00	\$ 65.00 98.00
4	Tailgate outer garnish	1	\$ 375.75	\$ 364.00 375.75
5	Tailgate inner lock	1	\$ 371.40	\$ 321.00 371.40
6	Tailgate lock stricker	1	\$ 121.10	\$ 121.10 121.10
7	Tailgate antenna sensor	1	\$ 198.20	\$ 153.20 198.20
8	Tailgate weatherstrip	1	\$ 381.90	\$ 316.00 381.90
9	Tailgate inner trim board	1	\$ 387.00	\$ 387.00 387.00
10	Tailgate inner handle	1	\$ 141.00	\$ 141.00 141.00
11	Tailgate lamp	2	\$ 503.60	\$ 1007.20 ✓ 1,007.20
12	Tailgate windscreen moulding	1	\$ 241.00	\$ 197.10 241.00
13	Rear bumper	1	\$ 691.10	\$ 691.10 ✓ 691.10
14	Rear bumper side retainer	2	\$ 65.00 87.60	\$ 130.00 175.20
15	Rear bumper protector centre	1	\$ 384.60	\$ 209.00 384.60
16	Rear bumper protector side	2	\$ 159 234.50	\$ 318.00 469.00
17	Rear bumper reflector	2	\$ 83.00 145.00	\$ 166.00 290.00
18	Rear end panel	1	\$ 788.20	\$ 788.20 788.20
19	Rear end panel top garnish	1	\$ 374.25	\$ 374.25 374.25
20	Spare tyre panel	1	\$ 975.65	\$ 975.65 975.65
21	Spare tyre panel top board	1	\$ 591.68	\$ 591.68 591.68
22	Spare tyre panel insulator	1	\$ 581.40	\$ 581.40 581.40
23	Rear fender inner trim board	2	\$ 688.74	\$ 1,377.48 1,377.48
24	Taillamp <i>RH BR & CUTLH</i>	2	\$ 779.80	\$ 1,559.60 ✓ 1,559.60
25	Taillamp lower bracket	2	\$ 83.10 184.30	\$ 166.20 368.60

Parts Sub Total : \$ ~~6800.00~~ 13,465.81
 Discount : \$ ~~1700.00~~ 3,366.45
PARTS TOTAL : \$ ~~5100.00~~ 10,099.36

5,100.00

DDV
 } NECV ✓
 BRV
 JMV ✓
 NDX
 BRV
 TNV
 } NDX
 CUTV
 NECV
 BRV
 } NECV
 CUTV
 CUTV ✓
 BRV
 } DDXR
 NDX
 } NDX
 NDX
 BRV ✓
 NECV ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 40.00 100.00
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00 50.00
4	Tailgate inner trim board clips	1	\$ 50.00	\$ -50.00
5	Tailgate lamp clips	2	\$ 50.00	\$ -100.00
6	Tailgate lamp seal	2	\$ 30.00 60.00	\$ 60.00 120.00
7	Tailgate windscreen sealant	1	\$ 120.00	\$ 40.00 120.00
8	Tailgate windscreen inner seal	1	\$ 60.00	\$ 30.00 60.00
9	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ -80.00
10	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
11	Rear bumper protector centre clips	1	\$ 50.00	\$ -50.00
12	Rear bumper protector side clips	2	\$ 50.00	\$ -100.00
13	Rear end panel sealant	1	\$ 100.00	\$ -100.00
14	Rear end panel top garnish clips	1	\$ 50.00	\$ -50.00
15	Spare tyre panel sealant	1	\$ 100.00	\$ -100.00
16	Rear fender inner trim board clips	2	\$ 50.00	\$ -100.00
17	Taillamp seal	2	\$ 30.00 60.00	\$ 60.00 120.00
18	Taillamp clips	2	\$ 50.00	\$ -100.00
19	Reverse sensor	2	\$ 250.00	\$ 200.00 500.00
SPECIAL NETT TOTAL :				\$ 2,030.00

490.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 150.00
2	R&R tailgate windscreen	\$ 120.00 250.00
3	R&R reverse sensor	\$ 60.00 100.00
4	Check wiring	\$ 20.00 100.00
5	Upholstery	\$ -200.00
6	Panel beating	\$ 1800.00 1,800.00
7	Rust proofing	\$ -200.00
8	Spray painting	\$ 600.00 1,800.00
LABOUR TOTAL :		\$ 4,600.00

1880.00

PARTS TOTAL : \$ 10,099.36
SPECIAL NETT TOTAL : \$ 2,030.00
LABOUR TOTAL : \$ 4,600.00
GRAND TOTAL : \$ 16,729.36

Survey 7/1/2022
1607 hrs
Totum hr

Resurvey 11/1/2022
1215 hrs
Totum hr

Part by Part Survey
Repair days 9

Parts 5100.00
SN 490.00
Labour 1,880.00
7470.00

OR 7470/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: