

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMS42A Volkswagen GTI

			Estimated Parts Price	
No	Qty	Parts Description		
1	1	Rear bumper assy	1148 \$	1,271.20 <i>de ✓</i>
2	2	Rear bumper bracket	\$	86.40 <i>x un</i>
3	2	Rear bumper retainer	\$	89.60 <i>x un</i>
4	1	Rear bumper reinforcement	\$	378.90 <i>bt ✓</i>
5	1	Rear bumper inner beam	\$	189.70 <i>x un</i>
6	1	Rear tailgate assy	1232 \$	1,632.10 <i>bt ✓</i>
7	1	Rear tailgate centre logo	\$	128.50 <i>x un</i>
8	1	Rear tailgate lock mechanism	\$	191.30 <i>bt</i>
9	1	Rear tailgate lock catch	\$	86.40 <i>x un</i>
10	2	Rear tailgate damper	\$	367.70 <i>x un</i>
11	1	Rear tailgate weatherstrip	\$	188.10 <i>twi ✓</i>
12	1	Rear tailgate left taillamp	\$	445.20 <i>x</i>
13	1	Rear tailgate right taillamp	\$ <i>de ✓</i>	445.20 <i>x</i> } <i>un</i>
14	1	Rear tailgate inner board	\$	378.60 <i>x</i>
15	1	Rear left taillamp	\$	698.20 <i>x</i>
16	1	Rear right taillamp	\$	698.20 <i>x</i>
17	1	Rear end lower panel	\$	956.60 <i>Rx</i>
18	1	Rear end lower panel top garnish	\$	128.10 <i>de ✓</i>
19	1	Rear spare tyre top board	\$	298.60 <i>x</i> } <i>un.</i>
20	1	Rear floor panel	\$	1,245.30 <i>x</i>
21	1	Rear exhaust heat shield	\$	296.80 <i>x</i>
22	1	Rear windscreen glass moulding	189 <i>bent</i> \$	289.10 <i>rel ✓</i>
23	1	Rear exhaust muffler assy	\$ <i>Rx</i>	1,602.80 <i>SN 300 local repair</i>
24	2	Rear exhaust muffler rubber mounting	\$	83.60 <i>x un.</i>
			\$	12,176.20
			\$	1,217.62
Less 10%			\$	10,958.58

3834

3450.60

SN 300

3750.60

3455.40
 3109.86

SN 300

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMS42A Volkswagen GTI

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Rear bumper clips	\$	50.00 30 new ✓
2	6	Rear end lower panel top garnish clips	\$	30.00 10 new ✓
3	1	Rear bumper lower spoiler	\$	1,200.00 de ✓ 450
4	1	Rear bumper lower spoiler sealant	\$	100.00 40 new ✓
5	10	Rear bumper lower spoiler clips	\$	50.00 X un
6	1	Rear bumper right side spoiler	\$	450.00 X un
7	1	Rear bumper left side spoiler	\$	450.00 X un
8	1	Rear end lower panel sealant	\$	120.00 X un.
9	1	Rear floor panel sealant	\$	150.00 X un
10	1	Rear floor panel insulator pad	\$	180.00 X un
11	8	Rear tailgate inner board clips	\$	40.00 X un.
12	2	Rear bumper reverse sensor	\$	500.00 20 new ✓
13	1	Rear windscreen glass sealant	\$	100.00 40 new ✓
14	1	Rear no plate with garnish	\$	100.00 45 new ✓
			\$	3,520.00
Total parts			\$	14,478.58

815

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMS42A Volkswagen GTI

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,400.00 600
2	To putty and spray painting rear portion.	\$ 1,400.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 60
5	To remove and install rear exhaust muffler assy.	\$ 120.00 60
6	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00 60
7	To apply anti rust proofing to rear affected area.	\$ 140.00 30
8	To remove and install rear bumper reverse sensor.	\$ 80.00 30
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120
10	Towing service.	\$ 100.00 100
Total labour :		\$ 3,690.00 1690

Tanpin 97495749

WP' 10/11/22 @ 5400

1/5 Resurvey after repair
05 days

Tanpin @ lkkauto.com

Total parts : \$ 14,478.58

Total labour : \$ 3,690.00

Total repair cost : \$ 18,168.58

3750.60
300
815
1690
6255.60

4595000
05 days

~~3109.86~~

~~300~~

~~815~~

~~1690~~

~~5914.86~~

~~4595000~~

~~05 days~~

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: