

ESTIMATE TO REPAIR

VEHICLE NO. : SE 45 U
 MAKE : MERCEDES BENZ
 MODEL : A200 AMG LINE AUTO
 YEAR : 2018
 CHASSIS NO : WDD1770872N010925

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 06-Jan-22
 DATE OF ACCIDENT : 05-Jan-22
 THIRD PARTY REF : SFQ 2868 P
 THIRD PARTY REF : BUDGET DIRECT INSURANCE SINGAPO

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper	Nett		\$ 1,337.00	
2 pcs	rear bumper sensor	Nett	\$ 159.00	\$ 318.00	
2 pcs	rear bumper bracket	Nett	\$ 63.00	\$ 126.00	
1 pc	rear bumper reinforcement	Nett		\$ 407.00	
	less 10%				\$ 2,188.00
					\$ 218.80
					\$ 1,969.20
	To putty & spray paint.				\$ 300.00
	To check rear wiring & replace sensor.				\$ 180.00
	labour charges.				\$ 280.00
TG/VL	TOTAL				\$ 2,729.20

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd