

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00114732100
Accident Date : 05-Jan-2022

No. : 06513

Date : 06-Jan-2022

Our Ref : 022005 / CHAN

PAGE : 1

CHINA TAIPING INSURANCE (SINGAPORE) P/L
3 ANSON ROAD
#16-00
SPRINGLEAF TOWER
Singapore 079909

NOT Withheld
Resurvey B& paint
Ex @ 500p 4 days

ESTIMATED COST OF REPAIR FOR M/BENZ B200 SMX4572J

1 pc	Front bumper fascia	R	950.00	✓
1 pc	Front n/s bumper bracket	mi	8.00	✓
1 pc	Front bumper logo	m	55.00	✓
1 pc	Front bumper reinforcement	R	290.00	X
1 pc	Front bumper sponge	su	97.00	X
1 pc	Front bumper under cover		213.00	?
4 pcs	Front bumper under cover rivet @ S\$ 5.00		20.00	?
1 pc	Front n/s foglamp cover	mi	45.00	✓
1 pc	Frt n/s foglamp sensor holder	mi	12.00	✓
1 pc	Frt n/s foglamp cover sensor	mi	115.00	✓
1 pc	Frt n/s parking sensor	cm	115.00	✓
1 pc	Frt n/s parking sensor seal	m	6.00	✓
1 pc	Frt n/s bumper radar sensor		850.00	?
1 pc	N/s bumper radar sensor brack		125.00	?
1 pc	N/s headlamp	cm	1,500.00	✓
1 pc	N/s headlamp ECU		370.00	?
1 pc	Front n/s fender	B	490.00	✓
1 pc	Front n/s fender bracket	B	12.00	✓
1 pc	Front n/s fender inner support		60.00	?
1 pc	Frt n/s fender lower shield	C	32.00	?
1 pc	Frt n/s fender inner shield(F)	cm	170.00	✓
4 pcs	Frt n/s inner shield clip @ S\$ 4.50	m	18.00	✓

5,553.00

Add: 10% : 555.30

6,108.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00114732100

Page : 2

1 pc Front n/s sport rim

800.00 *sn*

To rewire damaged parts and refocus
headlamp beam,diagnos & programme

120.00 *801*

To check and adjust wheel alignment

80.00 *601*

To putty and spray replaced parts

600.00 *4401*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 *4501*

Total :

S\$ 8,408.30

Singapore Dollars Eight Thousand Four Hundred
and Eight and Cents Thirty Only