

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000225/DVY3M4**Date:** 19/07/2022**REFERENCE**

|                              |                                               |                             |                    |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMB1SNA00006262102 |
| <b>Claimant Vehicle No :</b> | SKW3649H                                      | <b>Insured Vehicle No :</b> | PC5549X            |
| Date of Loss:                | 06/01/2022                                    | Nature of Claim:            | TP                 |
|                              |                                               | Claim No:                   | SNM22D200171/C02   |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                     |             |                   |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKW3649H</b>                     | Engine No:  | CJE112310         |
| Make & Model:               | AUDI A4, 1.8 TFSI MU Attraction (A) | Chassis No: | WAUZZZ8K0FA174903 |
| Reg. Date:                  | 27/10/2015 (Man. Year: 2015)        | Odometer:   | 95918 km          |
| Colour:                     | White                               |             |                   |
| Engine Capacity:            | 1798 cc                             |             |                   |
| Market Value/New Car Price: | N/A                                 |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>   |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 245/40 R18       | Rear Tyre Size:  | 245/40 R18       |
| Front Left Side:  | Continental 5 mm | Rear Left Side:  | Continental 5 mm |
| Front Right Side: | Continental 5 mm | Rear Right Side: | Continental 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 40,271.54         | 5,277.03          | 34,994.51         | 86.90         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 6,020.00          | 1,470.00          | 4,550.00          | 75.58         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>46,291.54</b>  | <b>6,747.03</b>   | <b>39,544.51</b>  | <b>85.42</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>5,400.00</b>   |                   |               |
| <b>(\$\$)</b>                             | 46,291.54         | 5,400.00          | 40,891.54         | 88.33         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 3,240.41          | 378.00            | 2,862.41          | 88.33         |
| <b>Nett Amount (\$\$)</b>                 | <b>49,531.95</b>  | <b>5,778.00</b>   | <b>43,753.95</b>  | <b>88.33</b>  |

**INSPECTION**

|                             |                          |                                                                                                                |
|-----------------------------|--------------------------|----------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 07/01/2022               |                                                                                                                |
| Date Inspected:             | 07/01/2022 Inspected At: | JWG International Pte Ltd (HQ)<br>Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK<br>AutoPoint<br>Singapore 568047 |
| Estimated Period of Repair: | 3.0 days                 |                                                                                                                |

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                      |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 19 Jul 2022)                        |
| <b>Parts:</b>        | 143                                                                                                                                                                          | AUDI A4 1.8 TFSI MU Attraction (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKW3649H)                                                                                                                                    |                                                                      |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                      |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                      |

### Recommended Parts

| No. | Qty | Part No. Particulars               | Condition                      | Repairer's  | Amount       |
|-----|-----|------------------------------------|--------------------------------|-------------|--------------|
| 1   | 1   | *BOOTLID                           | Dented                         | 3,492.00 FL | *1,937.90 FL |
| 2   | 1   | *BOOTLID AUDI LOGO                 | Necessary                      | 194.00 FL   | *108.15 FL   |
| 3   | 1   | *BOOTLID WEATHER STRIP             | Not Necessary                  | 459.00 FL   | *- FL        |
| 4   | 2   | *BOOTLID LAMP L+R                  | Not Necessary                  | 2,588.00 FL | *- FL        |
| 5   | 1   | *BOOTLID LOCK                      | Not Necessary                  | 429.00 FL   | *- FL        |
| 6   | 1   | *BOOTLID SWITCH                    | Not Necessary                  | 394.00 FL   | *- FL        |
| 7   | 1   | *BOOTLID INNER TRIM                | Not Necessary                  | 784.00 FL   | *- FL        |
| 8   | 2   | *BOOTLID HINGE L+R                 | Not Necessary                  | 620.00 FL   | *- FL        |
| 9   | 1   | *REAR BUMPER                       | Distorted / Mounting Cracked   | 2,839.00 FL | *1,960.80 FL |
| 10  | 2   | *REAR BUMPER REFLECTOR L+R         | Not Necessary                  | 380.00 FL   | *- FL        |
| 11  | 1   | *REAR BUMPER LOWER LID             | Mounting Cracked               | 1,432.00 FL | *313.20 FL   |
| 12  | 2   | *REAR BUMPER SIDE RETAINER L+R     | Not Necessary                  | 478.00 FL   | *- FL        |
| 13  | 1   | *REAR BUMPER TOW HOOK COVER        | Not Necessary                  | 94.00 FL    | *- FL        |
| 14  | 1   | *REAR BUMPER CENTER BRACKET        | Cracked Mounting               | 784.00 FL   | *225.30 FL   |
| 15  | 2   | *REVERSE SENSOR<br>(4PC)           | 2Pc Damaged/ 2Pc Not Necessary | 1,396.00 FL | *390.24 FL   |
| 16  | 1   | *SET REVERSE SENSOR HOLDER         | Serviceable                    | 81.60 FL    | *- FL        |
| 17  | 1   | *REVERSE SENSOR WIREHARNES         | Not Necessary                  | 2,495.00 FL | *- FL        |
| 18  | 1   | *REAR BUMPER UNDER COVER           | Not Necessary                  | 495.00 FL   | *- FL        |
| 19  | 1   | *REAR BUMPER SPONGE                | Not fitted                     | 429.00 FL   | *- FL        |
| 20  | 1   | *REAR REINFORCEMENT BAR            | Not Necessary                  | 1,984.00 FL | *- FL        |
| 21  | 2   | *REAR REINFORCEMENT BAR HOLDER L+R | Not Necessary                  | 1,340.00 FL | *- FL        |
| 22  | 1   | *REAR END PANEL                    | Not Necessary                  | 2,499.00 FL | *- FL        |
| 23  | 1   | *REAR END PANEL TOP GARNISH        | Not Necessary                  | 567.00 FL   | *- FL        |
| 24  | 1   | *SPARE WHEEL PANEL                 | Not Necessary                  | 3,149.00 FL | *- FL        |
| 25  | 1   | *SPARE WHEEL PANEL TOP BOARD       | Not Necessary                  | 1,092.00 FL | *- FL        |
| 26  | 1   | *SPARE WHEEL PANEL TOOL BOX        | Not Necessary                  | 562.00 FL   | *- FL        |
| 27  | 2   | *REAR FENDER INNER TRIM L+R        | Not Necessary                  | 3,098.00 FL | *- FL        |
| 28  | 2   | *TAIL LAMP L+R                     | Not Necessary                  | 4,210.00 FL | *- FL        |
| 29  | 2   | *TAIL LAMP LOWER BRACKET L+R       | Not Necessary                  | 658.00 FL   | *- FL        |
| 30  | 1   | *REAR EXHAUST PIPE                 | Not Necessary                  | 2,789.00 FL | *- FL        |
| 31  | 1   | *REAR EXHAUST MOUNTING             | Not Necessary                  | 194.00 FL   | *- FL        |
| 32  | 1   | *REAR EXHAUST HEAT SHIELD          | Not Necessary                  | 285.00 FL   | *- FL        |
| 33  | 1   | *REAR NUMBER PLATE                 | Not Necessary                  | 100.00 FS   | *- FS        |
| 34  | 1   | *REAR END PANEL SEALANT            | Not Necessary                  | 80.00 FS    | *- FS        |
| 35  | 1   | *REAR FENDER SEALANT               | Not Necessary                  | 80.00 FS    | *- FS        |
| 36  | 1   | *REAR END PANEL TOP GARNISH CLIPS  | Not Necessary                  | 80.00 FS    | *- FS        |
| 37  | 1   | *REAR FENDER INNER TRIM CLIPS      | Not Necessary                  | 120.00 FS   | *- FS        |
| 38  | 1   | *TAIL LAMP CLIPS                   | Not Necessary                  | 50.00 FS    | *- FS        |
| 39  | 1   | *REAR BUMPER CLIPS                 | Necessary                      | 50.00 FS    | *20.00 FS    |
| 40  | 1   | *REAR BUMPER LOWER LID CLIPS       | Necessary                      | 50.00 FS    | *15.00 FS    |
| 41  | 1   | *BOOTLID SPOILER                   | Cracked                        | 1,600.00 FS | *800.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** **44,500.60** **5,770.59**  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** **4,229.06** **493.56**

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount             |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|--------------------|
| Total Parts (S\$)                             |     |          |             |           |            | 40,271.54 5,277.03 |
| Report was unsubmitted during this print-out. |     |          |             |           |            |                    |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                         | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                     |          |                 |                 |
| 1                              | TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS                                       | New      | 300.00          | 0.00            |
| 2                              | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS                                             | New      | 2,000.00        | 600.00          |
| 3                              | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS                                                      | New      | 2,000.00        | 600.00          |
| 4                              | TO TUFF COAT DAMAGED AREAS                                                                          | New      | 300.00          | 20.00           |
| 5                              | TO RNR REVERSE CAMERA                                                                               | New      | 100.00          | 0.00            |
| 6                              | TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD                                                          | New      | 250.00          | 0.00            |
| 7                              | TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD                                                      | New      | 200.00          | 60.00           |
| 8                              | TO RNR EXHAUST SYSTEM AND ATTACHMENTS PARTS                                                         | New      | 250.00          | 0.00            |
| 9                              | TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS                                                            | New      | 200.00          | 0.00            |
| 10                             | TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS | New      | 300.00          | 150.00          |
| 11                             | TO RNR REVERSE SENSOR TO ASSIST WORK LOAD                                                           | New      | 120.00          | 40.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                     |          | <b>6,020.00</b> | <b>1,470.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >