

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: RK.atv.INS.Y44.114896.21/SN Date: 08th Mar 2022

Our Ref: CS1/LAW22000228/Tqf3e2

## M/s Vision Law LLC

133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBE 2575U

INSURED VEHICLE: SKK 8679B ACCIDENT DATE: 24/01/2021

We thank you for your instruction on 07/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBE 2575U from M/s Prominent Appraiser Services Pte Ltd.
- b) Survey report by QuanTum Risk Management with colour photographs.
- c) Final Repair Bill of GBE 2575U from M/s Yi Heng Motor Workshop.
- d) Singapore Accident Statement of Vehicles GBE 2575U and SKK 8679B.
- e) Police Report of Vehicles SKK 8679B.
- f) Colour damaged vehicle photographs of GBE 2575U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBE 2575U

Make & Model : Toyota Hiace Van 3.0 Auto

Chassis Number : KDH2010176781

Year of Registration : 2015 Engine Capacity : 2982 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.