

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000231/DVF3N2**Date:** 20/01/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29146267AT2
Claimant Vehicle No :	GBL1778X	Insured Vehicle No :	SJE7333Z
Date of Loss:	17/12/2021	Nature of Claim:	TP
		Claim No:	639376

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL1778X		
Make & Model:	CITROEN BERLINGO, 1.5 D BLUEHDI EAT8 L2 (M)	Engine No:	10Q4DR0027572
Reg. Date:	30/03/2021 (Man. Year: 2020)	Chassis No:	VR7EFYHZRLJ959162
Colour:	White	Odometer:	22707 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,410.10	704.07	13,706.03	95.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	240.00	6,860.00	96.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,510.10	944.07	20,566.03	95.61
Approved Total (Overridden) (\$\$)		750.00		
(\$\$)	21,510.10	750.00	20,760.10	96.51
+ GST 7.00/7.00% (\$\$)	1,505.71	52.50	1,453.21	96.51
Nett Amount (\$\$)	23,015.81	802.50	22,213.31	96.51

INSPECTION

Date of Assignment:	07/01/2022	
Date Inspected:	11/01/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jan 2022)	
Parts:	N/A	CITROEN BERLINGO 1.5 D BLUEHDI EAT8 L2 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1778X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT TAILGATE	Not Necessary	1,460.90 FL	*- FL
2	1		*RIGHT TAILGATE DOOR WINDSCREEN MOULDING	Not Necessary	229.30 FL	*- FL
3	1		*RIGHT TAILGATE DOOR WEATHER STRIP	Not Necessary	196.40 FL	*- FL
4	1		*RIGHT TAILGATE CITROEN LOGO	Not Necessary	128.00 FL	*- FL
5	1		*RIGHT TAILGATE CITROEN EMBLEM	Not Necessary	149.00 FL	*- FL
6	1		*RIGHT TAILGATE C&C EMBLEM	Not Necessary	127.00 FL	*- FL
7	1		*LEFT TAILGATE	Not Necessary	1,681.90 FL	*- FL
8	1		*LEFT TAILGATE WINDSCREEN MOULDING	Not Necessary	253.20 FL	*- FL
9	1		*LEFT TAILGATE BERLINGO EMBLEM	Not Necessary	75.00 FL	*- FL
10	1		*LEFT TAILGATE WEATHER STRIP	Not Necessary	206.40 FL	*- FL
11	1		*LEFT TAILGATE LOCK	Not Necessary	305.50 FL	*- FL
12	2		*TAIL LAMP LH/RH	Not Necessary	873.00 FL	*- FL
13	1		*REAR BUMPER	Distorted/Deformed	1,481.90 FL	*782.30 FL
14	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	150.00 FL	*- FL
15	1		*REAR END PANEL INNER	Not Necessary	982.30 FL	*- FL
16	1		*REAR END PANEL OUTER	Not Necessary	1,098.40 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	285.00 FL	*- FL
18	1		*REAR EXHAUST PIPE	Not Necessary	1,350.00 FL	*- FL
19	1		*REAR EXHAUST MOUNTING	Not Necessary	95.00 FL	*- FL
20	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	210.00 FL	*- FL
21	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
22	1		*LEFT TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*LEFT TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
24	1		*LEFT TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
25	1		*RIGHT TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*RIGHT TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
27	1		*RIGHT TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
28	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*70KM STICKER	Not Necessary	50.00 FS	*- FS
32	1		*6PAX STICKER	Not Necessary	50.00 FS	*- FS
33	1		*SET REVERSE SENSOR	Serviceable	300.00 FS	*- FS
34	1		*REAR FLOOR PANEL	Not Necessary	1,950.90 FL	*- FL
35	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,599.90 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,899.00	782.30
- List Item Discount on L Items 10.00/10.00% (S\$)	1,488.90	78.23
Total Parts (S\$)	14,410.10	704.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	0.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	300.00	0.00
6	TO RNR REVERSE CAMERA	New	100.00	0.00
7	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	0.00
8	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
10	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			7,100.00	240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >