

ESTIMATE TO REPAIR

VEHICLE NO. : CB 7816 X
 MAKE : TOYOTA
 MODEL : HIACE COMMYTER GL 3.0 AUTO
 YEAR : 2016
 CHASSIS NO : KDH2230029054

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 07-Jan-22
 DATE OF ACCIDENT : 05-Jan-22
 THIRD PARTY REF : SLM 812 M
 THIRD PARTY REF : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				\$ 571.50
1 pc	front bumper reinforcement				\$ 399.50
10 pcs	front bumper clips		\$ 5.50		\$ 55.00
1 pc	front grille lower				\$ 226.40
	Less 25%				\$ 1,252.40
					\$ 939.30
	To putty & spray paint				\$ 450.00
	Labour charges				\$ 300.00
TG/VL	TOTAL				\$ 1,689.30
TG/VL	TOTAL				\$ -

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64689127 Email: sdmund@LTM.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd