

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM22000249/ues3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

: Preli. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

4/3/22 4/5 \$1900 informed MR Leo.

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

AXIA

Name : Alexender Anthony (87489422)

Accident Date : 31-Dec-21

Vehicle No : FBR1642Y

Vehicle Model : Yamaha Sniper
T150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy <i>SVC</i>	\$ 640.00 <i>x</i>
1	Fork under bracket <i>SVC</i>	\$ 185.00 <i>x</i>
1	Handle-bar <i>SVC</i>	\$ 105.00 <i>x</i>
1	Hand grip (1 set) <i>ny</i>	\$ 55.00 <i>x</i>
1	Handle bar ends <i>o/s cut</i>	\$ 30 78.00 <i>—</i>
2	Side mirrors <i>o/s cut</i>	\$ 55 110.00 <i>loc</i>
1	Front pilot light <i>one</i>	\$ 228.00 <i>—</i>
2	Front signals <i>o/s 320/m</i>	\$ 60 140.00 <i>loc</i>
1	Front signal lower garnish <i>m/s</i>	\$ 95.00 <i>—</i>
1	Front inner cover <i>one</i>	\$ 145 180.00 <i>—</i>
1	Fairing assy (1 set) <i>320</i>	\$ 520 625.00 <i>—</i>
1	Front footrest brackets <i>Bent</i>	\$ 65.00 <i>—</i>
2	Front footrest <i>o/s cut</i>	\$ 42 84.00 <i>1p2</i>
1	Brake pedal <i>Bent</i>	\$ 42.00 <i>—</i>
2	Rear footrest <i>ny</i>	\$ 80.00 <i>x</i>
1	Rear footrest bracket <i>o/s one</i>	\$ 112 156.00 <i>—</i>
1	Exhaust assy <i>Bent/7m</i>	\$ 528.00 <i>—</i>
1	Exhaust protector <i>good</i>	\$ 60.00 <i>—</i>
1	Exhaust protector end cap <i>D-1</i>	\$ 35 45.00 <i>—</i>
1	Rear fender - 1 <i>ny</i>	\$ 95.00 <i>x</i>
1	Rear fender - 2 <i>De</i>	\$ 68.00 <i>—</i>
2	Rear fender bracket <i>Bent</i>	\$ 53 106.00 <i>1p2</i>
1	Rear signal <i>o/s cut</i>	\$ 60 180.00 <i>loc</i>
1	Brake pump <i>su</i>	\$ 198.00 <i>x</i>
1	Rear number plate lamp <i>320</i>	\$ 68 98.00 <i>—</i>
1	Rear Rim <i>R</i>	\$ 350.00 <i>x</i>
1	Rear rim shaft <i>nn</i>	\$ 98.00 <i>x</i>
1	Swing arm <i>ny</i>	\$ 380.00 <i>x</i>
1	Swing arm bush <i>11</i>	\$ 180.00 <i>x</i>
1	Swing arm shaft <i>ny</i>	\$ 98.00 <i>x</i>
		\$ 5,352.00
	Less 10%	\$ 535.20
		\$ 4,816.80

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Alexender Anthony (87489422)

Accident Date : 31-Dec-21

Vehicle No : FBR1642Y

Vehicle Model : Yamaha Sniper
T150

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	3mf	\$	38.00	20
2	Fork oils	11	\$	30.00	X
2	Fork oil seals	11	\$	56.00	X
1	Steering cone (1 set)	11	\$	95.00	X
1	Helmet	12	\$	180.00	X
1	Sticket (1 set)	111	\$	68 95.00	✓
			\$	494.00	

S/No. Labour

1	To provide towing service (LOD)	\$	-	
2	To check wiring and reset headlamp focusing	\$	11 80.00	X
3	To realign body frame	\$	11 380.00	X
4	To provide labour	\$	480.00	300
		\$	940.00	

Grand Total

\$ 6,250.80

Singapore Dollars: Six Thousand Two Hundred Fifty and Cents: Eighty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-2266
102
p-2039.4
s.n-88
h-300
2427.4
1541