

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

AXA

Name : Alexender Anthony (87489422)

Accident Date : 31-Dec-21

Vehicle No : FBR1642Y

Vehicle Model : Yamaha Sniper
T150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy <i>SVC</i>	\$ 640.00 <i>X</i>
1	Fork under bracket <i>SVC</i>	\$ 185.00 <i>X</i>
1	Handle-bar <i>SVC</i>	\$ 105.00 <i>X</i>
1	Hand grip (1 set) <i>ny</i>	\$ 55.00 <i>X</i>
1	Handle bar ends <i>o/s cur</i>	\$ 78.00 <i>X</i>
2	Side mirrors <i>o/s cur</i>	\$ 110.00 <i>1pc</i>
1	Front pilot light <i>one</i>	\$ 228.00 <i>✓</i>
2	Front signals <i>o/s 500/m</i>	\$ 140.00 <i>1pc</i>
1	Front signal lower garnish <i>mis</i>	\$ 95.00 <i>✓</i>
1	Front inner cover <i>one</i>	\$ 180.00 <i>✓</i>
1	Fairing assy (1 set) <i>320</i>	\$ 625.00 <i>✓</i>
1	Front footrest brackets <i>320</i>	\$ 65.00 <i>✓</i>
2	Front footrest <i>o/s cur</i>	\$ 84.00 <i>1pc</i>
1	Brake pedal <i>320</i>	\$ 42.00 <i>✓</i>
2	Rear footrest <i>ny</i>	\$ 80.00 <i>X</i>
1	Rear footrest bracket <i>o/s cur</i>	\$ 156.00 <i>✓</i>
1	Exhaust assy <i>320/701</i>	\$ 528.00 <i>✓</i>
1	Exhaust protector <i>320/701</i>	\$ 60.00 <i>✓</i>
1	Exhaust protector end cap <i>320</i>	\$ 45.00 <i>✓</i>
1	Rear fender - 1 <i>ny</i>	\$ 95.00 <i>X</i>
1	Rear fender - 2 <i>De</i>	\$ 68.00 <i>✓</i>
2	Rear fender bracket <i>320</i>	\$ 106.00 <i>1pc</i>
1	Rear signal <i>o/s cur</i>	\$ 180.00 <i>1pc</i>
1	Brake pump	\$ 198.00 <i>?</i>
1	Rear number plate lamp <i>320</i>	\$ 98.00 <i>✓</i>
1	Rear Rim <i>7</i>	\$ 350.00
1	Rear rim shaft <i>7</i>	\$ 98.00
1	Swing arm <i>ny</i>	\$ 380.00 <i>α</i>
1	Swing arm bush <i>11</i>	\$ 180.00 <i>α</i>
1	Swing arm shaft <i>ny</i>	\$ 98.00 <i>X</i>
		\$ 5,352.00
	Less 10%	\$ 535.20
		\$ 4,816.80

Not Added
re
2/5
4/5
7/1/22

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Alexander Anthony (87489422)

Accident Date : 31-Dec-21

Vehicle No : FBR1642Y

Vehicle Model : Yamaha Sniper
T150

Estimated Repair Costs


<u>Special Nett Items</u>			
1	Number plate (1 set) <i>Buf</i>	\$	38.00 <i>20</i>
2	Fork oils <i>11</i>	\$	30.00 <i>X</i>
2	Fork oil seals <i>11</i>	\$	56.00 <i>X</i>
1	Steering cone (1 set) <i>11</i>	\$	95.00 <i>X</i>
1	Helmet <i>12</i>	\$	180.00 <i>X</i>
1	Sticket (1 set) <i>11</i>	\$	95.00 <i>✓</i>
		\$	494.00

S/No. Labour

1	To provide towing service (LOD)	\$	-
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	80.00 <i>X</i>
3	To realign body frame	\$ <i>11</i>	380.00 <i>X</i>
4	To provide labour	\$	480.00 <i>300</i>
		\$	940.00

Grand Total \$ 6,250.80

Singapore Dollars: Six Thousand Two Hundred Fifty and Cents: Eighty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: