

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0011/22
DATE : 04-JAN-2022

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : M/S ASIATIC GREEN HORTICULTURE AND LANDSCAPE
ADDRESS : 84 SUNGEI TENGAH ROAD

TELEPHONE NO : S(698986)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 7210048100
VEHICLE NO : GBL3195P
MODEL CODE : YDTARCBM20ED2Y597Z
MODEL/YEAR : NISSAN NV200 PETROL - AT MY2020
ENGINE NO : HR16179366D
CHASSIS NO : JN1YAAM20Z0001459
MILEAGE : 19030 KM
DATE IN : 04/01/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 01/01/2022

not Authorized
HUU
11/1/22
take photo before painting
11 days

- 9645 0084 e/mu@tanchoy.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBL3195P

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
		390 x 7	
1 ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR, LH INNER REAR FENDER PANEL, LH INNER RR FENDER EXTENSION PANEL	3675.00	2730
2 ZZ/002	LH INNER WHEELHOUSE, RENEW LH RR FENDER OUTER PANEL OUTER END PANEL, RR BUMPER AND TAIL GATE		
3 ZZ/003	CHARGES TO SPRAY PAINTING FOR THE ABOVE MENTIONED PANEL	1800.00	1250
4 ZZ/004	PERFORM RUSTPROOFING TRUNKFLOOR, OUTER END PANEL LH RR FENDER OUTER PANEL	360.00	240
5 ZZ/005	REMOVE AND INSTALL REAR WINDSCREEN GLASS	180.00	✓
6 ZZ/006	REMOVE AND TRANSFER TAIL GATE MECHANISM	80.00	✓
7 ZZ/007	RENEW REVERSE SENSOR	55.00	✓
8 ZZ/008	APPLY SEALANT TO OUTER END PANEL AND TAIL GATE	200.00	✓
9 ZZ/009	PERFORM WHEEL ALIGNMENT	95.00	✗
10 ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	✓
11 ZZ/10	RENEW LH RR COMB LAMP AND CHECK REAR WIRING SYSTEM	48.00	✓
	TOTAL LABOUR CHARGES	6613.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	LH RR COMB LAMP	26555-JX53A	one 252.00	✓	
2	SENSOR-REVERSE	SENSOR		should	250.00 ✓
3	EMBLEM-REAR VANETTE	90892-JX00A	new 64.90	✓	
4	EMBLEM-REAR NV200	90895-JX00A	new 94.40	✓	
5	EMBLEM-REAR NISSAN	90890-JX00A	new 64.90	✓	
6	REAR LICENCE PLATE	RLP		80	60.00 X
7	LABEL-PAX6	PAX		new	15.00 ✓
8	70KM/H STICKER	70KM/H		new	15.00 ✓
9	OUTER RR END PANEL	75617-JX00A	DD 115.20	✓	
10	LH SIDE BRACKET RR BUMPER	85229-JX00A	3rd 37.20	✓	
11	ENERGY ABSORBER RR BUMPER	85090-JX00A	94.00	?	
12	REAR BUMPER	85022-5LA0B	DIS 915.60	✓	
13	RH TAILGATE LOCK COVER	90595-JX00A	3.30	?	
14	RH TAILGATE LOCK COVER	90594-JX00A	3.30	?	
15	TAILGATE LOCK	90500-5LA0A	JM 287.10	✓	
16	STRIKER-TAIL GATE	90570-5LA0A	34.80	?	
17	REAR W/SCREEN SEALANT	SEALANT - 4		new	80.00 ✓
18	LH BACKDOOR STAY	90451-JX00A	200.00	?	
19	WEATHER STRIP TAILGATE	90830-5LA0A	88.40	?	
20	TAILGATE	K010M-JX0AB	3.6.70 1635.00	✓	
21	LH RAILGUIDE FINISHER	76827-JX00A	58.50	?	
22	LH RR FENDER RAIL GUIDE	77761-JX00A	new 167.30	X	
23	LH RR FENDER BACK PILLAR OUTER PANEL	77611-JX00A	423.00	?	
24	LH RR FENDER OUTER PANEL	78101-3LR0B	3rd 1439.70	✓	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
SUB TOTAL		5978.60	0.00	420.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1195.72	0.00	0.00
GRAND TOTAL		4782.88	0.00	420.00
OVERALL TOTAL		5202.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBL3195P

TOTAL LABOUR CHARGES	6613.00
TOTAL SPARE PARTS CHARGES	5202.88

GRAND TOTAL	11815.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.