



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ONG KIAN THENG DERICK			Ref: CC4/ASM22000251/Kga3q2 Date: 14/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 9359M	Veh. Inspected	SKP 940Y
	Policy No.	GA583591	Coverage (\$)	0.00
	Claim No.	S2M03QDD	Excess (\$)	0.00
	Assign From		Assign Date	07/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	ACR507008962	Colour	METALLIC SILVER
	Odometer	182820 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45 R18	MICHELIN	7 mm
	L/H Front Tyre	235/45 R18	MICHELIN	7 mm
	R/H Rear Tyre	235/45 R18	MICHELIN	7 mm
	L/H Rear Tyre	235/45 R18	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/01/2022	Inspection Date	07/01/2022
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	