

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKP940Y

Spare Parts

No.	Qty	List Items
1	1	Rear bumper
2	1	Rear bumper RH tow cover
3	2	Rear bumper reflector
4	2	Rear bumper side retainer
5	2	Rear bumper corner retainer
6	2	Rear bumper inner foam
7	1	Rear tailgate
8	1	Rear tailgate centre "TOYOTA" logo
9	1	Rear tailgate LH "ESTIMA" emblem
10	1	Rear tailgate RH "AERAS" emblem
11	1	Rear tailgate outer handle
12	2	Rear tailgate number plate lamp
13	1 set	Rear tailgate windscreen moulding
14	1	Rear tailgate centre reflector
15	2	Rear tailgate side reflector
16	1	Rear tailgate inner trim board
17	1 set	Rear tailgate inner trim board clips
18	1	Rear tailgate weatherstrip
19	2	Rear tailgate damper
20	1	Rear tailgate top lock
21	1	Rear tailgate lower lock catch
22	2	Taillamp
23	1	Rear end panel
24	1	Rear end panel top garnish
25	1	Rear end panel inner garnish
26	1	Rear end panel keyless sensor
27	1	Rear end panel buzzer
28	2	Rear fender inner side garnish
29	1 set	Rear fender inner side trim clips
30	1	Rear floor panel
31	1	Rear floor panel top board
32	1	Rear lower exhaust silencer
33	2	Rear lower exhaust silencer mounting

\$	B ₁	880.23	—
\$	CM	43.90	—
\$	Pen	115.20	X
ols \$	D ₁	78.80	✓
ols \$	o ₁	64.80	✓
\$		106.00	?
\$	B ₁	1,785.80	✓
\$	Ma	58.90	✓
\$	Ma	47.60	✓
\$	Ma	48.10	✓
\$	Wap	145.60	✓
\$	Ma	68.00	X
\$	Ma	148.90	✓
\$	Ma	291.60	X
\$	Ma	602.80	X
\$	Ma	631.40	✓
\$	Ma	50.00	✓
\$	Qul D ₁	392.10	508m
\$	Ma	420.00	X
\$	Ma	469.60	✓
\$	Ma	110.30	X
\$	Ma	794.20	X
\$	B ₁	669.40	✓
\$	Ma	272.60	✓
\$	Ma	198.40	✓
\$		256.40	?
\$		186.30	?
\$	Ma	1,356.80	✓
\$		60.00	✓
\$		809.00	?
\$	CM	1,167.70	✓
\$		971.10	?
\$	Pen	76.80	X
\$		13,378.33	

Less 25% \$ 3,344.58
Total : \$ 10,033.75

Special Nett Items

34	1 set	Rear windscreen sealant
35	1	Rear number plate
36	1 set	Rear end panel sealant
37	1 set	Reverse sensors

\$	Ma	80.00	405N
\$	CM	50.00	455N
\$	Ma	80.00	305N
\$	Ma	250.00	2005N

Not Authorized
11 Sep 8
Murray Alar Paim
9 days

38

1 set Reverse camera

\$ *in* 600.00 X
 Total : \$ 1,060.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,200.00	?
2	To putty and spray Spray Paintings charges.	\$	1,200.00	1000/-
3	To check wirings and lighthtings.	\$	50.00	20/-
4	To remove, refit reverses and reverse camera.	\$	150.00	60/-
5	To remove, refit rear windscreen glass.	\$	140.00	120/-
6	To remove, refit rear tailgate fittings.	\$	80.00	60/-
7	To remove, refit rear upholstery and attachments.	\$	120.00	100/-
8	To apply anti rust treatment	\$	100.00	?
Total :		\$	3,040.00	

Total Parts and Labour : \$ 14,133.75

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: