

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Apr 2020

LVV

DATE: 5-Jan-22

MODEL: Hyundai i40

INSURANCE CHINA TAIPING (LIS)

MVA LIMITS

VEHICLE NO: SH 7488M

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$1,052.20
	Front Bumper Clips	10	\$2.20	\$22.00
	Front Bumper Side Bracket LH	1		\$22.40
	Front Fender LH	1		\$663.00
	Front Fender Shield LH	1		\$174.90
	Front Fender Retainer LH	1		\$217.20
	Radiator Grille	1		\$1,388.00
	Radiator Grille H Emblem	1		\$129.50
	HeadLamp LH	1		\$1,388.00
	Front Wheel Cap LH	1		\$217.20
	SUB TOTAL			\$5,274.40
	LESS 20%			\$1,054.88
	DISCOUNTED TOTAL			\$4,219.52
	Front Wheel Tyre LH	1		\$216.00
	NETT TOTAL			\$216.00
	SPARE PARTS TOTAL			\$4,435.52
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Check Lightings			\$40.00
	Tuff Kote			\$60.00
	TOTAL LABOUR			\$1,500.00
	ESTIMATE TOTAL			\$5,935.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

thervan@lkhauto.com
82235169
5/1/22 1600
LIS ✓ after repair photo
in 3 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 05.01.2022 08:19

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4159016

JG NC805500430

OMER

IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)


JUNT CARD NO.

REG NO SH 7488M	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE TIME IN 04.01.2022 14:40
YR OF MANU 29.12.2016	TARGET DATE
CHASSIS CODE KMHLB41UMHU097343	COMPLETION DATE/TIME:

JOB DESCRIPTION

Incident Date: 04.01.2022
ATURE: 3P 04.01.2022/C

NO LABOR CODE DESCRIPTION
0010 PB PANEL BEATING-SH 7488M



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

SH 7488M LIMITS

Vehicle No.: SH 7488M

Service Advisor

Signature/Date

Name of Service Advisor

Date

med to Service Reception upon collection

To be kept by Security Guard