

Not Authorized
Recovery B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E

AAD2201-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

06 JAN 2022

SHD9299E

JTDKB3FU803079981

TOYOTA

PRIUS

03/01/2022

17/05/2019

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ R 1,300.70
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ S 193.50
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ S 390.60
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ R 110.60
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ R 97.50
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ R 13.30
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ R 43.50
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ R 26.30
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$ S 926.00
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ S 238.30
1 WEATHERSTRIP, FRONT DOOR, RH	\$ S 231.30
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ B 1,294.90
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ S 97.40 X
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ S 193.50 X
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ R 87.10 X
1 HINGE ASSY, REAR DOOR, UPPER LH	\$ R 98.90 X
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ R 21.90
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ R 34.90
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ R 15.40
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ 926.00 ?
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ 206.70 ?
1 WEATHERSTRIP, REAR DOOR, RH	\$ S 180.10 X
1 PANEL SUB-ASSY, QUARTER, RH	\$ B 871.50
1 LINER, REAR WHEEL HOUSE, RH	\$ S 139.80 X
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$ CM 594.80
1 REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$ R 343.40 X
TOTAL	\$ 6,728.40
25%	\$ 1,682.10

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E

AAD2201-

\$	5,046.30
----	----------

Special Nett

1 CLIP(FOR FRONT DOOR TRIM BOARD)	\$	nn	65.00	X
1 CLIP(FOR REAR DOOR TRIM BOARD)	\$	nn	65.00	X
1 REAR DOOR STICKER "6555-3333"	\$	nn	100.00	65.00
1 FRT DOOR STICKER 'TRANSCAB'	\$	nn	100.00	65.00
1 FENDER LINER CLIP	\$	nn	65.00	X
1 ROCKER PANEL CLIP	\$	nn	65.00	✓
TOTAL	\$		330.00	

TOTAL PARTS	\$	5,376.30
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	601
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	801
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	4,790.00	
Over All Total	\$	10,166.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

20 Days

6 days