



55 UBI ROAD I, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NOBA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/1090/2021/JT  
DATE : 5-Jan-22  
WIP : 61344

*Denise.*

*\$6802.72*

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS KOH GUEK HONG (XU YUEFANG)  
ADDRESS : 368 THOMSON ROAD  
#22-03  
SINGAPORE 298127  
TELEPHONE : HP +65 90189349  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 20701177540  
VEHICLE NO : SBG 383 J  
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC  
MODEL YEAR : 28/12/2020  
ENGINE NO : CZD C21286  
CHASSIS NO : WAUZZZF33M1050133  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 6-Dec-21  
PLACE OF ACCIDENT : 368 THOMSON ROAD CAR PARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBG 383 ]**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	X
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	X
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRRAG. ETC	S/N \$ 1,400.00	X
4	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$ 300.00	X
5	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	S/N \$ 400.00	X
<b>SUB TOTAL LABOUR CHARGES</b>		<b>: \$ 3,860.00</b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBC 383 ]**

**ESTIMATED LABOUR CHARGES FOR AL**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE TEST ON REAR 1/4 GLASS.	S/N \$ 200.00	X
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ <del>400.00</del>	280
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ <del>8,800.00</del>	1250
9	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCES, DRAIN CHANNEL AND REAR END PANELLING.	\$ <del>5,500.00</del>	1200
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>18,952.00</u></b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6541 1183  
 EMAIL: NOPA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBC 383

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR FENDER - LH <i>Repis</i>	1	\$ 3,388.00 +		
2	QUARTER WINDOW - LH <i>new</i>	1	\$ 614.00 +		
3	REAR END PANEL <i>new</i>	1	\$ 311.00 +		
4	PRIMER <i>xtol n</i>	1	\$ 20.00 +		
5	TAIL LIGHT - LH <i>at</i>	1	\$ 926.00 ✓	740.4	
6	TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 30.00 x		
7	REAR DOOR - LH <i>Dented</i>	1	\$ 2,909.00 ✓	2327.2	
8	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 135.00 ✓	108	
9	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 311.00 x		
10	REAR DOOR CATCH - LH <i>Damaged,</i>	1	\$ 120.00 ✓	? 96	
11	REAR DOOR HANDLE - LH <i>at</i>	1	\$ 198.00 ✓	158	
12	REAR DOOR HOUSING - LH <i>at</i>	1	\$ 27.00 ✓	21.6	
13	REAR DOOR UNDERLAY - FRONT / BACK - LH <i>new</i>	2	\$ 9.00 +		
14	REAR DOOR MOUNTING BAR <i>new</i>	1	\$ 162.00 x		
15	REAR DOOR BOWDEN CABLE <i>new</i>	1	\$ 52.00 +		
16	REAR DOOR COVER - LH <i>new</i>	1	\$ 257.00 ✓	205.2	
17	REAR WHEEL ARCH COVER - LH / RH <i>LH new</i>	2	\$ 536.00 ✓	268 214.4	
18	STONE CHIP	S/N	\$ 180.00 +		
19	ARYLIC SEALANT	S/N	\$ 180.00 +		
20	CAVITY WAX	S/N	\$ 140.00 +		
21	METAL FILLER POWDER	S/N	\$ 280.00 +		
22	1/4 GLASS SEALANT	S/N	\$ 100.00 +		
23	SUNDRIES <i>new</i>	S/N	\$ 400.00 ✓	? 9.92	
TOTAL SPARE PARTS		:	\$ 11,285.00		
TOTAL LABOUR CHARGES		:	\$ 18,952.00		
GRAND TOTAL		:	\$ 30,237.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Adnan L  
07/01/22

Not Authorised, 05 Days  
[Signature]

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT