

# ★ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiao Chan.

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 995 H

| S/N                  | NATURE OF JOBS                                                                                                                                                                                                                                                     | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                                                                                                                                      | S/N \$ 360.00 X       |                            |
| 2                    | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                                                                              | S/N \$ 350.00 250     |                            |
| 3                    | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURIES COOLING SYSTEM VACUUM AND REGAS                                                                                                         | S/N \$ 1,400.00 ?     |                            |
| 4                    | TO DISMANTLE AND RENEW FRONT BUMPER (RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT CHASSIS MEMBER COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | \$ 6,300.00 1000 1500 | (Fender Aluminium)         |
| 5                    | TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER AND RHS FRONT CHASSIS MEMBER COVER PLATE.                                                                                                                                                                | \$ 4,000.00 1600      |                            |
| 6                    | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.                                                                                                                                                                                                                            | S/N \$ 384.00 192     |                            |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                                    | : \$ 12,794.00        |                            |

Car in sk 12/1/22

mp 62210

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

kiam/

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 995 H

AIG - Adrian  
- 5 days.

|                       |                                                         |     | DAMAGED PARTS & PRICES |                |
|-----------------------|---------------------------------------------------------|-----|------------------------|----------------|
| S/N                   | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS        |
| 1                     | FRONT BUMPER <i>Distorted</i>                           | 1 S | 2,016.00               | ✓              |
| 2                     | FRONT BUMPER FIXING PARTS <i>new</i>                    | 1 S | 187.00                 | +              |
| 3                     | FRONT BUMPER GUIDE SECTION - RH ?                       | 1 S | 39.00                  | ?              |
| 4                     | FRONT BUMPER GRILLE - CENTER <i>new</i>                 | 1 S | 160.00                 | +              |
| 5                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>  | 1 S | 297.00                 | +              |
| 6                     | FRONT BUMPER CLOSING ELEMENT - RH <i>cracked</i>        | 1 S | 297.00                 | ✓ <i>fl.s.</i> |
| 7                     | RADIATOR GRILLE <i>cracked</i>                          | 1 S | 1,406.00               | ✓              |
| 8                     | RADIATOR CLOSING ELEMENT <i>cracked</i>                 | 1 S | 191.00                 | ✓ <i>fl.s.</i> |
| 9                     | FRONT BUMPER AIR GUIDE GRILE - RH ?                     | 1 S | 188.00                 | ?              |
| 10                    | FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>           | 1 S | 189.00                 | ✓              |
| 11                    | FRONT BUMPER REINFORCEMENT BEAM COVER ?                 | 1 S | 122.00                 | ?              |
| 12                    | FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>             | 1 S | 795.00                 | ✓              |
| 13                    | AIR COND STICKER <i>new</i>                             | 1 S | 8.00                   | ✓              |
| 14                    | "CAUTION" STICKER <i>new</i>                            | 1 S | 14.00                  | ✓              |
| 15                    | HORN - RH ?                                             | 1 S | 200.00                 | ?              |
| 16                    | FRONT FENDER - RH <i>new</i> <i>cracked (Aluminium)</i> | 1 S | 851.00                 | ✓ <i>fl.s.</i> |
| 17                    | POP RIVET <i>new</i>                                    | 8 S | 27.00                  | ✓ <i>fl.s.</i> |
| 18                    | FRONT FENDER ATTACHMENT PARTS <i>new</i>                | 1 S | 72.00                  | +              |
| 19                    | FRONT FENDER BRACKET - RH <i>Best</i>                   | 1 S | 48.00                  | ✓ <i>fl.s.</i> |
| 20                    | FRONT FENDER CLOSING ELEMENT - RH <i>new</i>            | 1 S | 62.00                  | ✓ <i>fl.s.</i> |
| SUB TOTAL SPARE PARTS |                                                         | :   | \$ 7,169.00            |                |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

Adrian Lj  
12/01/22  
Resurveyed *fl.s.*

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 995 H

|                       |                                            |     | DAMAGED PARTS & PRICES |         |            |
|-----------------------|--------------------------------------------|-----|------------------------|---------|------------|
| S/N                   | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS |            |
| 21                    | FRONT FENDER BRACE - RH <i>Best</i>        | 1   | \$ 96.00               | ✓       | <i>sls</i> |
| 22                    | FRONT FENDER BRACKET END - RH <i>green</i> | 1   | \$ 28.00               | +       |            |
| 23                    | FRONT WHEEL HOUSING LINER - RH             | 1   | \$ 169.00              | +       |            |
| 24                    | BONNET <i>Dent</i>                         | 1   | \$ 2,745.00            | ✓       |            |
| 25                    | BONNET ATTACHMENT PARTS <i>new</i>         | 1   | \$ 165.00              | +       |            |
| 26                    | BONNET HINGE - LH / RH <i>new</i>          | 2   | \$ 124.00              | +       |            |
| 27                    | BONNET EDGE PROTECTION - FRONT <i>new</i>  | 1   | \$ 28.00               | ✓       |            |
| 28                    | BONNET STRIKER - LH / RH <i>green</i>      | 2   | \$ 220.00              | +       |            |
| 29                    | BONNET MICROSWITCH - RH                    | 2   | \$ 427.00              | ✓       |            |
| 30                    | BONNET CATCH-HOOK                          | 1   | \$ 90.00               | +       |            |
| 31                    | BONNET BOWDEN CABLE - CENTER <i>new</i>    | 1   | \$ 58.00               | +       |            |
| 32                    | BONNET BOWDEN CABLE COVER                  | 1   | \$ 10.00               | +       |            |
| 33                    | BONNET CATCH HOOK - LOWER                  | 1   | \$ 63.00               | +       |            |
| 34                    | HEADLIGHT - RH <i>Control</i>              | 1   | \$ 5,455.00            | ✓       |            |
| 35                    | HEADLIGHT POWER MODULE - RH                | 1   | \$ 758.00              | ?       |            |
| 36                    | HEADLIGHT HEAT SINK - RH                   | 1   | \$ 733.00              | ?       |            |
| 37                    | HEADLIGHT CONTROL UNIT                     | 1   | \$ 557.00              | ?       |            |
| 38                    | HEADLIGHT HOSE - RH <i>torn</i>            | 1   | \$ 40.00               | ✓       | <i>sls</i> |
| 39                    | LIFT CYLINDER - RH                         | 1   | \$ 142.00              | ?       |            |
| 40                    | LIFT CYLINDER HOSE <i>new</i>              | 1   | \$ 68.00               | +       |            |
| SUB TOTAL SPARE PARTS |                                            | :   | \$ 11,976.00           |         |            |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 995 H

|                      |                                               |     |        |           | DAMAGED PARTS & PRICES |             |
|----------------------|-----------------------------------------------|-----|--------|-----------|------------------------|-------------|
| S/N                  | PARTS DESCRIPTION                             | QTY | S/NETT |           | REMARKS                |             |
| 41                   | LOCK CARRIER ?                                | 1   | \$     | 727.00    | ?                      |             |
| 42                   | A/C CONDENSER <i>neu</i>                      | 1   | \$     | 529.00    | +                      |             |
| 43                   | REFRIGERANT LINE <i>neu</i>                   | 1   | \$     | 619.00    | +                      |             |
| 44                   | REFRIGERANT LINE <i>neu</i>                   | 2   | \$     | 475.00    | +                      |             |
| 45                   | REFRIGERANT LINE BRACKET <i>neu</i>           | 1   | \$     | 27.00     | +                      |             |
| 46                   | REFRIGERANT LINE DUAL CLIP <i>neu</i>         | 1   | \$     | 30.00     | +                      |             |
| 47                   | OUTSIDE TEMPERATURE SENSOR BRACKET <i>neu</i> | 1   | \$     | 19.00     | ✓                      | <i>H.S.</i> |
| 48                   | ADDITIONAL RADIATOR <i>neu</i>                | 1   | \$     | 859.00    | +                      |             |
| 49                   | RADIATOR ?                                    | 1   | \$     | 951.00    | ?                      |             |
| 50                   | RADIATOR BRACKET - UPPER ?                    | 2   | \$     | 82.00     | ?                      |             |
| 51                   | RADIATOR BUSH LOWER - LH / RH ?               | 2   | \$     | 19.00     | ?                      |             |
| 52                   | RADIATOR FAN <i>neu</i>                       | 1   | \$     | 1,285.00  | +                      |             |
| 53                   | RADIATOR AIR GUIDE - RH ?                     | 1   | \$     | 25.00     | ?                      |             |
| 54                   | RADIATOR SEAL - RH OUTER ?                    | 1   | \$     | 8.00      | ?                      |             |
| 55                   | RADIATOR AIR GUIDE - UPPER CENTER ?           | 1   | \$     | 12.00     | ?                      |             |
| 56                   | RADIATOR COOLANT ?                            | 6   | \$     | 266.00    | ?                      |             |
| 57                   | AIR INTAKE GUIDE UPPER COVER ?                | 1   |        | TBC       | ?                      |             |
| 58                   | AIR INTAKE GUIDE UPPER ?                      | 1   |        | TBC       | ?                      |             |
| 59                   | AIR INTAKE GUIDE UPPER - LH ?                 | 1   |        | TBC       | ?                      |             |
| 60                   | RADIATOR AIR DUCT - TOP ?                     | 1   | \$     | 66.00     | ?                      |             |
| 61                   | FRONT CHASSIS MEMBER PLATE - LH ?             | 1   | \$     | 95.00     | ?                      |             |
| 62                   | FRONT NO PLATE <i>neu</i>                     | S/N | \$     | 60.00     | ✓                      |             |
| 63                   | SUNDRIES ?                                    |     | \$     | 400.00    | ?                      |             |
| TOTAL SPARE PARTS    |                                               | :   | \$     | 25,699.00 |                        |             |
| TOTAL LABOUR CHARGES |                                               | :   | \$     | 12,794.00 |                        |             |
| GRAND TOTAL          |                                               | :   | \$     | 38,493.00 |                        |             |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.