



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0007/2021/JT
DATE : 06-Jan-22
WIP : 62163

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,
4 days - ok - Jy - 11 Mar 22

OWNER'S NAME : MS CECILIA CHIA HYAU LIAN
ADDRESS : BLK 41 HOLLAND DRIVE
#04-25
SINGAPORE 270041
TELEPHONE : HP +65 96643833
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100379472-07
VEHICLE NO : SM 2222 U
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 17/07/2014
ENGINE NO : CXS 097471
CHASSIS NO : WAUZZZ8V9E1037984
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 03-Jan-22
PLACE OF ACCIDENT : ALONG TAN QUEEN LAN STREET

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SM 2222 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$	2,542.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SM 2222 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,233.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	
3	FRONT BUMPER TRIM COVER - RH	1	\$ 163.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 163.00	
5	FRONT BUMPER GUIDE SECTION - RH	1	\$ 39.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 109.00	
7	FRONT FENDER - RH	1	\$ 851.00	\$ 87.20
8	FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00	\$ 680.40
9	FRONT FENDER BRACKET	1	\$ 39.00	
10	FRONT FENDER BRACE	1	\$ 96.00	
11	POP RIVET	5	\$ 17.00	
12	HEADLIGHT - RH	1	\$ 2,641.00	\$ 2,112.80
13	LIFT CYLINDER - RH	1	\$ 193.00	
14	LIFT CYLINDER HOSE	1	\$ 182.00	
15	FRONT WHEEL HOUSING LINER - RH	1	\$ 169.00	
16	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 89.00	
17	SUNDRIES		\$ 300.00	\$ 18.00
TOTAL SPARE PARTS		:	\$ 7,543.00	\$ 2,898.40
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$ 2,542.00
GRAND TOTAL		:	\$ 12,545.00	\$ 5,440.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-23/02/22



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT