

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NOEAKHIA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0010/2021/JT
DATE : 6-Jan-22
WIP : 62270

Veron.
120 days. Cannot
\$25890.32.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/1/22

09 Days.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG HONG YEE, ALVIN
(HUANG HONGYI ALVIN)
ADDRESS : BLK 71 MARINE DRIVE
#08-230
SINGAPORE 440071
TELEPHONE : HP +65 91291022
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900149540-02
VEHICLE NO : SMN 7430 T
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 27/8/2019
ENGINE NO : CHZ C32155
CHASSIS NO : WAUZZZ8V2KA111631
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jan-22
PLACE OF ACCIDENT : AYE EXPRESSWAY

PREMIUM AUTOMOBILES



55 UBI ROAD, SINGAPORE 408699


TEL: 6346 2323 FAX: 6841 1183

EMAIL: NDRA.KHALI@PREMIUMAUTO.COM.SG / LATM5@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 7430 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	x ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	500 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM VACUUM AND REGAS	S/N \$ 1,400.00	✓ ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 5,600.00	2750 ✓
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER AND BOTH UPPER A-PILLAR.	\$ 5,500.00	2750 ✓
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 13,944.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHALID@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7430 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Replaced</i>	1	\$ 1,987.00	✓ 1589.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	✗
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 78.00	✗
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 160.00	✗ 128
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 536.00	✗
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 594.00	✗ ? X
7	FRONT BUMPER TRIM COVER - LH / RH <i>Not nec</i>	2	\$ 326.00	✗ X
8	FRONT BUMPER ADAPTER - LH / RH <i>Not nec</i>	2	\$ 76.00	✗ X
9	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓ 1124.80
10	RADIATOR CLOSING ELEMENT <i>cracked</i>	1	\$ 191.00	✗ 152.40
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Not nec</i>	2	\$ 376.00	✗ X
12	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 189.00	✓ 151.20
13	FRONT BUMPER REINFORCEMENT BEAM COVER <i>at</i>	1	\$ 122.00	✓ 97.20
14	FRONT BUMPER REINFORCEMENT BEAM <i>Pented.</i>	1	\$ 795.00	✓ 636
15	AIR COND STICKER <i>new</i>	1	\$ 8.00	✓ 5.68
16	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	✓ 10.88
17	HORN - LH / RH <i>Not nec</i>	2	\$ 400.00	✗ X
18	FRONT FENDER - LH / RH <i>LH Bredand</i>	2	\$ 1,702.00	851 680.40
19	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 72.00	✓
20	FRONT FENDER RIVET <i>Nec</i>	10	\$ 33.00	✓ 26.40
SUB TOTAL SPARE PARTS			\$ 9,252.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55, UST ROAD 1, SINGAPORE 408699

TEL: 6365 3423 FAX: 6361 1383

EMAIL: NORA.HUAN@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7430 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - LH / RH <i>} LH Bent</i>	2	\$ 78.00	30.72
22	FRONT FENDER BRACE - LH / RH	2	\$ 192.00	76.48
23	FRONT FENDER BRACKET END - LH / RH <i>new</i>	2	\$ 56.00	+
24	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 338.00	+
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 89.00	+
26	BONNET <i>Buckled</i>	1	\$ 3,134.00	2507.20
27	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 165.00	X
28	BONNET HINGE - LH / RH <i>Bent</i>	2	\$ 124.00	97.76
29	BONNET EDGE PROTECTION <i>new</i>	1	\$ 28.00	22
30	BONNET CATCH HOOK <i>Damaged</i>	1	\$ 90.00	71.28
31	BONNET CATCH HOOK LOWER <i>Damaged</i>	1	\$ 63.00	50.32
32	BONNET STRIKER - LH / RH <i>Not rec</i>	2	\$ 220.00	X
33	BONNET MICROSWITCH - LH / RH <i>} Damaged</i>	2	\$ 427.00	341.60
34	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	46
35	BONNET BOWDEN CABLE COVER <i>Not rec</i>	1	\$ 10.00	X
36	PLENUM CHAMBER COVER <i>cut</i>	1	\$ 179.00	143.20
37	BONNET ABSORBER <i>new</i>	1	\$ 104.00	+
38	HEADLIGHT - LH / RH <i>cracked</i>	2	\$ 10,910.00	8728
39	LIFT CYLINDER - LH / RH <i>} new</i>	2	\$ 284.00	+
40	LIFT CYLINDER HOSE <i>new</i>	1	\$ 68.00	+
SUB TOTAL SPARE PARTS		:	\$ 16,617.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6360 2323 FAX: 6941 3183

EMAIL: INFO@PREMIUMAUTOS.COM.SG CLAIMS@PREMIUMAUTOS.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7430 T

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LOCK CARRIER <i>Cracked</i>	1	\$ 727.00	✓ 581.60
42	A/C CONDENSER <i>Not Nec</i>	1	\$ 529.00	? X
43	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Not Nec</i>	1	\$ 19.00	? X
44	ADDITIONAL RADIATOR <i>Not Nec</i>	1	\$ 859.00	? X
45	RADIATOR <i>Not Nec</i>	1	\$ 951.00	? X
46	RADIATOR BRACKET <i>Not Nec</i>	2	\$ 82.00	? X
47	RADIATOR BUSH LOWER - LH / RH <i>Not Nec</i>	2	\$ 19.00	? X
48	RADIATOR COOLANT <i>Not Nec</i>	6	\$ 266.00	✓ 212.64
49	RADIATOR FAN <i>Not Nec</i>	1	\$ 1,265.00	? X
50	RADIATOR AIR GUIDE - LH / RH <i>Torn</i>	2	\$ 50.00	? 38.88
51	RADIATOR SEAL - RH OUTER <i>Not Nec</i>	1	\$ 8.00	? X
52	RADIATOR AIR GUIDE - UPPER CENTER <i>Torn</i>	1	\$ 12.00	? 9.44
53	WINDSCREEN WATER DEFLECTOR STRIP - LH / RH <i>Not Nec</i>	2	\$ 186.00	✓ 60
54	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 33.04
55	SUNDRIES <i>Nec</i>		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 31,252.00	
TOTAL LABOUR CHARGES		:	\$ 13,944.00	
GRAND TOTAL		:	\$ 45,196.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AN ESTIMATE OF REPAIR COSTS FOR THE AFFECTED VEHICLE. THIS IS NOT A MATERIAL LIST FOR REPAIRS TO BE MADE.

NAME : Adnan Lij
 SURVEYED DATE : 07/01/22
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : Not Authorised, 09 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK & Co Consultants hence notify the Insurer of the following:

- To survey before/after spray painting
- To survey damaged parts during resurvey
- All estimates are subject to confirmation
- The survey is on a "Without Prejudice" basis
- All modifications are allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company
- Acknowledged by Repairer

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

CST Reg No. 19-9902271-W

Veron.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0010/2021/JT
14-Jan-22
CHANG
1 of 1
SMN 7430 T
AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	WINDSCREEN NOZZLE - LH <i>Damaged</i>	\$ 117.00	✓ 93.60
GRAND TOTAL		\$ 117.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling.
17/01/22