



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1092/2021/JT
DATE : 6-Jan-22
WIP : 62256

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN CHENG HONG
ADDRESS : BLK 107 TECK WHYE LANE
#12-538
SINGAPORE 68107
TELEPHONE : HP +65 98159670
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800003668-03
VEHICLE NO : SGW 7667 B
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 12/1/2018
ENGINE NO : CVK 050751
CHASSIS NO : WAUZZZF51JA049480
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Dec-21
PLACE OF ACCIDENT : BUKIT PANJANG ROAD TOWARDS PIE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGW 7667 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@500 X 2 \$ 2,400.00 1000	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	@550 \$ 2,500.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,972.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 7667 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de /</i>	1	\$ 2,251.00	<i>1820.80</i>
2	FRONT BUMPER FIXING PARTS <i>? xnn</i>	1	\$ 407.00	
3	FRONT BUMPER SECURING STRIP <i>? xnn</i>	2	\$ 71.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>? xnn</i>	1	\$ 228.00	
5	FRONT BUMPER AIR GUIDE - RH <i>? xnn</i>	1	\$ 63.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>? xnn</i>	1	\$ 474.00	
7	FRONT FENDER - RH <i>bl /</i>	1	\$ 1,060.00	<i>848.00</i>
8	FRONT FENDER ATTACHMENT PARTS <i>? xnn</i>	1	\$ 53.00	
9	FRONT FENDER CLOSING ELEMENT - RH <i>ne /</i>	1	\$ 74.00	<i>59.04</i>
10	FRONT FENDER BRACKET - RH <i>ne /</i>	1	\$ 35.00	<i>27.92</i>
11	POP RIVET <i>ne /</i>	5	\$ 17.00	<i>13.20</i>
12	FRONT FENDER BRACE - RH <i>? xnn</i>	1	\$ 118.00	
13	FRONT FENDER BRACKET - RH CENTER <i>? xnn</i>	1	\$ 49.00	
14	FRONT FENDER TRIM - RH <i>? ne /</i>	1	\$ 164.00	<i>130.80</i>
15	FRONT FENDER FLEDGE COVER LONG - RH <i>ne /</i>	1	\$ 36.00	<i>28.24</i>
16	FRONT FENDER FLEDGE COVER SHORT - RH <i>ne /</i>	1	\$ 16.00	<i>12.24</i>
17	FRONT WHEEL HOUSING LINER - RH <i>? xnn</i>	1	\$ 275.00	
18	FRONT WHEEL SPOILER <i>? xnn</i>	1	\$ 73.00	
19	FRONT WHEEL SPOILER LOWER - RH <i>? xnn</i>	1	\$ 36.00	
20	HEADLIGHT - RH <i>sa /</i>	1	\$ 7,902.00	<i>6321.60</i>
SUB TOTAL SPARE PARTS		:	\$ 13,402.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 7667 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	LIFT CYLINDER - RH ? x n n	1	\$	198.00	
22	FRONT NO PLATE X x n n	S/N	\$	60.00	
23	SUNDRIES ? x n n		\$	300.00	
TOTAL SPARE PARTS		:	\$	13,960.00	
TOTAL LABOUR CHARGES		:	\$	5,972.00	
GRAND TOTAL		:	\$	19,932.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - Hp 90010068
: 07/01/22 @ 1545
: 5 days
: EXCESS: TBA
: Repair / Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT