

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1091/2021/JT
DATE : 5-Jan-22
WIP : 62019

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHAN TECK WEI
ADDRESS : 84 ST.PATRICK ROAD
#03-37
SINGAPORE 424183
TELEPHONE : HP +65 93688994
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800083915-03
VEHICLE NO : SMC 6973 H
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 17/7/2018
ENGINE NO : CHZ 959070
CHASSIS NO : WAUZZZ8VXJ1074343
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Dec-22
PLACE OF ACCIDENT : IMBIAH WALK CAR PARK

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 6973 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ / 360.00 360.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ / 350.00 350.00 250 /	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$ / 1,400.00 ? /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S \$ 4,200.00 4,200.00 750 2250 /	
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	S/N \$ / 2,000.00 2,000.00 1100 /	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S \$ / 192.00 /	
TOTAL LABOUR CHARGES		: \$ 8,502.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6973 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del</i>	1	\$ 1,987.00	1589.60
2	FRONT BUMPER FIXING PARTS <i>? xnn</i>	1	\$ 187.00	
3	FRONT BUMPER GUIDE SECTION - RH <i>? cm</i>	1	\$ 39.00	30.48
4	FRONT BUMPER GRILLE - CENTER <i>cm</i>	1	\$ 160.00	128.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>? cm</i>	1	\$ 536.00	428.80
6	FRONT BUMPER CLOSING ELEMENT - RH <i>? xnn</i>	1	\$ 297.00	
7	FRONT BUMPER TRIM COVER - RH <i>cm</i>	1	\$ 163.00	130.00
8	FRONT BUMPER ADAPTER - RH <i>? xnn</i>	1	\$ 38.00	
9	RADIATOR GRILLE <i>cm</i>	1	\$ 1,406.00	1124.80
10	FRONT CLOSING ELEMENT <i>? cm</i>	1	\$ 191.00	152.40
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>scu</i>	1	\$ 188.00	150.00
12	FRONT BUMPER FOAM FILLER PIECE <i>? cm</i>	1	\$ 189.00	151.20
13	FRONT BUMPER TOP COVER <i>? xnn</i>	1	\$ 122.00	
14	FRONT BUMPER REINFORCEMENT <i>? xnn</i>	1	\$ 795.00	
15	HORN - RH <i>? xnn</i>	1	\$ 200.00	
16	AIR COND STICKER <i>new</i>	1	\$ 8.00	5.68
17	CAUTION STICKER <i>new</i>	1	\$ 14.00	10.88
18	FRONT FENDER - RH <i>repair bt</i>	1	\$ 851.00	680.40
19	FRONT FENDER ATTACHMENT PARTS <i>xnn</i>	1	\$ 72.00	
20	FRONT FENDER BRACKET - RH <i>x nn</i>	1	\$ 39.00	
SUB TOTAL SPARE PARTS		:	\$	7,482.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6973 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE bt ✓	1	\$ 96.00	76.48
22	POP RIVET x nn	5	\$ 17.00	
23	FRONT WHEEL HOUSING LINER - RH ? ca ✓	1	\$ 169.00	134.80
24	HEADLIGHT - RH ca ✓	1	\$ 5,455.00	4 364.00
25	LIFT CYLINDER - RH ? x nn	1	\$ 142.00	
26	LIFT CYLINDER HOSE ? cut ✓	1	\$ 68.00	53.84
27	RADIATOR COOLANT LOCK CARRIER MOUNTING ? ca ✓	1	\$ 727.00	581.60
28	RADIATOR COOLANT ? ca ✓	6	\$ 185.00	147.36
29	RADIATOR AIR GUIDE - RH ? ca ✓	1	\$ 25.00	19.44
30	RADIATOR SEAL - RH OUTER ? x nn	1	\$ 8.00	
31	RADIATOR AIR GUIDE - UPPER CENTER ? x nn	1	\$ 12.00	
32	RADIATOR BRACKET ? x nn	1	\$ 19.00	
33	FRONT NO PLATE bt ✓	S/N	\$ 60.00	✓
34	SUNDRIES ? ca ✓		\$ 350.00	56.16
TOTAL SPARE PARTS		:	\$ 14,815.00	
TOTAL LABOUR CHARGES		:	\$ 8,502.00	
GRAND TOTAL		:	\$ 23,317.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Parcel - HP 90010068
07/01/22 @ 1430
4 days + 3 = 7 days
EXCESS: TBA
Revert / Reg before print

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

XE1328M

Make/Model

Motor Claims Department