

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0009/2021/JT

14-Jan-22

CHANG

1 of 1

SMN 3130 K

AUDI Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	ELBOW FITTING (washer bracket) - BR (2)	\$ 66.00	52.16
2	COUPLING ELEMENT - MC 1	\$ 13.00	10.16
GRAND TOTAL		\$ 79.00	

For Premium Automobiles Pte Ltd

Steve
17/1/22



Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	? + 250 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 1,700.00	? ✓ (photo)
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	5,600.00 @ 500 X 5	750 + 1500. 3 dy ✓
5	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER.	@ 550 X 3 \$ 3,500.00	1650 ✓
TOTAL LABOUR CHARGES (FRONTAL)		: \$ 11,960.00	

+ 7 days

3 (M)
3 (H)
1 (Exht)

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRNASFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	/
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AN REAR LID WIPER ASSY.	S/N \$	480.00	/
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	480.00	? ✓
4	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	/
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
SUB TOTAL LABOUR CHARGES (REAR)		:	\$ 2,120.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00 150
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@500x2 S 5,200.00 1000 + 1500 ✓ 3 dys
8	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND SPARE WHEEL HOUSING LINER.	@550x2 S 4,000.00 1100 + 550 ✓ ed M
9	TO RENEW LHS REAR EXHAUST SILENCER AND CENTER EXHAUST SILENCER. TO ALIGN BACK TO POSITION.	S/N \$ 480.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 3
TOTAL LABOUR CHARGES (FRONTAL + REAR)		: \$ 24,344.00

Car-in

12/1/22

wip: 62240

PREMIUM AUTOMOBILES

Kiam



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT

Azer-Rasu /
- 10 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,936.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 347.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 197.00	BR
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 338.00	
5	FRONT BUMPER END CAP - LH / RH	2	\$ 118.00	
6	FRONT BUMPER SPOILER	1	\$ 299.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 156.00	
8	FRONT WHEEL SPOILER - LH / RH	2	\$ 68.00	
9	FRONT BUMPER ADAPTER - LH / RH	2	\$ 78.00	
10	RADIATOR GRILLE	1	\$ 1,411.00	
11	RADIATOR STRIKER PLATE	1	\$ 124.00	BR
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 78.00	
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 723.00	DD
14	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	
15	FRONT BUMPER TOP COVER	1	\$ 100.00	BR
16	CAUTION STICKER	1	\$ 14.00	MC
17	AIR COND STICKER	1	\$ 8.00	MC
18	HORN - RH	1	\$ 180.00	
19	HORN SUPPORT - RH	1	\$ 31.00	
20	FRONT FENDER - RH	1	\$ 1,147.00	Repair
SUB TOTAL SPARE PARTS			\$ 7,425.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES			REMARKS
		QTY	S/NETT		
21	FRONT FENDER ATTACHMENT PARTS X	1	\$	40.00	
22	FRONT FENDER BRACKET - RH X	1	\$	48.00	
23	FRONT FENDER BRACKET END - RH X	1	\$	16.00	
24	FRONT FENDER BRACE - RH X	1	\$	44.00	
25	POP RIVET X	6	\$	20.00	
26	BONNET repair	1	\$	2,789.00	
27	BONNET ATTACHMENT PARTS X	1	\$	165.00	
28	BONNET HINGE - LH / RH X	2	\$	124.00	
29	BONNET IMPACT PROTECTION - CENTER / LH / RH X	3	\$	90.00	
30	BONNET STRIKER - RH X	1	\$	110.00	
31	BONNET MICROSWITCH X	1	\$	214.00	
32	BONNET RELEASE ELEMENT X	1	\$	58.00	
33	BONNET BOWDEN CABLE - CENTER X	1	\$	58.00	
34	BONNET BOWDEN CABLE CAP X	1	\$	10.00	
35	HEADLIGHT MOUNTING - LH / RH X - BR	2	\$	236.00	
36	HEADLIGHT - LH / RH X - CUT	2	\$	9,830.00	
37	LIFT CYLINDER - LH / RH ?	2	\$	284.00	
38	LIFT CYLINDER HOSE ?	1	\$	182.00	
39	FRONT WHEEL ARCH COVER - LH / RH ✓	2	\$	644.00	
40	RADIATOR COOLANT ? - BR lack carrier.	1	\$	994.00	
SUB TOTAL SPARE PARTS		:	\$	15,956.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST


LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	RADIATOR COOLANT ? - NR	6	\$	266.00	
42	RADIATOR AIR GUIDE - RH ? - BR	1	\$	31.00	
43	RADIATOR SEAL - RH OUTER ?	1	\$	7.00	
44	RADIATOR AIR GUIDE - UPPER CENTER ? - BR	1	\$	22.00	
SUB TOTAL SPARE PARTS		:	\$	326.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>de</i>	1	\$ 1,280.00	
2	REAR BUMPER FIXING PARTS ?	1	\$ 77.00	
3	REAR BUMPER SPOILER <i>de</i>	1	\$ 284.00	
4	REAR BUMPER TOWING EYE <i>?</i>	1	\$ 43.00	
5	REAR LIGHT REFLECTOR - LH / RH	2	\$ 60.00	
6	TAIL LIGHT - LH ?	1	\$ 1,321.00	
7	TAIL LIGHT TRIM - LH ?	1	\$ 30.00	
8	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 579.00	
9	REAR BUMPER HOLDING STRAP - LH / RH ?	2	\$ 26.00	
10	REAR BUMPER GUIDE SECTION - LH / RH ?	2	\$ 108.00	
11	REAR PARKING AID SENSOR - INNER / OUTER ?	2	TBC	
12	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 9.00	
13	REAR BUMPER WIRING SET ?	1	\$ 515.00	
14	REAR LID <i>lt</i>	1	\$ 2,359.00	
15	REAR LID ATTACHMENT PARTS ?	1	\$ 120.00	
16	REAR LID GASKET <i>X</i>	1	\$ 118.00	
17	REAR LID LOCK STRIKER <i>X</i>	1	\$ 291.00	
18	REAR LID LOCK <i>X</i>	1	\$ 241.00	
19	BONNET LOCK COVER ?	1	\$ 13.00	
20	REAR PACKING ADHESIVE <i>new</i>	1	\$ 19.00	
SUB TOTAL SPARE PARTS		:	\$ 7,493.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	AUDI EMBLEM <i>nee</i>	1	\$	138.00	
22	Q2 EMBLEM <i>nee</i>	1	\$	99.00	
23	REAR FOAM STRIPS ?	1	\$	133.00	
24	REAR SPOILER FIXING PARTS <i>nee</i>	1	\$	133.00	
25	BOOT LID BUNGS <i>nee</i>	4	\$	117.00	
26	REAR WINDSCREEN <i>nee</i> <i>photo</i>	1	\$	779.00	
27	PRIMER <i>nee</i>	1	\$	20.00	
28	REAR END PANEL ? <i>OD</i> ?	1	\$	245.00	
29	REAR END PANEL REINFORCEMENT	1	\$	733.00	
30	REAR END PANEL CONNECTING PLATE - LH / RH ?	2	\$	82.00	
31	REAR END PANEL TRIM ?	1	\$	155.00	
32	REAR WHEEL ARCH COVR - LH / RH <i>nee</i>	2	\$	340.00	
33	REAR SILENCER <i>BT</i>	1	\$	708.00	
34	DUAL CLIP <i>nee</i>	1	\$	59.00	
35	EXHAUST SYSTEM RETAINER (LH/RH) <i>BT</i>	2	\$	83.00	
36	FRONT SILENCER ? (CENR) <i>BT</i>	1	\$	623.00	
37	DUAL CLIP ? <i>AK</i>	1	\$	59.00	
38	REAR SILENCER HEAT SHIELD ? <i>BT</i>	1	\$	163.00	
39	REAR NO PLATE <i>con</i>	S/N	\$	60.00	
40	FRONT NO PLATE <i>BT</i>	S/N	\$	60.00	
SUB TOTAL SPARE PARTS			:	\$	4,789.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	ARYLIC SEALANT ? - m	S/N	\$	180.00	
42	CAVITY WAX ? - ne	S/N	\$	140.00	
43	STONE CHIP ? - ne	S/N	\$	180.00	
44	METAL FILLER POWDER ? - ne	S/N	\$	280.00	
45	REAR WINDSCREEN SEALANT	S/N	\$	200.00	
46	SUNDRIES ?		\$	400.00	
TOTAL SPARE PARTS (FRONT & REAR)		:	\$	37,369.00	
TOTAL LABOUR CHARGES (FRONT & REAR)		:	\$	24,344.00	
GRAND TOTAL		:	\$	61,713.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.