



# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183  
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**  
**Date**  
**Service Advisor**  
**Pages**  
**Regn No**  
**Model No**

PA/OD/0009/2021/JT  
14-Jan-22  
CHANG  
1 of 1  
SMN 3130 K  
AUDI Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	ELBOW FITTING (washer bracket) - BR (2)	\$ 66.00	
2	COUPLING ELEMENT - MC 1	\$ 13.00	
<b>GRAND TOTAL</b>		<b>\$ 79.00</b>	

For Premium Automobiles Pte Ltd

Steve  
17/1/22



Authorised Signature

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	? + 250 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 1,700.00	? ✓ (photo)
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	<del>5,600.00</del> @500 X 5	750 + 1500. 3 days ✓
5	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER.	<del>3,500.00</del> @550 X 3	1650
<b>TOTAL LABOUR CHARGES (FRONTAL)</b>		<b>\$ 11,960.00</b>	

+ 7 days ✓

3 (M)  
 3 (H)  
 1 (Exht)

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRNASFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	/
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AN REAR LID WIPER ASSY.	S/N \$	480.00	/
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	480.00	? ✓
4	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	/
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
<b>SUB TOTAL LABOUR CHARGES (REAR)</b>		:	<b>\$ 2,120.00</b>	

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ <del>200.00</del> 150
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@500x2 S \$ <del>5,200.00</del> 1000 + 1500 ✓
8	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND SPARE WHEEL HOUSING LINER.	@550x2 S \$ <del>4,000.00</del> 1100 + 550 ✓
9	TO RENEW LHS REAR EXHAUST SILENCER AND CENTER EXHAUST SILENCER. TO ALIGN BACK TO POSITION.	S/N \$ 480.00 / end M
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 / 3
<b>TOTAL LABOUR CHARGES (FRONTAL + REAR)</b>		<b>: \$ <u>24,344.00</u></b>

Car-in

12/1/22

wip: 62240

# PREMIUM AUTOMOBILES

KIAM



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

After-Rasu /  
- 10 days

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT

### DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,936.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 347.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 197.00	BR
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 338.00	
5	FRONT BUMPER END CAP - LH / RH	2	\$ 118.00	
6	FRONT BUMPER SPOILER	1	\$ 299.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 156.00	
8	FRONT WHEEL SPOILER - LH / RH	2	\$ 68.00	
9	FRONT BUMPER ADAPTER - LH / RH	2	\$ 78.00	
10	RADIATOR GRILLE	1	\$ 1,411.00	
11	RADIATOR STRIKER PLATE	1	\$ 124.00	BR
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 78.00	
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 723.00	DD
14	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	
15	FRONT BUMPER TOP COVER	1	\$ 100.00	BR
16	CAUTION STICKER	1	\$ 14.00	MC
17	AIR COND STICKER	1	\$ 8.00	ML
18	HORN - RH	1	\$ 180.00	
19	HORN SUPPORT - RH	1	\$ 31.00	
20	FRONT FENDER - RH	1	\$ 1,147.00	Repair
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 7,425.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER ATTACHMENT PARTS X	1	\$	40.00	
22	FRONT FENDER BRACKET - RH X	1	\$	48.00	
23	FRONT FENDER BRACKET END - RH X	1	\$	16.00	
24	FRONT FENDER BRACE - RH X	1	\$	44.00	
25	POP RIVET X	6	\$	20.00	
26	BONNET repair	1	\$	2,789.00	
27	BONNET ATTACHMENT PARTS X	1	\$	165.00	
28	BONNET HINGE - LH / RH X	2	\$	124.00	
29	BONNET IMPACT PROTECTION - CENTER / LH / RH X	3	\$	90.00	
30	BONNET STRIKER - RH X	1	\$	110.00	
31	BONNET MICROSWITCH X	1	\$	214.00	
32	BONNET RELEASE ELEMENT X	1	\$	58.00	
33	BONNET BOWDEN CABLE - CENTER X	1	\$	58.00	
34	BONNET BOWDEN CABLE CAP X	1	\$	10.00	
35	HEADLIGHT MOUNTING - LH / RH X - BR	2	\$	236.00	
36	HEADLIGHT - LH / RH X - CUT	2	\$	9,830.00	
37	LIFT CYLINDER - LH / RH ?	2	\$	284.00	
38	LIFT CYLINDER HOSE ?	1	\$	182.00	
39	FRONT WHEEL ARCH COVER - LH / RH ✓	2	\$	644.00	
40	RADIATOR COOLANT ? plus lock carrier - BR	1	\$	994.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>15,956.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	RADIATOR COOLANT ? - NR	6	\$ 266.00	
42	RADIATOR AIR GUIDE - RH ? - BR	1	\$ 31.00	
43	RADIATOR SEAL - RH OUTER ?	1	\$ 7.00	
44	RADIATOR AIR GUIDE - UPPER CENTER ? - BR	1	\$ 22.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 326.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>de ✓</i>	1	\$	1,280.00
2	REAR BUMPER FIXING PARTS ?	1	\$	77.00
3	REAR BUMPER SPOILER <i>de ✓</i>	1	\$	284.00
4	REAR BUMPER TOWING EYE ? X	1	\$	43.00
5	REAR LIGHT REFLECTOR - LH / RH ? X	2	\$	60.00
6	TAIL LIGHT - LH ?	1	\$	1,321.00
7	TAIL LIGHT TRIM - LH ?	1	\$	30.00
8	REAR BUMPER REINFORCEMENT BEAM ?	1	\$	579.00
9	REAR BUMPER HOLDING STRAP - LH / RH ?	2	\$	26.00
10	REAR BUMPER GUIDE SECTION - LH / RH ?	2	\$	108.00
11	REAR PARKING AID SENSOR - INNER / OUTER ?	2		TBC
12	REAR PARKING AID SENSOR SEAL RING <i>new ✓</i>	4	\$	9.00
13	REAR BUMPER WIRING SET ?	1	\$	515.00
14	REAR LID <i>de ✓</i>	1	\$	2,359.00
15	REAR LID ATTACHMENT PARTS ?	1	\$	120.00
16	REAR LID GASKET X	1	\$	118.00
17	REAR LID LOCK STRIKER X	1	\$	291.00
18	REAR LID LOCK X	1	\$	241.00
19	BONNET LOCK COVER ?	1	\$	13.00
20	REAR PACKING ADHESIVE <i>new ✓</i>	1	\$	19.00
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$</b>	<b>7,493.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	AUDI EMBLEM <i>new</i>	1	\$	138.00	
22	Q2 EMBLEM <i>new</i>	1	\$	99.00	
23	REAR FOAM STRIPS ?	1	\$	133.00	
24	REAR SPOILER FIXING PARTS <i>new</i>	1	\$	133.00	
25	BOOT LID BUNGS <i>new</i>	4	\$	117.00	
26	REAR WINDSCREEN <i>new</i> <i>photo</i>	1	\$	779.00	
27	PRIMER <i>new</i>	1	\$	20.00	
28	REAR END PANEL ? <i>OD ?</i>	1	\$	245.00	
29	REAR END PANEL REINFORCEMENT	1	\$	733.00	
30	REAR END PANEL CONNECTING PLATE - LH / RH ?	2	\$	82.00	
31	REAR END PANEL TRIM ?	1	\$	155.00	
32	REAR WHEEL ARCH COVR - LH / RH <i>new</i>	2	\$	340.00	
33	REAR SILENCER <i>BT</i>	1	\$	708.00	
34	DUAL CLIP <i>new</i>	1	\$	59.00	
35	EXHAUST SYSTEM RETAINER <i>LH RH</i> <i>BT</i>	2	\$	83.00	
36	FRONT SILENCER ? <i>(CENR)</i> <i>BT</i>	1	\$	623.00	
37	DUAL CLIP ? <i>MC</i>	1	\$	59.00	
38	REAR SILENCER HEAT SHIELD ? <i>BT</i>	1	\$	163.00	
39	REAR NO PLATE <i>cur</i>	S/N	\$	60.00	
40	FRONT NO PLATE <i>BT</i>	S/N	\$	60.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 4,789.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	ARYLIC SEALANT ? - ne	S/N	\$ 180.00	
42	CAVITY WAX ? - ne	S/N	\$ 140.00	
43	STONE CHIP ? - ne	S/N	\$ 180.00	
44	METAL FILLER POWDER ? - ne	S/N	\$ 280.00	
45	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
46	SUNDRIES ?		\$ 400.00	
<b>TOTAL SPARE PARTS (FRONT &amp; REAR)</b>		:	<b>\$ 37,369.00</b>	
<b>TOTAL LABOUR CHARGES (FRONT &amp; REAR)</b>		:	<b>\$ 24,344.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 61,713.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.