



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0009/2021/JT  
**DATE** : 6-Jan-22  
**WIP** : 62240

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/1/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

*Hi Rasul*

*17 days exclude 3 Sundays*

*Johnny Boo 21 Mar 22*

**OWNER'S NAME** : MR MOHAMED NOOR BIN AKBAR  
**ADDRESS** : BLK 98 BEDOK NORTH AVE 4  
#06-1902  
SINGAPORE 460096  
**TELEPHONE** : HP +65 97720046  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900141871-01  
**VEHICLE NO** : **SMN 3130 K**  
**MODEL CODE** : AUDI Q2 1.0 TFSI S TRONIC  
**MODEL YEAR** : 31/7/2019  
**ENGINE NO** : CHZ C30340  
**CHASSIS NO** : WAUZZZGA3KA061319  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 6-Jan-22  
**PLACE OF ACCIDENT** : PIE THOMSON VIADUCT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - FRONT**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	<i>SURVEYOR'S RECOMMENDATIONS</i>
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	\$ <b>360.00</b>
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	\$ <b>250.00</b>
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$ 1,700.00	\$ <b>1,700.00</b>
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	\$ <b>2,250.00</b>
5	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER.	\$ 3,500.00	\$ <b>1,650.00</b>
<b>TOTAL LABOUR CHARGES ( FRONTAL)</b>		<b>: \$ 11,960.00</b>	<b>\$ <b>6,210.00</b></b>



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - REAR**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
c/f				\$ 6,210.00
1	TO REMOVE AND TRNASFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AN REAR LID WIPER ASSY.	S/N \$	480.00	\$ 480.00
3	TO DISLUDGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	480.00	\$ 480.00
4	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	\$ 480.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	na
<b>SUB TOTAL LABOUR CHARGES (REAR)</b>		<b>:</b>	<b>\$ 2,120.00</b>	<b>\$ 7,930.00</b>



**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K - REAR**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
c/f			\$ 7,930.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	\$ 150.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,200.00	\$ 2,500.00
8	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND SPARE WHEEL HOUSING LINER.	\$ 4,000.00	\$ 1,650.00
9	TO RENEW LHS REAR EXHAUST SILENCER AND CENTER EXHAUST SILENCER. TO ALIGN BACK TO POSITION.	S/N \$ 480.00	\$ 480.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
<b>TOTAL LABOUR CHARGES (FRONTAL + REAR)</b>		<b>: \$ 24,344.00</b>	<b>\$ 13,094.00</b>



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER	1	\$	1,936.00	\$ 1,547.60
2	FRONT BUMPER FIXING PARTS	1	\$	347.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$	197.00	\$ 157.20
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$	338.00	\$ 270.40
5	FRONT BUMPER END CAP - LH / RH	2	\$	118.00	
6	FRONT BUMPER SPOILER	1	\$	299.00	\$ 238.80
7	FRONT BUMPER CLOSING ELEMENT	1	\$	156.00	
8	FRONT WHEEL SPOILER - LH / RH	2	\$	68.00	
9	FRONT BUMPER ADAPTER - LH / RH	2	\$	78.00	
10	RADIATOR GRILLE	1	\$	1,411.00	\$ 1,128.80
11	RADIATOR STRIKER PLATE	1	\$	124.00	\$ 99.20
12	FRONT BUMPER FOAM FILLER PIECE	1	\$	78.00	
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$	723.00	\$ 578.40
14	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	72.00	
15	FRONT BUMPER TOP COVER	1	\$	100.00	\$ 80.00
16	CAUTION STICKER	1	\$	14.00	\$ 10.88
17	AIR COND STICKER	1	\$	8.00	\$ 5.68
18	HORN - RH	1	\$	180.00	
19	HORN SUPPORT - RH	1	\$	31.00	
20	FRONT FENDER - RH	1	\$	1,147.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>7,425.00</b>	<b>\$ 4,116.96</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>C/F</i>		\$	<b>4,116.96</b>
21	FRONT FENDER ATTACHMENT PARTS	1	\$	40.00	
22	FRONT FENDER BRACKET - RH	1	\$	48.00	
23	FRONT FENDER BRACKET END - RH	1	\$	16.00	
24	FRONT FENDER BRACE - RH	1	\$	44.00	
25	POP RIVET	6	\$	20.00	
26	BONNET	1	\$	2,789.00	
27	BONNET ATTACHMENT PARTS	1	\$	165.00	
28	BONNET HINGE - LH / RH	2	\$	124.00	
29	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	90.00	
30	BONNET STRIKER - RH	1	\$	110.00	
31	BONNET MICROSWITCH	1	\$	214.00	
32	BONNET RELEASE ELEMENT	1	\$	58.00	
33	BONNET BOWDEN CABLE - CENTER	1	\$	58.00	
34	BONNET BOWDEN CABLE CAP	1	\$	10.00	
35	HEADLIGHT MOUNTING - LH / RH	2	\$	236.00	\$ <b>94.40</b>
36	HEADLIGHT - LH / RH	2	\$	9,830.00	\$ <b>3,932.00</b>
37	LIFT CYLINDER - LH / RH	2	\$	284.00	
38	LIFT CYLINDER HOSE	1	\$	182.00	
39	FRONT WHEEL ARCH COVER - LH / RH	2	\$	644.00	\$ <b>514.40</b>
40	RADIATOR COOLANT	1	\$	994.00	\$ <b>795.20</b>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>15,956.00</b>	<b>\$ 9,452.96</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - FRONT**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>C/F</i>		\$	<b>9,452.96</b>
41	RADIATOR COOLANT	6	\$	266.00	\$ <b>212.64</b>
42	RADIATOR AIR GUIDE - RH	1	\$	31.00	\$ <b>24.16</b>
43	RADIATOR SEAL - RH OUTER	1	\$	7.00	
44	RADIATOR AIR GUIDE - UPPER CENTER	1	\$	22.00	\$ <b>17.20</b>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>326.00</b>	<b>\$ 9,706.96</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	<b>9,706.96</b>
1	REAR BUMPER	1	\$	1,280.00	\$ <b>1,024.00</b>
2	REAR BUMPER FIXING PARTS	1	\$	77.00	
3	REAR BUMPER SPOILER	1	\$	284.00	\$ <b>227.20</b>
4	REAR BUMPER TOWING EYE	1	\$	43.00	
5	REAR LIGHT REFLECTOR - LH / RH	2	\$	60.00	
6	TAIL LIGHT - LH	1	\$	1,321.00	
7	TAIL LIGHT TRIM - LH	1	\$	30.00	
8	REAR BUMPER REINFORCEMENT BEAM	1	\$	579.00	
9	REAR BUMPER HOLDING STRAP - LH / RH	2	\$	26.00	
10	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	108.00	
11	REAR PARKING AID SENSOR - INNER / OUTER	2		TBC	
12	REAR PARKING AID SENSOR SEAL RING	4	\$	9.00	
13	REAR BUMPER WIRING SET	1	\$	515.00	
14	REAR LID	1	\$	2,359.00	\$ <b>1,887.20</b>
15	REAR LID ATTACHMENT PARTS	1	\$	120.00	
16	REAR LID GASKET	1	\$	118.00	
17	REAR LID LOCK STRIKER	1	\$	291.00	
18	REAR LID LOCK	1	\$	241.00	
19	BONNET LOCK COVER	1	\$	13.00	
20	REAR PACKING ADHESIVE	1	\$	19.00	\$ <b>14.88</b>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>7,493.00</b>	<b>\$ 12,860.24</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>C/F</i>		<b>\$</b>	<b>12,860.24</b>
21	AUDI EMBLEM	1	\$	138.00	<b>\$ 110.00</b>
22	Q2 EMBLEM	1	\$	99.00	<b>\$ 79.04</b>
23	REAR FOAM STRIPS	1	\$	133.00	
24	REAR SPOILER FIXING PARTS	1	\$	133.00	<b>\$ 106.00</b>
25	BOOT LID BUNGS	4	\$	117.00	<b>\$ 93.12</b>
26	REAR WINDSCREEN	1	\$	779.00	<b>\$ 623.20</b>
27	PRIMER	1	\$	20.00	<b>\$ 15.76</b>
28	REAR END PANEL	1	\$	245.00	<b>\$ 196.00</b>
29	REAR END PANEL REINFORCEMENT	1	\$	733.00	
30	REAR END PANEL CONNECTING PLATE - LH / RH	2	\$	82.00	
31	REAR END PANEL TRIM	1	\$	155.00	
32	REAR WHEEL ARCH COVR - LH / RH	2	\$	340.00	<b>\$ 272.00</b>
33	REAR SILENCER	1	\$	708.00	<b>\$ 566.00</b>
34	DUAL CLIP	1	\$	59.00	<b>\$ 46.96</b>
35	EXHAUST SYSTEM RETAINER - LH / RH	2	\$	83.00	<b>\$ 65.92</b>
36	FRONT SILENCER	1	\$	623.00	<b>\$ 498.00</b>
37	DUAL CLIP	1	\$	59.00	<b>\$ 46.96</b>
38	REAR SILENCER HEAT SHIELD	1	\$	163.00	<b>\$ 130.00</b>
39	REAR NO PLATE	S/N	\$	60.00	<b>\$ 60.00</b>
40	FRONT NO PLATE	S/N	\$	60.00	<b>\$ 60.00</b>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>4,789.00</b>	<b>\$ 15,829.20</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K - REAR**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<b>C/F</b>		<b>\$ 15,829.20</b>
41	ARYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
42	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
43	STONE CHIP	S/N	\$ 180.00	\$ 180.00
44	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
45	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
46	<b>ADD PARTS</b>		<b>\$ 79.00</b>	<b>\$ 62.32</b>
47	SUNDRIES		\$ 400.00	\$ 12.72
<b>TOTAL SPARE PARTS (FRONT &amp; REAR)</b>		<b>:</b>	<b>\$ 37,448.00</b>	<b>\$ 16,884.24</b>
<b>TOTAL LABOUR CHARGES (FRONT &amp; REAR)</b>		<b>:</b>	<b>\$ 24,344.00</b>	<b>\$ 13,094.00</b>
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 61,792.00</b>	<b>\$ 29,978.24</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



**Supplementary Estimate-1**

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept <b>Tel: 6841 0055 / Fax: 6256 4315</b>		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/OD/0009/2021/JT 14-Jan-22 CHANG 1 of 1 SMN 3130 K AUDI Q2 1.0 TFSI	
Quantity	Description		Unit Price	Amount
<b>Parts</b>				
1	ELBOW FITTING NEC	2	\$ 66.00	\$ <b>52.16</b>
2	COUPLING ELEMENT NEC	1	\$ 13.00	\$ <b>10.16</b>
<b>GRAND TOTAL</b>			<b>\$ 79.00</b>	<b>\$ 62.32</b>

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT