


**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| <b>STRIDES Automotive Services Pte Ltd</b>        |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

**Date Generated : 13/01/2022**
**User ID                      PohSuan**
**Section A - Accident Details**

|                                    |                      |
|------------------------------------|----------------------|
| Registration Number                | SHB5004B             |
| Case Reference Number              | TAX/12/21/2077       |
| Registration Date                  | 19/1/2017            |
| Company Type                       | Strides Taxi Pte Ltd |
| Make                               | TOYOTA               |
| Model                              | PRIUS                |
| Name of Driver                     | NG CHEE TECK         |
| Type of Accident                   | Head to Rear         |
| Accident Date and Time             | 31/12/2021 9:55 AM   |
| Accident Reported Date and Time    | 31/12/2021 11:26 AM  |
| Is Surveyor Required?              | Yes                  |
| Survey by                          |                      |
| Vehicle is Towed Back?             | No                   |
| Towed Back Date and Time           |                      |
| Replacement Vehicle issued?        | No                   |
| Job Card Number                    | 24113549             |
| Special Instruction to ARC, if any | TP / LEFT PORTION    |
| Prepared Date and Time             | 31/12/2021 7:49 PM   |
| Chassis Number                     |                      |
| Mileage                            |                      |
| Work Shop                          |                      |
| Repair Completion Date and Time    |                      |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$845.00                                                                            | \$400.00                                                                            |
| Total Spray Cost             | \$2,610.00                                                                          | \$800.00                                                                            |
| Total Spare Part Cost        | \$11,563.44                                                                         | \$641.48                                                                            |
| Total Other Cost             | \$940.00                                                                            | (\$341.48)                                                                          |
| <b>TOTAL COST</b>            | <b>\$15,958.44</b>                                                                  | <b>\$1,500.00 (L/S)</b>                                                             |
| <b>Lump Sum Total</b>        | <b>\$0.00</b>                                                                       | <b>\$0.00</b>                                                                       |
| Number of Repair Days        | 7.0                                                                                 | 4.0                                                                                 |
| Prepared / Adjusted By       | <b>Ang Bang Kien</b>                                                                | <b>GUO QIANG (LKK) / NTUC</b>                                                       |
| ARC / Surveyor Sign Off Date | <b>03/01/2022 3:56 PM</b>                                                           | <b>03/01/2022 3:05 PM</b>                                                           |
| Signature                    |  |  |
| Remarks                      |                                                                                     | LUM SUM AFTER PAINT PHOTO                                                           |

**Section C - Quotation and Accident Invoice Details**

|                         |              |                       |  |
|-------------------------|--------------|-----------------------|--|
| <b>Quotation Number</b> | QN-2201-0138 | <b>Invoice Number</b> |  |
| <b>Quotation Date</b>   | 13.01.2022   | <b>Invoice Date</b>   |  |
| <b>Invoice Amount</b>   |              | <b>Prepared Date</b>  |  |

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

| <b>Job Scope</b>     | <b>Quotation from AR</b> | <b>Adjusted by Surveyor, if applicable</b> |
|----------------------|--------------------------|--------------------------------------------|
| TO REPAIR LH PORTION | \$845.00                 | \$400.00                                   |
| <b>Total Labour</b>  | <b>\$845.00</b>          | <b>\$400.00</b>                            |

**Part 2 - Spray Painting & Panel Beating Related Works**

| <b>Job Scope</b>                                | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
|-------------------------------------------------|---------------------------|--------------------------------------------|
| TO RESPRAY FRONT BUMPER                         | \$378.00                  | \$200.00                                   |
| TO RESPRAY FRONT FENDER LH                      | \$378.00                  | \$200.00                                   |
| TO RESPRAY RIM                                  | \$360.00                  | \$0.00                                     |
| RESPRAY MIRROR COVER LH                         | \$180.00                  | \$0.00                                     |
| TO RESPRAY ROCKER PANEL MOULDING                | \$180.00                  | \$0.00                                     |
| TO RESPRAY FRONT DOOR LH                        | \$378.00                  | \$200.00                                   |
| TO RESPRAY REAR DOOR LH                         | \$378.00                  | \$200.00                                   |
| TO RESPRAY REAR FENDER LH                       | \$378.00                  | \$0.00                                     |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$2,610.00</b>         | <b>\$800.00</b>                            |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| <b>Job Scope</b>                                | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
|-------------------------------------------------|---------------------------|--------------------------------------------|
| Lump Sum Adjustment by Surveyor                 | \$0.00                    | (\$391.48)                                 |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING          | \$120.00                  | \$0.00                                     |
| TO TRANSFER DOOR MECHANISM                      | \$120.00                  | \$0.00                                     |
| TO REMOVE AND REFIX WING MIRROR                 | \$120.00                  | \$0.00                                     |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | \$240.00                  | \$0.00                                     |
| TO REPLACE SUNDRY PARTS                         | \$100.00                  | \$0.00                                     |
| TO APPLY RUST-PROOFING ON AFFECTED AREA         | \$100.00                  | \$20.00                                    |
| TO CHECK WIRING AND SYSTEM FUNCTION             | \$80.00                   | \$30.00                                    |
| TO WASH AND VACUUM                              | \$60.00                   | \$0.00                                     |
| <b>Total Other Costs</b>                        | <b>\$940.00</b>           | <b>(\$341.48)</b>                          |

**Part 4 - Spare Parts / Material Usage**

| <b>Part Number</b> | <b>Portion</b> | <b>Stock Number</b> | <b>Part Name</b>       | <b>Quantity</b> | <b>List Price (\$)</b> | <b>Discount (%)</b> | <b>Final Price (\$)</b> | <b>Estimator Approved</b> | <b>Surveyor Approved</b> |
|--------------------|----------------|---------------------|------------------------|-----------------|------------------------|---------------------|-------------------------|---------------------------|--------------------------|
|                    |                | 52119-47930         | BUMPER FRT             | 1.00            | \$482.00               | 100.00              | \$0.00                  | Replace                   | Repair                   |
|                    |                | 52161-16010         | BUMPER CLIPS           | 0.00            | \$1.61                 | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                    |                | 52115-47040         | BUMPER SUPPORT F/RH    | 0.00            | \$76.40                | 0.00                | \$0.00                  | Replace                   | Check                    |
|                    |                | 52116-47040         | BUMPER SUPPORT F/LH    | 0.00            | \$76.40                | 0.00                | \$0.00                  | Replace                   | Check                    |
|                    |                | 81521-47050         | LENS & BODY,FR TURN LH | 0.00            | \$511.80               | 0.00                | \$0.00                  | Replace                   | Check                    |
|                    |                | 76851-47020         | BUMPER LIP FRT         | 0.00            | \$139.60               | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                    |                | 51410-12105         | UNDER COVER CENTER     | 0.00            | \$448.30               | 0.00                | \$0.00                  | Replace                   | Not Given                |

R  
X  
X  
X  
X  
X  
X  
X

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| <b>STRIDES Automotive Services Pte Ltd</b>        |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 13/01/2022

User ID                      PohSuan

|              |  |             |                                          |      |                    |        |                 |         |           |   |
|--------------|--|-------------|------------------------------------------|------|--------------------|--------|-----------------|---------|-----------|---|
|              |  | 53802-47050 | FENDER FRT/LH                            | 1.00 | \$723.40           | 25.00  | \$542.55        | Replace | Replace   | ✓ |
|              |  | 75374-47051 | NAME PLATE (HYBRID)                      | 1.00 | \$51.90            | 25.00  | \$38.93         | Replace | Replace   | ✓ |
|              |  | 53826-47010 | FENDER PROTECTOR FRT/LH UPPER            | 0.00 | \$46.10            | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 53828-47060 | PROTECTOR, FRONT FENDER SIDE PANEL LH    | 0.00 | \$114.50           | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 53867-47030 | SEAL, FRONT FENDER TO COWL SIDE LH       | 0.00 | \$15.20            | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 53876-47030 | FENDER LINER FRT/LH                      | 0.00 | \$171.70           | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 53852-47020 | FENDER LINER PAD, FR WHEEL. LH           | 0.00 | \$49.30            | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 53702-47050 | FENDER APRON SUB FRT/LH                  | 0.00 | \$637.80           | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 42611-47140 | WHEEL DISC. FRONT                        | 0.00 | \$1,484.20         | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  |             | TYRE                                     | 0.00 | \$126.74           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 75852-47900 | MOULDING BODY, LH                        | 0.00 | \$673.60           | 0.00   | \$0.00          | Replace | Check     | X |
|              |  | 43550-47011 | WHEEL HUB FRT                            | 0.00 | \$549.70           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 67002-47070 | DOOR FRT/LH                              | 1.00 | \$894.40           | 100.00 | \$0.00          | Replace | Repair    | R |
|              |  |             | STICKER DECAL STRIDES (DOOR)             | 1.00 | \$60.00            | 0.00   | \$60.00         | Replace | Replace   | ✓ |
|              |  | 68740-12120 | HINGE LOWER LHF, DOOR                    | 0.00 | \$90.10            | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 68720-15151 | HINGE UPPER LHF, DOOR                    | 0.00 | \$80.50            | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 68610-47021 | CHECK ASSY, FR DOOR,                     | 0.00 | \$150.30           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 69210-74030 | DOOR OUTER HANDLE FRT/LH                 | 0.00 | \$370.80           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 69802-21010 | DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH | 0.00 | \$238.30           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 85720-47140 | DOOR FRONT MOTOR ASSY, POWER WINDOW      | 0.00 | \$926.00           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 87940-47310 | MIRROR ASSY, LH                          | 0.00 | \$1,224.90         | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 81740-52040 | MIRROR LAMP LH                           | 0.00 | \$65.30            | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 87945-74010 | COVER, OUTER MIRROR, LH                  | 0.00 | \$107.40           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 67004-47080 | DOOR RR/LH                               | 1.00 | \$954.50           | 100.00 | \$0.00          | Replace | Repair    | R |
|              |  | 68780-52031 | HINGE LOWER LHR, DOOR                    | 0.00 | \$72.20            | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 68760-20122 | HINGE UPPER LHR, DOOR                    | 0.00 | \$81.70            | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 68630-47031 | CHECK ASSY, RR DOOR,                     | 0.00 | \$150.30           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 61602-47091 | FENDER RR/LH                             | 0.00 | \$766.80           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  |             | STRIDES LOGO                             | 0.00 | \$7.80             | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  |             | STICKER DECAL 65558888                   | 0.00 | \$21.60            | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  |             | TYRE                                     | 0.00 | \$126.74           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 42611-47140 | WHEEL DISC                               | 0.00 | \$1,484.20         | 0.00   | \$0.00          | Replace | Not Given | X |
|              |  | 42450-47040 | WHEEL HUB REAR                           | 0.00 | \$489.40           | 0.00   | \$0.00          | Replace | Not Given | X |
| <b>Total</b> |  |             |                                          |      | <b>\$14,743.49</b> |        | <b>\$641.48</b> |         |           |   |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|--------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| <b>Total</b> |         |              |           |          |               |              |                  |           |                |

|   |          |               |
|---|----------|---------------|
|   | 641.48   |               |
| + | 400.00   |               |
| + | 850.00   | L/S \$1,500/- |
|   | 1,891.48 |               |
|   | -20%     |               |
|   | 1,513.18 |               |