

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 22-Dec-21MODEL: Hyundai IoniqVEHICLE NO.: SHB3706YINSURANCE: NTUC (L4S)MVA: LIMIT S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$459.40 / OR
	Rear Bumper Side Retainer RH	1		\$112.70 / REC
	Rear Bumper Reflector RH	1		\$41.45 X SUC
	Rear Bumper Centre Moulding Assy	1		\$451.25 X SUC
	Rear Bumper Clips	10	\$2.20	\$22.00 / REC
	Rear Wheel Cap RH	1		\$346.40 / SUC ✓
	SUB TOTAL			\$1,433.20
	LESS 20%			\$358.30
	DISCOUNTED TOTAL			\$1,074.90
	S/NETT TOTAL			\$-
	SPARE PARTS TOTAL			\$1,074.90
	Labour Charge			
	Panel Beating			\$800.00 200
	Spray Painting Charge - Rear Fender RH			\$600.00 300
	Remove/Refix Reverse Sensor			\$120.00 20 ✓
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$1,894.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theruan@Lkhauto.com
 82235769
 22/12/21 1645
 L/S after repair photo
 3 days w/p ✓

F: \$1600
 repair days 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: