

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

14/1/22 2/2 54977-60 informed willian
needed 3959-70 Borneo price



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SDJ8800E

Date of Accident : 08 January 2022

Not Authorised
due
2/2# 497760
10/1/22
Sebra pa.ing
3 days

Miss Chew Shu Choon

Date : 11 January 2022

4977-60

Estimate To Repair SKS9688B - Toyota PREVIAAERAS 2.4 CVT MR

Chassis No : JTEGD56M707170949

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>Dis</i>	\$ 604.90
02	8 ps	front bumper clips @ \$4.30 <i>neu</i>	\$ 34.40
03	1 pc	front bumper centre garnish <i>Dis</i>	\$ 588.00
04	1 pc	front bumper centre grille <i>Grand</i>	\$ 215.00
05	1 pc	front bumper tow cover <i>mis</i>	\$ 42.00
06	2 ps	front bumper side retainer @ \$70.90 <i>neu</i>	\$ 141.80
07	1 pc	front bumper under plastic <i>Dis</i>	\$ 155.70
08	1 pc	front bumper foam <i>Dis</i>	\$ 79.60
09	1 pc	front bumper reinforcement <i>neu</i>	\$ 435.00
10	1 pc	n/s front fender inner cowlng <i>neu</i>	\$ 222.80
11	8 ps	n/s front fender inner cowlng clips @ \$4.30 <i>neu</i>	\$ 34.40
12	1 pc	front grille asy <i>neu</i>	\$ 589.20
13	1 pc	n/s headlamp <i>neu</i>	\$ 2,520.00
14	1 pc	horn n/s <i>neu</i>	\$ 134.80
15	1 pc	front grille emblem <i>neu</i>	\$ 336.00
		Less 25 %	\$ 6,133.60
			\$ 1,533.40
			\$ 4,600.20
<u>SPECIAL NETT ITEMS</u>			
16	1 pc	front number plate <i>neu</i>	\$ 50.00
			\$ 50.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of front bumper parking sensor.	\$ 80.00
02		To check electrical lighting concerned.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 150.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
05		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 1,910.00
			\$ 6,560.20
		Total	\$ 6,560.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

2-555880
25%
4167.6