

Not Notified
C1 Sm & 450dp

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5737J

AAD2201-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 JAN 2022

SHD5737J

JTDBK3FU403077158

TOYOTA

PRIUS

07/01/2022

II

04/12/2018

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	R 1,300.70 ✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	L 193.50 X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	R 231.30 X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	R 110.60 X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	R 97.50 X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	R 13.30 —
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	R 43.50 —
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	R 26.30 —
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	T 926.00 ✓
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	R 238.30 ✓
1	PILLAR, CENTER BODY, OUTER LH	\$	R 323.10 X
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	R 1,294.90 X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	R 87.10 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	R 98.90 X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	R 21.90 X
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	R 34.90 X
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	R 15.40 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	\$	S 926.00 X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	S 206.70 X
1	PANEL SUB-ASSY, QUARTER, LH	\$	R 871.50 ✓
1	LINER, REAR WHEEL HOUSE, LH	\$	S 139.80 X
1	COVER, REAR BUMPER	\$	Bu/R 442.60 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	D 116.50 ✓
1	FILLER, REAR BUMPER EXTENSION, LH	\$	S 123.70 X
1	RIM	\$	S 1,900.10 X
TOTAL		\$	9,784.10

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5737J**AAD2201-**

25%	\$	2,446.03
	\$	7,338.08

Special Nett

1 FENDER CLIP	\$	<i>nn</i>	65.00	X
1 FENDER LINDER CLIP	\$	<i>nn</i>	65.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	<i>nn</i>	65.00	X
1 FRT DOOR STICKER TRANSCAB	\$	<i>nn</i>	100.00	<i>60JA</i>
1 REAR DOOR STICKER TEL. NO	\$	<i>nn</i>	100.00	<i>60JA</i>
1 TYRE	\$	<i>nn</i>	350.00	X
1 FRT DOOR ADVERTISEMENT	\$	<i>nn</i>	300.00	<i>150JA</i>
1 RR DOOR ADVERTISEMENT	\$	<i>nn</i>	300.00	<i>150JA</i>
1 RR BUMPER ADVERTISEMENT	\$	<i>nn</i>	100.00	<i>50JA</i>
TOTAL	\$		1,445.00	

TOTAL PARTS	\$	8,783.08
--------------------	----	-----------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	<i>60JA</i>
----	--------	-------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	1,400.00	<i>900JA</i>
----	----------	--------------

Putty And Spray Painting Of The Affected Portion.

\$	1,400.00	<i>1100JA</i>
----	----------	---------------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	240.00	<i>60JA</i>
----	--------	-------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>20JA</i>
----	--------	-------------

TOTAL	\$	3,590.00
--------------	----	-----------------

Over All Total	\$	12,373.08
-----------------------	----	------------------

Trans-cab Auto Services Pte Ltd

AAD2201-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5737J

(PART-BY-PART) Repair Days

~~20~~ days

7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: